

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AXA16007699/KGA3Q2-1

Date: 27/07/2020

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1742953

Claimant

Vehicle No : SHC5308U

Insured Vehicle No :

FX7389K

Date of Loss: 22/04/2016

Nature of Claim:

TP

Claim No: C0381414

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC5308U**

Make & Model: RENAULT LATITUDE, 2.0 CVT ABS (A)

Engine No: M9R8839C000883

Reg. Date: 21/03/2014 (Man. Year: 2013)

Chassis No: VF1ABL15AUC276795

Colour: Metallic White/Red

Odometer: 273931 km

Engine Capacity: 1995 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Rovel 5 mm

Rear Left Side:

Rovel 4 mm

Front Right Side: Rovel 5 mm

Rear Right Side:

Rovel 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,501.57	2,277.88	9,223.69	80.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,740.00	660.00	6,080.00	90.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,241.57	2,937.88	15,303.69	83.89
+ GST 7.00/7.00% (S\$)	1,276.91	205.65	1,071.26	83.89
Nett Amount (S\$)	19,518.48	3,143.53	16,374.95	83.89
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$128.40/day) (S\$)		513.60		
(S\$)		3,857.13		
Liabile Amount (50.00%) (S\$)		1,928.57		
+ Doc/Search Fee (S\$)		6.00		
Nett Liability (S\$)		1,934.57		

INSPECTION

Date of Assignment: 28/04/2016

Date Inspected: 25/04/2016 Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)

2, Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Mar 2018)
Parts:	143	RENAULT LATITUDE 2.0 CVT ABS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC5308U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT (CONSISTENT)	Mtg Cracked	968.79 FL	*968.79 FL
2	1		*BUMPER SPOILER FRT (CONSISTENT)	Missing	139.81 FL	*139.81 FL
3	1		*BUMPER ABSORBER FRT (CONSISTENT)	Cracked	303.60 FL	*303.60 FL
4	1		*BUMPER BRACKET FRT LH (HEADLAMP LOWER) (CONSISTENT)	Serviceable	116.47 FL	*- FL
5	1		*BUMPER RETAINER FRT LH (CONSISTENT)	Serviceable	18.37 FL	*- FL
6	1		*BUMPER BRACKET FRT RH (HEADLAMP LOWER) (CONSISTENT)	Cracked	115.98 FL	*115.98 FL
7	1		*BUMPER RETAINER FRT RH (CONSISTENT)	Distorted	18.37 FL	*18.37 FL
8	1		*BUMPER UNDERTRAY FRT (CONSISTENT)	Serviceable	363.71 FL	*- FL
9	1		*BUMPER GRILLE LOWER FRT (CONSISTENT)	Serviceable	205.23 FL	*- FL
10	1		*BUMPER BEAM FRT (CONSISTENT)	Repair	703.14 FL	*- FL
11	1		*RADIATOR GRILLE (CONSISTENT)	Serviceable	1,313.68 FL	*- FL
12	1		*RADIATOR GRILLE BADGE RENAULT (CONSISTENT)	Serviceable	173.36 FL	*- FL
13	1		*RADIATOR GRILLE FRAME (CONSISTENT)	Serviceable	1,041.35 FL	*- FL
14	1		*FRAME FULL SUPPORT PANEL (CONSISTENT)	Repair	473.77 FL	*- FL
15	1		*HEADLAMP LH (CONSISTENT)	Serviceable	911.10 FL	*- FL
16	1		*HEADLAMP RH (CONSISTENT)	Mtg Cracked	911.10 FL	*911.10 FL
17	1		*HEADLAMP PANEL FRT RH (CONSISTENT)	Serviceable	134.59 FL	*- FL
18	1		*HEADLAMP PANEL FRT LH (CONSISTENT)	Serviceable	134.59 FL	*- FL
19	1		*BONNET (CONSISTENT)	Repair	1,493.56 FL	*- FL
20	1		*FENDER PANEL FRT LH (CONSISTENT)	Repair	602.95 FL	*- FL
21	1		*FENDER PANEL FRT RH (CONSISTENT)	Repair	602.95 FL	*- FL
22	1		*FENDER WHEELARCH FRT LH (LINNER) (CONSISTENT)	Serviceable	107.32 FL	*- FL
23	1		*FENDER WHEELARCH FRT RH (LINNER) (CONSISTENT)	Serviceable	214.49 FL	*- FL
24	1		*WIPER RESERVOIR (CONSISTENT)	Serviceable	190.96 FL	*- FL
25	1		*WIPER RESERVOIR NECK (CONSISTENT)	Serviceable	27.78 FL	*- FL
26	1		*WIPER RESERVOIR MOTOR (CONSISTENT)	Serviceable	100.95 FL	*- FL
27	1		*SET RADIATOR GRILLE FRMAE CLIP (CONSISTENT)	Not Necessary	52.00 FS	*- FS
28	1		*SET BUMPER CLIP FRT (CONSISTENT)	Necessary	66.00 FS	*66.00 FS
29	1		*TOW COVER FRT (CONSISTENT)	Serviceable	14.50 FS	*- FS
30	1		*RIM RH FRT (CONSISTENT)	Serviceable	385.00 FS	*- FS
31	1		*TYRE RH FRT (CONSISTENT)	Serviceable	330.00 FS	*- FS
32	1		*SET RADITOR GRILLE SCREW (CONSISTENT)	Not Necessary	16.00 FS	*- FS
33	1		*SET BUMPER GRILLE LOWER CLIP (CONSISTENT)	Not Necessary	69.00 FS	*- FS
34	1		*SET FRAME FULL SUPPORT PANEL CLIP (CONSISTENT)	Not Necessary	70.00 FS	*- FS
35	2		*FRAME FULL SUPPORT PANEL NUT (CONSISTENT)	Serviceable	20.00 FS	*- FS
36	2		*FRAME FULL SUPPORT PANEL STUD (CONSISTENT)	Serviceable	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*SET WHEELARCH CLIP LH (CONSISTENT)	Not Necessary	30.50 FS	*- FS
38	1		*SET WHEELARCH CLIP RH (CONSISTENT)	Not Necessary	29.40 FS	*- FS
39	1		*SET NUMBER PLATE WITH HOLDER (CONSISTENT)	Serviceable	140.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					12,640.37	2,523.65
- List Item Discount on L Items 10.00/10.00% (\$\$)					1,138.80	245.77
Total Parts (\$\$)					11,501.57	2,277.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,800.00	200.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (\$\$)			6,740.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >