

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5308U - AXA**Candy**

Date
12/11/16
NOT Authorised
1-B.1
8 2937.88
Recovery B4 paint

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5308U - Candy

VF1ABL15AUC276795

RENAULT

LATITUDE

22.04.16

AXA

		PART		LIST
1	1	BUMPER COVER FRT	\$	<i>ngm</i> 968.79 ✓
2	1	BUMPER SPOILER FRT	\$	<i>mt</i> 139.81 ✓
3	1	BUMPER ABSORBER FRT	\$	<i>CR</i> 303.60 ✓
4	1	BUMPER BRACKET FRT LH(Headlamp lower)	\$	<i>mt</i> 116.47 +
5	1	BUMPER RETAINER FRT LH	\$	<i>in</i> 18.37 X
6	1	BUMPER BRACKET FRT RH(Headlamp lower)	\$	<i>CR</i> 115.98 ✓
7	1	BUMPER REPAIRER FRT RH	\$	<i>mt</i> 18.37 ✓
8	1	BUMPER UNDERTRAY FRT	\$	<i>in</i> 363.71 X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>in</i> 205.23 X
10	1	BUMPER BEAM FRT	\$	<i>R</i> 703.14 X
11	1	RADAIOR GRILLE	\$	<i>in</i> 1,313.68 X
12	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	<i>in</i> 173.36 X
13	1	RADAIOR GRILLE FRAME	\$	<i>in</i> 1,041.35 X
14	1	FRAME FULL SUPPORT PANEL	\$	<i>R</i> 473.77 X
15	1	HEADLAMP LH	\$	<i>in</i> 911.10 X
16	1	HEADLAMP RH	\$	<i>my</i> 911.10 ✓
17	1	HEADLAMP PANEL FRT RH	\$	<i>in</i> 134.59 X
18	1	HEADLAMP PANEL FRT LH	\$	<i>in</i> 134.59 X
19	1	BONNET	\$	<i>R</i> 1,493.56 X
20	1	FENDER PANEL FRT LH	\$	<i>R</i> 602.95 X
21	1	FENDER PANEL FRT RH	\$	<i>R</i> 602.95 X
22	1	FENDER WHEELARCH FRT LH (Linner)	\$	<i>in</i> 107.32 X
23	1	FENDER WHEELARCH FRT RH (Linner)	\$	<i>in</i> 214.49 X
24	1	WIPER RESERVOIR	\$	<i>in</i> 190.96 X
25	1	WIPER RESERVOIR NECK	\$	<i>in</i> 27.78 X
26	1	WIPER RESERVOIR MOTOR	\$	<i>in</i> 100.95 X

\$665.34

TOTAL	\$	11,387.97
10%	\$	1,138.80
	\$	10,249.17

Specical Nett

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST 63 SINGAPORE 569111

TEL NO.6287 6666 FAX NO.6257 1330

CO/GST REG NO.201019626G

SHC 5308U - AXA**Candy**

1	1SET	RADAIOR GRILLE FRAME CLIP	\$	nn	52.00	X
2	1SET	BUMPER CLIP FRT	\$	nn	66.00	✓
3	1	TOW COVER FRT	\$	nn	14.50	X
4	1	RIM RH FRT	\$	nn	385.00	X
5	1	TYRE RH FRT	\$	nn	330.00	X
6	1SET	RADAIOR GRILLE SCREW	\$	nn	16.00	X
7	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	X
8	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	X
9	2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	X
10	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	X
11	1SET	WHEELARCH CLIP LH	\$	nn	30.50	X
12	1SET	WHEELARCH CLIP RH	\$	nn	29.40	X
13	1SET	NUMBER PLATE WITH HOLDER	\$	nn	140.00	X

TOTAL	\$	1,252.40
TOTAL PARTS	\$	11,501.57

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 2000

Putty and spray painting of the affected portion.

\$ 3,000.00 4000

To rust-proofing of the affected areas.

\$ nn 170.00 X

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

To check steering geometry and computer wheel alignment

\$ nn 220.00 X

To Check Electrical Lighting Concerned.

\$ 170.00 200

TOTAL	\$	6,740.00
Over All Total	\$	18,241.57

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

< parts by parts > Repair Days

10 DAYS

2000