

One Zone Autocare

PHOTOCOPY

No 7 Soon Lee Street
Ispace Building #01-05
Singapore 627608
Business Reg. no: 53150343K

INVOICE

Name: Tham Hon Sun	Date of Invoice: 6/7/2018
One Zone Autocare No 7 Soon Lee Street Ispace Building #01-05 Singapore 627608	

Claim Type: Third Party	Date of Accident: 9/6/2018
Vehicle Reg No: SJQ7989T	Claimant: Tham Hon Sun
Vehicle Make/Model: Toyota Corolla Altis 1.6 Auto	
Description	Amount (S\$)
Lump Sum Repair as per recommendation	5,000.00
Total	5,000.00
Singapore Dollar: Five thousand dollars only.	



PHOTOCOPY

SINCERE APPRAISAL SERVICES PTE LTD Co.Reg no: 201800639R

60 Paya Lebar Road #07-41 Paya Lebar Square Singapore 409051

Tel : 6636 4628 Fax : 6636 4638 E-mail : sincereappraisal@gmail.com

INVOICE

Tham Hon Sun
C/O One Zone Autocare
No 7 Soon Lee Street
Ispace Building #01-05
Singapore 627608

Invoice No: 060718-340
Our ref: 340/TP/2018
Date: 6/7/2018

Claim Type: Third Party	Date of Loss: 9/6/2018
Vehicle Reg No: SJQ7989T	Claimant: Tham Hon Sun
Vehicle Make/Model: Toyota Corolla Altis 1.6 Auto	

Description	Amount (S\$)
1. Professional Fee (including Transport, 24 Photographs and Miscellaneous charges)	564
Total	564

Singapore Dollar: Five hundred and sixty four dollars only.

Cheques should be crossed A/C PAYEE and made payable to Sincere Appraisal Services Pte Ltd



Sincere Appraisal Services Pte Ltd



VEHICLE DAMAGE INSPECTION REPORT

Our Ref: 340/TP/2018

Date: 6/7/2018

REFERENCE

Date of loss: 9/6/2018
Claimant: Tham Hon Sun

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ7989T	Make &	Toyota
Reg date:	27/5/2009	Model	Corolla Altis 1.6 Auto
Colour:	Silver	Engine No:	3ZZ4884644
Type:	Motor Car	Chassis No:	MR053ZEE106144330
Type of Claims:	Third Party	Odometer No:	76001km
		Engine Cap:	1598cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY

(STATIC ONLY)

General Condition: Good	Steering: Good	Engine Modification: Nil
Paint work: Good	Handbrake: Good	Pre-accident
	Footbrake: Good	Damage: Nil

CONDITION OF TYRES

Front Left Size: Yokohama 195/65R15 70%	Front Right Size: Yokohama 195/65R15 70%
Rear Left Size: Yokohama 195/65R15 70%	Rear Right Size: Yokohama 195/65R15 70%

The above percentages represent the remaining life of the tyre threads

COST OF REPAIRS


	Repairer S\$	Adjuster S\$
Parts	\$ 4,245.25	\$ 4,245.25
Labour	\$ 2,360.00	\$ 2,050.00
Calculated Cost (S\$) :	<u>\$ 6,605.25</u>	<u>\$ 6,295.25</u>

Recommended Lump Sum Repair Cost (S\$) : \$ 5,000.00

Date of Assignment:	12/6/2018	Inspected At:	One Zone Autocare
Date Inspected:	12/6/2018		No 7 Soon Lee Street
Est. repair Period:	07 days		Ispace Building #01-05
			Singapore 627608

POINT OF IMPACT

Damaged at the left hand front portion



BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's vehicle at the car park of Lucky Plaza, Level 5.

GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are at the left hand front portion.

SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$6,605.25. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$5,000.00.

We have not authorised the repair. Under normal circumstances, estimated **07** working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Dave Chang
Automotive Appraiser
AUTO. ENG, CAE, CGI
MIRTE, MSAAA, MTM

Automotive Appraiser: Dave Chang

Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Front bumper assy	grazed/cut	\$ 585.00	\$ 585.00
2	1	Front left bumper bracket	bent/necessary	\$ 45.00	\$ 45.00
3	1	Front left bumper retainer	bent/necessary	\$ 44.00	\$ 44.00
4	1	Front bumper reinforcement	bent/necessary	\$ 246.00	\$ 246.00
5	1	Front grille assy	warped/bent	\$ 170.00	\$ 170.00
6	1	Front grille emblem	necessary	\$ 68.00	\$ 68.00
7	1	Front left headlamp	grazed/cut	\$ 389.00	\$ 389.00
8	1	Front left fender assy	bent/warped	\$ 972.00	\$ 972.00
9	1	Front left fender vvti emblem	necessary	\$ 63.00	\$ 63.00
10	1	Front left fog lamp	bent	\$ 252.00	\$ 252.00
11	1	Front left fog lamp garnish	necessary	\$ 87.00	\$ 87.00
12	1	Front left suspension assy	bent	\$ 786.00	\$ 786.00
13	1	Front left lower arm	bent	\$ 371.00	\$ 371.00
14	1	Front left knuckle arm	bent	\$ 398.00	\$ 398.00
15	1	Front left wheel hub bearing	bent	\$ 251.00	\$ 251.00
				<hr/>	<hr/>
				\$ 4,727.00	\$ 4,727.00
Less 25%				\$ 1,181.75	\$ 1,181.75
				<hr/>	<hr/>
				\$ 3,545.25	\$ 3,545.25
<u>Special Nett Items</u>					
1	10	Front bumper clips	necessary	\$ 50.00	\$ 50.00
2	1	Front left sports rim	grazed/cut	\$ 650.00	\$ 650.00
				<hr/>	<hr/>
				\$ 700.00	\$ 700.00
Total parts				\$ 4,245.25	\$ 4,245.25

ANNEX B

REPAIR DETAILS

Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount
1	Labour for panel beating, cut, weld, straighten front left affected area and replace front left damaged parts.	\$ 900.00	\$ 800.00
2	To putty and spray painting front left portion.	\$ 900.00	\$ 800.00
3	To apply anti rust proofing to front left affected area.	\$ 100.00	\$ 80.00
4	To check wiring and focus front headlamp.	\$ 50.00	\$ 30.00
5	To remove and install front left undercarriage parts.	\$ 280.00	\$ 250.00
6	To balance front left wheel.	\$ 50.00	\$ 30.00
7	To conduct wheel alignment.	\$ 80.00	\$ 60.00
Total labour :		\$ 2,360.00	\$ 2,050.00

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 4,245.25	\$ 4,245.25
Total labour :	\$ 2,360.00	\$ 2,050.00
Total repair cost :	<u>\$ 6,605.25</u>	<u>\$ 6,295.25</u>

Adjusted Repair Cost (Lump Sum Repair)

\$ 5,000.00

