

 **FORMTEAM ADJUSTERS PTE LTD**

No.33, Ubi Ave 3
#02-15, Vertex
Singapore 408868

Tel : (65) 6509 1788
Fax : (65) 6509 6221

Email: claims@fta.com.sg

Co.Reg No: 201212134W

GST Reg No: 201212134W

Our Reference : FTA/AHA/1811/11210
Your Reference: 5847782677SG
Date : 27-Nov-2018

Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120

Attention : Mr Loh Chee Heng

Dear Sir/Mdm,

PAPER RE-INSPECTION OF VEHICLE NO . SJQ 7989T

Pursuant to your instructions on 22 November 2018 , we have conducted a paper reinspection of the above vehicle.

We recommend a repair cost of **\$1,662.75** (see report) based on part by part repair and the estimated duration of repairs would take **04 days** .

We also enclosed our note of charges for your consideration.

Thank you for this assignment.

Adjusters & Surveyors (Licensed Appraiser)


Ng You Han
Automobile Appraiser

(Email : yhng@fta.com.sg)

Encl. Re-inspection Report

AUTOMOBILE ASSESSMENT REPORT

PAGE : 1

Our Reference : FTA/AHA/1811/11210Your Reference : 5847782677SG

Date : 27-Nov-2018

Attention : Mr Loh Chee Heng

TO : Motor Claims Department

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #07-16

Singapore 079120

Dear Sir/Madam,

Vehicle No : SJQ 7989T
 Model : Toyota Corolla Altis 1.6 (A)
 Mileage : -
 Chassis No : MR053ZEE106144330
 Workshop : M/S One Zone Autocare

Pursuant to your instructions on **22 November 2018**, we have conducted a paper reinspection of the above vehicle.

We are pleased to submit hereunder our adjustment which we trust should serve your purpose: -

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
	<u>PARTS REPLACEMENT-LIST ITEMS</u>				
1	Front Bumper Assy	Grazed/Cut		585.00	585.00
1	Front Left Bumper Bracket	Bent/Necessary		45.00	45.00
1	Front Left Bumper Retainer	Bent/Necessary		44.00	44.00
1	Front Bumper Reinforcement	Not Necessary		246.00	-
1	Front Grille Assy	Not Consistent		170.00	-
1	Front Grille Emblem	Not Necessary		68.00	-
1	Front Left Headlamp	Not Replace		389.00	-
1	Front Left Fender Assy	Not Replace		972.00	-
1	Front Left Fender VVTI Emblem	Necessary		63.00	63.00
1	Front Left Fog Lamp	Not Replace		252.00	-
1	Front Left Fog Lamp Garnish	Not Necessary		87.00	-
1	Front Left Suspension Assy	Not Consistent		786.00	-
1	Front Left Lower Arm	Not Consistent		371.00	-

Our Reference : FTA/AHA/1811/11210

Your Reference : 5847782677SG

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
1	Front Left Knuckle Arm	Not Consistent		398.00	-
1	Front Left Wheel Hub Bearing	Not Consistent		251.00	-
	Sub-Total			4,727.00	737.00
	Discount Percentage 25%			1,181.75	184.25
	Total Parts List Items			3,545.25	552.75
	<u>PARTS REPLACEMENT-SPECIAL NETT ITEMS</u>				
10	Front Bumper Clips	Necessary		50.00	50.00
1	Front Left Sports Rim	Not Consistent		650.00	-
	Sub-Total			700.00	50.00
	Total Parts List Items			4,245.25	602.75

Our Reference : FTA/AHA/1811/11210Your Reference: 5847782677SG

QTY	DESCRIPTION	SUBMITTED	REVISED
	<u>LABOUR & MISC</u>		
1	Labour for panel beating, cut, weld, straighten front left affected area and replace front left damaged parts	800.00	500.00
2	To putty and spray painting front left portion.	800.00	500.00
3	To apply anti rust proofing to front left affected area.	80.00	30.00
4	To check wiring and focus front headlamp	30.00	30.00
5	To remove and install front left undercarriage parts	250.00	-
6	To balance front left wheel	30.00	-
7	To conduct wheel alignment	60.00	-
	Total Labour Amount	2,050.00	1,060.00
	Total Parts and Labour	6,295.25	1,662.75

Our Reference : FTA/AHA/1811/11210

Your Reference: 5847782677SG

QTY	DESCRIPTION	SUBMITTED	REVISED
	Our Recommended Repair Cost (see remarks)	\$5,000.00	\$1,662.75

REMARKS :

Our recommended Part by Part Repair Cost is **\$1,662.75** (instead of the submitted repair cost of **\$5,000.00** .In normal circumstances, repairs to the vehicle would take approximately **04 days** to complete. Please find enclosed our note of charges for your kind attention.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **FORMTEAM ADJUSTERS PTE LTD** for any reliance on this report by any third party, unless with the permission of the addressee.

Yours faithfully,

FORMTEAM ADJUSTERS PTE LTD

Frankie Pang
 AMSAE(AUST), AMIRTE, AMSOE,
 MASPACI, MSAAA
 Licensed Appraiser

Ng You Han
 Automobile Appraiser

SJQ7989T [SKL511Z] - Submitted by: FormTeam Adjusters Pte Ltd (HQ)



1/90: General View



2/90: General View



3/90: General View




4/90: General View

SJQ7989T [SKL511Z] - Submitted by: FormTeam Adjusters Pte Ltd (HQ)



5/90: General View



6/90: General View



7/90: General View



8/90: General View

SJQ7989T [SKL511Z] - Submitted by: FormTeam Adjusters Pte Ltd (HQ)



9/90: General View



10/90: General View




11/90: General View




12/90: General View

SJQ7989T [SKL511Z] - Submitted by: FormTeam Adjusters Pte Ltd (HQ)




13/90: General View



14/90: General View



15/90: General View




16/90: General View

SJQ7989T [SKL511Z] - Submitted by: FormTeam Adjusters Pte Ltd (HQ)



17/90: General View



18/90: General View



19/90: General View



20/90: General View

SJQ7989T [SKL511Z] - Submitted by: FormTeam Adjusters Pte Ltd (HQ)



21/90: General View



22/90: General View



23/90: General View



24/90: General View