

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20005193/UKA3Q2

Date: 28/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLR9267B	Insured Vehicle No :	SHA4241U
Date of Loss: 13/04/2020	Nature of Claim: TP	Claim No: MCT20040151

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR9267B		
Make & Model:	HONDA HR-V, 1.5 DX CVT (A)	Engine No:	L15B4532759
Reg. Date:	31/08/2017 (Man. Year: 2017)	Chassis No:	JHMRU1810GX202757
Colour:	Black	Odometer:	72114 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,881.80	2,056.25	1,825.55	47.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,140.00	7,860.00	3,280.00	29.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	15,021.80	9,916.25	5,105.55	33.99
+ GST 7.00/7.00% (\$\$)	1,051.53	694.14	357.39	33.99
Nett Amount (\$\$)	16,073.33	10,610.39	5,462.94	33.99
+ Car Rental (7.0 x S\$100.00/day + 7.00% GST) (\$\$)		749.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		11,366.84		

INSPECTION

Date of Assignment:	14/04/2020	
Date Inspected:	16/04/2020	Inspected At:
		Kah Motor Co Sdn Bhd (Ubi)
		15 Ubi Road 4
		Singapore 408610
Estimated Period of Repair:	7.0 days	

Adjuster: MARCUS CHUA

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Jul 2020)	
Parts:	N/A	HONDA HR-V 1.5 DX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR9267B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
2	4		*ACT RR SENSOR	Shorted	320.00 FS	*320.00 FS
3	1		*LAMP UNITR	Not Necessary	361.80 FS	*- FS
4	1		*LAMP UNITL	Not Necessary	361.80 FS	*- FS
5	1		*LIGHT ASSY ,R.LID	Not Necessary	207.67 FS	*- FS
6	1		*LIGHT ASSYL.LID	Not Necessary	207.67 FS	*- FS
7	1		*EMBLEMH	Not Necessary	8.02 FS	*- FS
8	2		*NUTPUSH 3MM	Not Necessary	3.15 FS	*- FS
9	1		*GARNISH ASSYRR LICENSE	Not Necessary	148.95 FS	*- FS
10	1		*ANTENNE ASSYL.F	Not Necessary	45.60 FS	*- FS
11	1		*BUZZER ASSYSMART	Not Necessary	46.50 FS	*- FS
12	1		*DAMPERSTD 5X5	Necessary	6.52 FS	*6.52 FS
13	1		*RUBBER CL WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS
14	1		*CAPPIVOT	Necessary	3.75 FS	*3.75 FS
15	1		*FASTENER BW/SHIELD (4 PCS)	Necessary	15.90 FS	*15.90 FS
16	1		*FASTENER B (2 PCS)	Necessary	7.95 FS	*7.95 FS
17	2		*FASTENER AW/SHIELD	Necessary	5.70 FS	*5.70 FS
18	1		*CLIP.BUMPER (10 PCS)	Necessary	17.25 FS	*17.25 FS
19	1		*PROTECTOR.R.RR.WHEEL ARCH	Torn	135.07 FS	*135.07 FS
20	1		*FACER.RR.BUMPER CORNER	Torn	72.37 FS	*72.37 FS
21	1		*SPACER.R.RR BUMPER SIDE	Necessary	12.97 FS	*12.97 FS
22	1		*SPACER.L RR BPR S	Not Necessary	12.97 FS	*- FS
23	1		*FACE RR BUMPER	Dented	598.57 FS	*347.77 FS
24	1		*PANEL COMPRR	Badly Dented	287.02 FS	*287.02 FS
25	1		*WEATHERSTRIPTAILGATE	Serviceable	75.97 FS	*- FS
26	1		*LOCK ASSYTAILGATE	Serviceable	64.65 FS	*- FS
27	1		*TAIL GATE COMP	Badly Dented	658.42 FS	*658.42 FS
28	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
29	1		*LINING ASSYRR PANEL	Twisted	33.75 FS	*33.75 FS
30	1		*EMBLEMRR	Necessary	10.95 FS	*10.95 FS
31	1		*EMBLEM,RR.I-VTEC	Necessary	11.92 FS	*11.92 FS
32	1		*RUBBER CR .WINDSHIELD DAMPER	Necessary	14.47 FS	*14.47 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **3,881.80** **2,056.25**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	BODY UNDERSIDE COATING	New	100.00	100.00
2	BODY JOINT SEALANT	New	100.00	100.00
3	INPECT RR LIGHTING MECHANISMS PERFORM WATER	New	150.00	120.00
4	REMOVE & INSTALL REVERSE SENSORS	New	180.00	140.00
5	APPLY BODY UNDERSIDE COATING	New	250.00	200.00
6	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	380.00	350.00
7	RESET VEHICLE SMART ENTRY SYSTEM	New	380.00	350.00
8	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	400.00	300.00
9	REMOVE & INSTALL RR WINDSCREEN WITH SEALANT	New	500.00	450.00
10	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST &	New	600.00	550.00
11	CUT OFF & RENEW RR PANEL STRAIGHTEN RR FENDERS AN	New	4,800.00	2,600.00
12	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	3,300.00	2,600.00
Gross Labour Cost (\$\$)			11,140.00	7,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >