

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: INDIA INTERNATIONAL INSURANCE PTE	Document No.	: SQT20001541	Page	1
	64 CECIL STREET	Date	: 14. Apr 2020		
	#04-00 & #05-00 IOB BUILDING	Customer No.	: WZ1007		
	SINGAPORE 049711	Svc Advisor	: ARY CHUA WAI NGEE		
Registration No	: SLR9267B	Engine No	: L15B4532759		
Chassis No	: JHMRU1810GX202757	Date Time	: 14. Apr 2020 11:06:32 AM		
Model	: HRV DX-SIN CVT YM 2016	Surveyor Name	: DID : +65 6846 5673		
Owner's Name	: NG CHAN KEET	Survey Date	: HP : +65 8100 6306		
Ins Policy No.	: 19-MU009166-R01	Authorisation Date	: Email : arychua@honda.com.sg		
Date of Accident	: 13/4/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 746)						
	OWNER: NG CHAN KEET						
	OWNER INSURER: TOKIO MARINE INSURANCE LTD						
	ACC DATE: 13/04/2020@13.20PM						
	ACC: T/J TOA PAYOH L4(L/P23A)&TOA PAYOH CTL(L/P1)						
	SURVEYED BY:						
	REF NO:						
	TP INSURER: INDIA INTERNATIONAL INSURANCE PTE LTD						
	TP VEH: SHA4241U - HYUNDAI/I40/BLUE TAXI						
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.40
33502-T7A-J01	LAMP UNITR.	1	482.40	25	361.80	25.33	387.13
33552-T7A-J01	LAMP UNITL.	1	482.40	25	361.80	25.33	387.13
34150-T7A-J01	LIGHT ASSY,R.LID	1	276.90	25	207.67	14.54	222.21
34155-T7A-J01	LIGHT ASSYL.LID	1	276.90	25	207.67	14.54	222.21
75701-T5A-000	EMBLEMH	1	10.70	25	8.02	0.56	8.58
90301-ST0-003	NUTPUSH 3MM	2	2.10	25	3.15	0.22	3.37
74890-T7A-J12ZC	GARNISH ASSYRR.LICENSE	1	198.60	25	148.95	10.43	159.38
38387-TZ5-A01	ANTENNA ASSYL.F.	1	60.80	25	45.60	3.19	48.79
74940-TZ5-A01	BUZZER ASSYSMART	1	62.00	25	46.50	3.26	49.76
73226-SZW-000	DAMPERSTD 5X5	1	8.70	25	6.52	0.46	6.98
73254-T7J-H01	RUBBER CL.WINDSHIELD DAMPER	1	19.30	25	14.47	1.01	15.48
76711-T6A-003	CAPPIVOT	1	5.00	25	3.75	0.26	4.01
91501-S70-003	FASTENER BW/SHIELD	4	5.30	25	15.90	1.11	17.01
91502-S70-003	FASTENER B	2	5.30	25	7.95	0.56	8.51
91536-SS0-J01	FASTENER AW/SHIELD	2	3.80	25	5.70	0.40	6.10
91505-TM8-003	CLIP,BUMPER	10	2.30	25	17.25	1.21	18.46
74410-T7B-003	PROTECTOR,R,RR WHEEL ARCH	1	180.10	25	135.07	9.45	144.52

Printed on 14/4/2020 11:50:15 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : INDIA INTERNATIONAL INSURANCE PTE
64 CECIL STREET
#04-00 & #05-00 IOB BUILDING
SINGAPORE 049711
Registration No : SLR9267B
Chassis No : JHMRU1810GX202757
Model : HRV DX-SIN CVT YM 2016
Owner's Name : NG CHAN KEET
Ins Policy No. : 19-MU009166-R01
Date of Accident : 13/4/2020

Document No. : SQT20001541
Date : 14. Apr 2020
Customer No. : WZ1007
Svc Advisor : ARY CHUA WAI NGEE
Engine No : L15B4532759
Date | Time : 14. Apr 2020 11:06:32 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
04717-T7A-000ZZ	FACER.RR BUMPER CORNER	1	96.50	25	72.37	5.07	77.44
71593-T7A-J00	SPACER,R.RR BUMPER SIDE	1	17.30	25	12.97	0.91	13.88
71598-T7A-J00	SPACER,L.RR.BPR S	1	17.30	25	12.97	0.91	13.88
71501-T7B-000	FACE RR.BUMPER	1	798.10	25	598.57	41.90	640.47
66100-T7A-300ZZ	PANEL COMPRR.	1	382.70	25	287.02	20.09	307.11
74440-T7A-003	WEATHERSTRIPTAILGATE	1	101.30	25	75.97	5.32	81.29
74800-T7A-J02	LOCK ASSYTAILGATE	1	86.20	25	64.65	4.53	69.18
68100-T7A-J20ZZ	TAIL GATE COMP	1	877.90	25	658.42	46.09	704.51
Sum Item					3760.71	263.28	4,023.99

BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BOBC	BODY UNDERSIDE COATING (N)	1	100.00	✓	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT.	1	100.00	✓	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	150.00	120	150.00	10.50	160.50
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	180.00	140	180.00	12.60	192.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00	200	250.00	17.50	267.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	380.00	350	380.00	26.60	406.60
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	380.00	350	380.00	26.60	406.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	400.00	300	400.00	28.00	428.00
BG02D	REMOVE & INSTALL RR. WINDSCREEN WITH SEALANT	1	500.00	450	500.00	35.00	535.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	600.00	550	600.00	42.00	642.00
BKRP21M	CUT OFF & RENEW RR PANEL. STRAIGHTEN RR FENDERS AN	1	4800.00	2600	4800.00	336.00	5136.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	3300.00	2600	3300.00	231.00	3531.00
Sum Labor					11190.00	783.30	11,973.30

Survey By

Date & Time

Printed on 14/4/2020 11:42:01 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To disassemble part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

15,997.29