

CS3/LPC19021287/T1vf3 -1

23/12/2019

ASS. REC. BY:

REF:

~~CS3/LPC19021287/T1vf3~~

Special Instruction:

Surveyor: Tan Hui

ASSIGNMENT (Office)

03/04/2020

From (Person): Ong lili

of

Jpc

Date/Time:

~~21/12/19 4:55pm~~

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBG709D

Insured:

GBE 1989R

at Workshop info:

Auto Best Motor

Tel:

9745 6932

of

Blk 3006 Ubi Road 1 # 01-362

Policy No:

Claim No:

19/19/19/VCO5/000726

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

29/11/2019

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time:

11.30am 3/12/19

Person Contacted:

Mr. Lee

Vehicle IN/OUT

Date/Time

Action/Instruction

1. Insured ✓

GBG709D NA/M5414V2/150/114

29/11/19

GBG709D NA/M5414V2/150/114

29/11/2019

After paint (G) Dec '19

11/12/19

Submit PRS


20/4/20 Submit LS \$5000, (Red 2350, 3290), 7 days

2/12/19

JPC

2/12/19

GBG 709D
Auto Best Motor
BLK 3006 Ubi Road 1 #01-362



The veh had commenced its
operation at the time of inspection

CA / REV / REP / 24 HRS
Yes / No
Yes / No
Yes / No
Yes / No

CA / REV / REP / 24 HRS
Yes / No
Yes / No
Yes / No
Yes / No

CA / REV / REP / 24 HRS
Yes / No
Yes / No
Yes / No
Yes / No

W/S to independent PPS work

2019

964709D 2012 May

GBG 709D
Auto Best Motor
BLK 3006 Ubi Road 1 #01-362

GBG 709D
Auto Best Motor
BLK 3006 Ubi Road 1 #01-362

GBG 709D
Auto Best Motor
BLK 3006 Ubi Road 1 #01-362

GBG 709D
Auto Best Motor
BLK 3006 Ubi Road 1 #01-362

GBG 709D
Auto Best Motor
BLK 3006 Ubi Road 1 #01-362

GBG 709D
Auto Best Motor
BLK 3006 Ubi Road 1 #01-362

GBG 709D
Auto Best Motor
BLK 3006 Ubi Road 1 #01-362

GBG 709D
Auto Best Motor
BLK 3006 Ubi Road 1 #01-362

GBG 709D
Auto Best Motor
BLK 3006 Ubi Road 1 #01-362

GBG 709D
Auto Best Motor
BLK 3006 Ubi Road 1 #01-362

GBG 709D
Auto Best Motor
BLK 3006 Ubi Road 1 #01-362

GBG 709D
Auto Best Motor
BLK 3006 Ubi Road 1 #01-362

GBG 709D
Auto Best Motor
BLK 3006 Ubi Road 1 #01-362

GBG 709D
Auto Best Motor
BLK 3006 Ubi Road 1 #01-362

GBG 709D
Auto Best Motor
BLK 3006 Ubi Road 1 #01-362

11/12 - type

120

120

AUTO BEST MOTOR SERVICES

BLOCK 3006, UBI ROAD 1 #01-362

SINGAPORE 408700

TEL : 67456932, .

HP NOS : 97456932

FAX : 67458669

REG. NOS. : 376845/00-K

DATE: 21st MAR 2020

ATLAS MAINTENANCE PTE LTD

BLOCK 3006 UBI ROAD 1

#01-362

SINGAPORE 408700

DEAR SIR,

DATE OF ACCIDENT: 29th NOV 2019


FINAL REPAIRS BILL TO NISSAN WITH VEHICLE NOS: GBG 709D
CABSTAR


TO SUPPLY:

LUMP SUM REPAIRS RECOMMENDED BY THE SURVEYOR _____ \$ 7350/-

DOLLARS SEVEN THOUSAND THREE HUNDRED FIFTY ONLY

AUTO BEST MOTOR SERVICES





kelvin automotive appraising services
6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Claim Reference : -
Insured Vehicle No. : -
Thirty Party Veh No. : -
Officer-in-Charge : -

Our Reference : KAAS/TA/5924/0709/TP/11.19
Date : 20 March 2020

To: Atlas Maintenance Pte Ltd
c/o Blk 3006 Ubi Road 1
#01-362
Singapore 408700

VEHICLE APPRAISAL REPORT

Name of Workshop : Auto Best Motor Services
Place of inspection : Blk 3006 Ubi Road 1 #01-362, Singapore 408700
Date of Assignment : 04 December 2019
Date of Accident : 29 November 2019
Date of Inspection : 04 December 2019

PARTICULARS OF INSPECTED VEHICLE

Registration No	: GBO 709D	Chassis Frame No.	: JN1SC2F24Z0859577
Make / Model	: Nissan Cabstar 3.0 5MT 2Dr 2WD Euro5	Engine No. (Logcard)	: ZD30022549N
Year of Manufacture/Reg	: 2017	Odometer Reading	: 69,952 KM
Colour	: Blue		
Class / Type	: Truck		

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition : Very Good
Paintwork : Very Good
Market Value : -
Scrap Value : -

CONDITION OF TYRES ON VEHICLE

	<u>Make/Size</u>	<u>Thread Balance</u>
Front L	WESTLAKE 195 R15C	7 mm
Front R	WESTLAKE 195 R15C	7 mm
Rear L	WESTLAKE 165 R13C	7 mm
Rear R	WESTLAKE 165 R13C	7 mm

*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.

K A A S
kelvin automotive appraising services


6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Our Reference
Vehicle Number

: KAAS/TA/5924/0709/TP/11.19
: GBG 709D

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered **Squarely to the Rear** portion of the vehicle.



The general area of damages is at the **Front and Rear portion**
(Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs **Auto Best Motor Services** is \$ 11,373.70 .
We have adjusted the cost to \$ 9,200.21 and the repairer has agreed to undertake the repairs at a
Contract Lump Sum of \$ 7,350.00 to a acceptable quality and standards.
However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of **7** working days.

26 photographs were taken at the time of static inspection.

This report is strictly done in a **Without Prejudice Basis**.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No. **5924** for our services rendered and
we thank you for engaging our services.

TERRENCE HONG
Dip Engineering / DECC (SP)
Certs Automotive Technology (NP)
Cert. Crash Investigation & Reconstruction
Cert SCI (General Insurance)
AMSAAA, AM SAE-A

KELVIN TEO
Licensed Automotive Appraiser
Nitec in Automotive Technology
Cert. Crash Investigation & Reconstruction
Dip MS
MSAAA, AM SAE-A

NOTE : This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify

KAAS
kelvin automotive appraising services

6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Our Reference : KAAS/TA/5924/0709/TP/11.19
Vehicle Number : GBG 709D

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
NETT ITEMS:-					
1	1 pc	tailgate	buckled	\$ 1,399.70	\$ ^{Rx} 1,399.70
2	1 pc	tailgate "nissan" sticker	necessary	\$ 141.80	\$ 141.80
3	1 pc	rear step panel	buckled	\$ 740.30	\$ ⁵⁰⁰ 740.30
4	1 pc	l/h taillamp	broken	\$ 248.60	\$ ²⁰⁸ 248.60
5	1 pc	r/h taillamp	cracked	\$ 248.60	\$ ²⁰⁸ 248.60
6	1 pc	rear floor panel	buckled	repair	repair
7	1 pc	front bumper	deformed	\$ 945.10	\$ ^{923.10} 945.10
8	1 pc	front grille - complete	cracked	\$ 578.60	\$ ^{461.90} 578.60
9	1 pc	front logo	necessary	\$ 55.10	\$ 55.10
10	1 pc	front panel	buckled	\$ 1,412.70	\$ 1,412.70
11	1 pc	front panel "cabstar" emblem	necessary	\$ 33.00	\$ 33.00
12	1 pc	l/h headlamp	unconfirmed	\$ 473.40	not affected
13	1 pc	r/h headlamp	unconfirmed	\$ 473.40	not affected
14	1 pc	front windscreen moulding	NECESSARY	\$ 363.40	\$ ²⁰⁰ 363.40
				\$ 7,113.70	\$ ^{4123.60} 6,166.90
Less 10%					\$ 616.69
				\$ 7,113.70	\$ ^{3711.24} 5,550.21
SPECIAL NETT ITEMS:-					
15	1 set	reverse sensor	not working	\$ 300.00	\$ ²⁰⁰ 250.00
16	1 roll	rear reflective sticker	necessary	\$ 50.00	\$ 50.00
				\$ 350.00	\$ ²⁵⁰ 300.00
Sub - Total				\$ 7,463.70	\$ 5,850.21



6 tampines st 73, #01-03, singapore 528825
 tel: 6746 2118 fax: 6746 1148
 reg no: 53058468m

Our Reference : KAAS/TA/5924/0709/TP/11.19
 Vehicle Number : GBG 709D

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 7,463.70	\$ 5,850.21
		LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts		\$ 1,600.00	\$ 1100 1,400.00
2		To check front wiring and rewire		\$ 60.00	\$ 30 50.00
3		To remove and reinstall front windscreen		\$ 150.00	\$ 120.00
4		To remove and reinstall dashboard		\$ 280.00	\$ Xnn 250.00
5		To check rear wiring and rewire		\$ 60.00	\$ 30 50.00
6		To remove and reinstall tailgate components		\$ 80.00	\$ 60.00
7		To remove and reinstall reverse sensor		\$ 140.00	\$ 40 100.00
8		To apply anti-rust		\$ 140.00	\$ 60 120.00
9		To putty and spray-paint of affected areas		\$ 1,400.00	\$ 800 1,200.00
				\$ 3,910.00	\$ 3,350.00
					2240
					6201.24
					45000
					7 days
		Sub - Total		\$ 11,373.70	\$ 9,200.21