

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20005202/ACF3E2

**Date:** 10/03/2021

### REFERENCE

Insured/Claimant:	NG RUI ZHI	Policy No:	1900114746		
Date of Loss:	08/04/2020	Nature of Claim:	OD	Claim No:	5401997239SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM4965S		
Make & Model:	AUDI A4, 2.0 TFSI QU S-TRONIC (A)	Engine No:	CVK079993
Reg. Date:	28/06/2019 (Man. Year: 2019)	Chassis No:	WAUZZZF41KN011524
Colour:	White	Odometer:	3855 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$128,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

*The above values represent the remaining tyre tread depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,800.00	23,092.96	13,707.04	37.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,364.00	7,264.00	5,100.00	41.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>49,164.00</b>	<b>30,356.96</b>	<b>18,807.04</b>	<b>38.25</b>
<b>- Excess (S\$)</b>	<b>800.00</b>	<b>800.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>48,364.00</b>	<b>29,556.96</b>	<b>18,807.04</b>	<b>38.89</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>3,385.48</b>	<b>2,068.99</b>	<b>1,316.49</b>	<b>38.89</b>
<b>Nett Amount (S\$)</b>	<b>51,749.48</b>	<b>31,625.95</b>	<b>20,123.53</b>	<b>38.89</b>

### INSPECTION

Date of Assignment:	14/04/2020		
Date Inspected:	14/04/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	10.0 days		

**Adjuster:** ADRIAN LING

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,068.00 FS	*1,654.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	553.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	67.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	185.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	198.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE - LH / RH	Not Necessary	118.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,254.00 FS	*1,003.20 FS
8	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	254.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Bent	757.00 FS	*605.20 FS
10	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	117.00 FS	*93.60 FS
11	1		*FRONT BUMPER COVER	Deformed	120.00 FS	*96.00 FS
12	2		*FRONT BUMPER GUIDE SECTION - LH / RH	Not Necessary	68.00 FS	*- FS
13	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.24 FS
14	1		*AIRCON STICKER	Necessary	7.00 FS	*5.36 FS
15	1		*LOCK CARRIER BRACKET	Cracked	129.00 FS	*103.20 FS
16	2		*FRONT BUMPER SUPPORT - LH / RH	Cracked	54.00 FS	*42.24 FS
17	2		*FRONT PARKING AID SENSOR - INNER / OUTER (NPA)	Not Necessary	0.00 FS	*- FS
18	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
19	1		*HORN - LH HIGH TONE	Not Necessary	38.00 FS	*- FS
20	1		*HORN - RH LOW TONE	Not Necessary	270.00 FS	*- FS
21	2		*SPRING SHACKLE - LH / RH	Not Necessary	54.00 FS	*- FS
22	1		*FRONT FENDER - LH / RH	O/S Buckled	1,444.00 FS	*577.60 FS
23	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	190.00 FS	*- FS
24	2		*FRONT FENDER CLOSING ELEMENT - LH / RH	Not Necessary	94.00 FS	*- FS
25	1		*FRONT FENDER BRACKET LH / RH	O/S Buckled	66.00 FS	*26.24 FS
26	2		*STONE CHIP GUARD - LH / RH	Not Necessary	96.00 FS	*- FS
27	1		*BONNET	Dented	2,634.00 FS	*2,107.20 FS
28	1		*BONNET ATTACHMENT PARTS	Not Necessary	388.00 FS	*- FS
29	2		*BONNET LID HINGE - LH / RH	Not Necessary	574.00 FS	*- FS
30	1		*BONNET IMPACT PROTECTION - CENTRE	Necessary	26.00 FS	*20.56 FS
31	2		*BONNET IMPACT PROTECTION - LH / RH	Necessary	52.00 FS	*41.36 FS
32	2		*TOP FENDER LEDGE COVER LH / RH INNER	Necessary	58.00 FS	*46.40 FS
33	2		*TOP FENDER LEDGE COVER LH / RH OUTER	Necessary	42.00 FS	*33.44 FS
34	2		*BONNET GAS FILLED STRUT	Not Necessary	224.00 FS	*- FS
35	2		*BONNET STRIKER - LH / RH	Bent	94.00 FS	*75.04 FS
36	2		*BONNET LID LOCK	Damaged	403.00 FS	*322.40 FS
37	1		*BONNET BOWDEN CABLE - CENTRE	Damaged	54.00 FS	*43.20 FS
38	1		*BONNET BOWDEN CABLE	Damaged	54.00 FS	*43.20 FS
39	1		*BONNET RELEASE LEVER	Damaged	13.00 FS	*10.00 FS
40	1		*BONNET SOUND ABSORBER	Not Necessary	323.00 FS	*- FS
41	2		*LED HEADLIGHT - LH / RH	Cracked	14,642.00 FS	*11,713.60 FS
42	1		*MAIN LIGHT ELECTRONICS POWER MODULE	Not Necessary	732.00 FS	*- FS
43	1		*LIGHT CONTROL SYSTEM CONTROL UNIT	Necessary	707.00 FS	*565.60 FS
44	1		*HEADLIGHT HOSE - LH	Not Necessary	34.00 FS	*- FS
45	1		*HEADLAMP HOUSING REPAIR KIT - LH	Not Necessary	124.00 FS	*- FS
46	2		*LIFT CYLINDER - LH / RH	Not Necessary	396.00 FS	*- FS
47	1		*LOCK CARRIER	Cracked	956.00 FS	*764.40 FS
48	2		*COOLANT REGULATOR SUPPORT	Not Necessary	71.00 FS	*- FS
49	1		*EXTERNAL TEMPERATURE SENSOR	Not Necessary	55.00 FS	*- FS
50	1		*TEMPERATURE SENSOR BRACKET	Cracked	18.00 FS	*13.68 FS
51	1		*AIRCON CONDENSER	Bent	586.00 FS	*468.80 FS
52	1		*RADIATOR	Dented	766.00 FS	*612.40 FS
53	1		*READY MIX COOLANT	Necessary	176.00 FS	*134.72 FS
54	1		*CHARGE AIR COOLER	Not Necessary	552.00 FS	*- FS
55	1		*AIR INTAKE AIR DUCT - RH	Not Necessary	21.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*AIR INTAKE AIR GUIDE	Not Necessary	50.00 FS	*- FS
57	1		*AIR INTAKE AIR ASS METER	Not Necessary	546.00 FS	*- FS
58	1		*AIR INTAKE HOSE	Not Necessary	90.00 FS	*- FS
59	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
60	1		*SUNDRIES	Necessary	400.00 FS	*46.64 FS
61	1		*RADIATOR UPPER SECURING PIN	Not Necessary	6.00 FS	*- FS
62	1		*RADIATOR AIR GUIDE INNER LHS	Cracked	27.00 FS	*21.04 FS
63	1		*RADIATOR AIR GUIDE INNER RHS	Cracked	27.00 FS	*21.04 FS
64	1		*RADIATOR AIR GUIDE OUTER LHS	Cracked	12.00 FS	*8.88 FS
65	1		*RADIATOR AIR GUIDE OUTER RHS	Cracked	12.00 FS	*8.88 FS
66	1		*RADIATOR FAN RING	Cracked	240.00 FS	*191.60 FS
67	1		*RADIATOR FAN WITH CONTROL UNIT	Damaged	1,877.00 FS	*1,501.60 FS
68	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	88.00 FS	*- FS
69	1		*AIR INTAKE AIR FILTER	Not Necessary	362.00 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Total Parts (S\$)</b>	<b>36,800.00</b>	<b>23,092.96</b>
--------------------------	------------------	------------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND RENEW AIRCOND CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	1,200.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	6,300.00	3,000.00
4	TO RESPRAY FRONT BUMPER, BONNET, HINGES AND BOTH FRONT FENDERS	New	4,000.00	2,200.00
5	TO CARRY OUT PRE-DIAGNOSTIC CHECK AND POST-DIAGNOSTIC CHECK	New	384.00	384.00
<b>Gross Labour Cost (\$\$)</b>			<b>12,364.00</b>	<b>7,264.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >