



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2005658
INV Date 18/08/2020
Reference CC4/FCI20005203/Kga3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SMQ 3417T
Insured Veh. SHA 4420U
Claim No. D20001851MFSH
Policy No. D-20094922MFSH
Accident Date 09/04/2020
Inspection Date 14/04/2020

Description	Total
Survey Inspection	349.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	349.00
GST (7%)	24.43
Grand Total	373.43

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20005203/Kga3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 18-08-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4420U	Veh. Inspected	SMQ 3417T	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20001851MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	14/04/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA SHUTTLE (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	GP72005277	Colour	METALLIC PEARL WHITE	
Odometer	34450	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Front Tyre	185/60 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	185/60 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/04/2020	Inspection Date	14/04/2020	
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 Sector C SINGAPORE 575643.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 3417T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	BENT	1,193.00	1,193.00
1	TAILGATE LOGO	NECESSARY	38.00	38.00
1	TAILGATE EMBLEM -SHUTTLE	NECESSARY	55.00	55.00
1	TAILGATE EMBLEM -HYBRID	NECESSARY	80.10	80.10
1	REAR BUMPER	BUCKLED	1,150.60	1,150.60
2	REAR BUMPER RETAINER @\$26.50	DISTORTED	53.00	53.00
1	REAR BUMPER SIDE COVER -LH	SERVICEABLE	45.00	-
1	REAR BUMPER REFLECTOR LH	CRACKED	45.00	45.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	560.80	-
1	REAR END PANEL TOP GARNISH	SERVICEABLE	155.50	-
1	REAR LH FENDER	TO REPAIR SEE LABOUR	1,010.90	-
1	REAR LH FENDER AIR DUCT	DISTORTED	38.50	38.50
1	REAR LH FENDER INNER TRIM	BUCKLED	455.00	455.00
1	REAR LH FLOOR PANEL	TO REPAIR SEE LABOUR	255.20	-
1	REAR LH FLOOR DECK BOX	SERVICEABLE	350.00	-
2	REAR LH QUARTER GLASS MOULDING @\$120.00	NOT NECESSARY	240.00	-
1	LH TAILLAMP	SERVICEABLE	520.50	-
1	REAR WINDSCREEN GLASS MOULDING	NECESSARY	80.50	80.50
1	REAR LH UNDER COVER	SERVICEABLE	105.00	-
	LESS 20% DISCOUNT		-1,286.32	-637.74
			5,145.28	2,550.96
<u>SPECIAL NETT ITEMS</u>				
1	REAR LH QUARTER GLASS SEALANT (SN)	NOT NECESSARY	40.00	-
1	REVERSE SENSOR (SN)	SERVICEABLE	350.00	-
1	REAR WINDSCREEN GLASS SEALANT (SN)	NECESSARY	40.00	40.00
			430.00	40.00
<u>LABOUR</u>				
	TO INSTALL REVERSE SENSOR .		40.00	40.00

Report Ref No. CC4/FCI20005203/Kga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS .		150.00	120.00
	TO REMOVE AND REFIT REAR LH QUARTER GLASS .	NOT NECESSARY	100.00	-
	TO REMOVE AND REFIT REAR SEATS AND UPHOLSTERY.		160.00	100.00
	TO REMOVE AND REFIT FUEL FILLER PIPE AND HOSES.	NOT NECESSARY	80.00	-
	TO SUPPL PANEL SEALANT AND TO SEAL OFF ALL WELD SPOT SEAMS AND GAPS.	NOT NECESSARY	90.00	-
	TO SPRAY RUBBERIZED UNDER COATING.		120.00	30.00
	TO REMOVE AND REFIT HYBRID BATTERIES AND TO USE DIAGNOSTIC COMPUTER TO REACTIVATE THE SYSTEM.	NOT NECESSARY	400.00	-
	TO KNOCK JACKOUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN, REFIX AND TO RENEW ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL,REAR LH FENDER AND REAR LH FLOOR PANEL .		1,300.00	900.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		1,000.00	800.00
			3,440.00	1,990.00
GRAND TOTAL			9,015.28	4,580.96
RECOMMENDED COST OF REPAIRS				4,580.96

Report Ref No. CC4/FCI20005203/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMQ 3417T

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMQ 3417T

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMQ 3417T

RE-INSPECTION

