



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 5332C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE (CONSISTENT)	DENTED	1,250.30	1,100.00
1	TAILGATE EMBLEM 'VEZEL' (CONSISTENT)	NECESSARY	76.80	76.80
1	TAILGATE INNER LOCK (CONSISTENT)	DAMAGED	256.00	256.00
1	TAILGATE INNER TRIM (CONSISTENT)	NOT NECESSARY	310.00	-
1	TAILGATE WEATHERSTRIP (CONSISTENT)	CUT	211.00	211.00
1	TAILGATE WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	145.00	145.00
1	REAR BUMPER (CONSISTENT)	DEFORMED	965.00	518.00
2	REAR BUMPER SIDE RETAINER @\$56.00 (CONSISTENT)	NECESSARY	112.00	112.00
1	REAR END PANEL (CONSISTENT)	DENTED	588.30	588.30
1	REAR END PANEL TOP GARNISH (CONSISTENT)	DEFORMED	136.50	136.50
1	REAR CONCAVE BUMPER RH (CONSISTENT)	NOT NECESSARY	230.00	-
	LESS 20% DISCOUNT		-856.18	-628.72
			3,424.72	2,514.88
<b><u>SPECIAL NETT ITEMS</u></b>				
1	TAILGATE INNER TRIM CLIP (SN) (CONSISTENT)	NOT NECESSARY	20.00	-
1	TAILGATE WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	60.00	60.00
1	REAR BUMPER CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	20.00
1	REAR END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	60.00	60.00
1	REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	20.00	10.00
1	REVERSE SENSOR (SN) (CONSISTENT)	DAMAGED	220.00	200.00
			400.00	350.00
<b><u>LABOUR</u></b>				
	TO PANEL BEAT ,REMOVE AND REPLACE PARTS.		1,000.00	800.00
	TO SPRAY PAINT AFFECTED AREA.		1,000.00	700.00
	WIRING CHECK.		60.00	30.00
	TUFF COAT.		150.00	60.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		100.00	50.00
	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING.		100.00	50.00

Report Ref No. CC4/ASM20005205/Aba3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TRANSFER TAILGATE MECHANISM .		120.00	60.00
	REMOVE AND REFIX TAILGATE WINDSCREEN.		140.00	120.00
			2,670.00	1,870.00
GRAND TOTAL			6,494.72	4,734.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,700.00

Report Ref No. CC4/ASM20005205/Aba3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.