

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20005208/AGA3Q2

Date: 30/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100414722
Claimant
Vehicle No : SFS8868P **Insured Vehicle No :** SFY5066A
Date of Loss: 07/04/2020 Nature of Claim: TP Claim No: 1824724972SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFS8868P**
Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A) Engine No: HRA2335088A
Reg. Date: 15/12/2016 (Man. Year: 2016) Chassis No: SJNFEAJ11U1773981
Colour: White Odometer: 39232 km
Engine Capacity: 1197 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,225.45	969.41	1,256.04	56.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	480.00	880.00	64.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,585.45	1,449.41	2,136.04	59.58
+ GST 7.00/7.00% (S\$)	250.98	101.46	149.52	59.57
Nett Amount (S\$)	3,836.43	1,550.87	2,285.56	59.58
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,702.87		
Global Sum Settlement (S\$)		1,700.00		

INSPECTION

Date of Assignment: 14/04/2020
Date Inspected: 14/04/2020 Inspected At: Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit
AutoHub
Singapore 417921
Estimated Period of Repair: 2.0 days

Adjuster: ADRIAN LING

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Deformed	976.10 FN	*796.70 FN
2	2		*REAR BUMPER SIDE HOLDER L/R	Not Necessary	150.40 FN	*- FN
3	1		*REAR BUMPER INNER SPONGE	Not Necessary	174.30 FN	*- FN
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	691.50 FN	*- FN
5	1		*REAR TOW HOOK COVER	Cut	58.20 FN	*58.20 FN
6	1		*SET REVERSE SENSOR	Cracked	380.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$)	2,430.50	1,054.90
- Nett Item Discount on N Items 10.00/10.00% (\$)	205.05	85.49
Total Parts (\$)	2,225.45	969.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	60.00	30.00
2	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	800.00	200.00
3	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	500.00	250.00
			Gross Labour Cost (\$)	480.00
			1,360.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >