

22/02/2021

ASS. REC. BY:

REF: CS/MSG20005220/UVf3

Special Instruction:

Surveyor: MARCUS ASSIGNMENT (Office)

merimen

From (Person): Irene Tan Gek Jng of MSIA Date/Time: 15.4.20 15.45p.m

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD ~~TP~~/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJV 4519K Insured: SJN 7502E

at Workshop m/s Zoom Auto Works Tel: 94507920

of 15 Kaki Bukit Road 4 #01-53

Policy No: A80368574 QMY Claim No: 623181

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 11.4.20  
(Client's Record)

CA / REV / REP. / REV 24 HRS MP H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 15.4.20 15.45p.m Person Contacted: Elin Vehicle: IN/OUT

Date/Time	Action/Instruction ( ✓ ) Estimate.
	<u>SJV 4519K - 706 / MSG / 1523579 / 15.4.20 - 02/12/2017</u>
	<u>SJV 7502E - X</u>
<u>27/11/20</u>	<u>Send preli revised via merimen</u>

ASS. REC. BY: *Marcus*

REF:

*CS/M5920005220/443*

ASSIGNMENT

From \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
DD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: *SJV 4519K*  
at Workshop no's: *2000*  
of \_\_\_\_\_  
insured: \_\_\_\_\_  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No: *SJV 4519K* Yr Regn: *1, 10*  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or LA /  
Make: *Toyota* *1105* CC: *1497*  
Colour: *Black* A/C: Insured / Std / NI / NA  
Sp Reading: *88 491* T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: *M R 053H49305135328*  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Insured / Jammed / Leaked / Burnt or  
Brake: Insured / Jammed / Leaked / Burnt or  
Modi: Nil / Custom / STD A/Rim or  
Tyre Size: F: *185 / 60 R 15*  
R: \_\_\_\_\_

(Policy Condition)  
Remark: The veh had commenced its  
repair at the time of inspection  
*24h.*  
Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
Est. Repairs: *8* days Res.: Yes or No  
Lump Sum: *20* % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS *036B*  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
R/Bal: *6* mm R/Bal: *6* mm  
L/Bal: *6* mm L/Bal: *6* mm  
D.O.A: *11/4/20* D.O.I: *15/4/20*  
Survey held at: \_\_\_\_\_  
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
*Rear*  
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
*25-1-2025 15453*  
*awaiting estimate. GIA of merimen.*

*27/4/20 4/5 @ 6000 confirmed with SLI (Real 973192, 6290)*

Date/Time File Pass to? : Prel. Report  
: Final Report

Days Of Repair: *8*  
Resurvey No. of Trip: *2*

Date/Time File Return to?  
*27/4 - typist*

Add Fee:  Site Insp (\$)  
 Interview (\$)  
 Tech. Invs (\$)  
 Weekend (\$)

Survey Fee: \_\_\_\_\_  
Transportation: \_\_\_\_\_  
S - RS - SI  
Photos  
Other  
TOTAL

Report Format: *Merimen*  
Lump Sum / I.B.I.: (\$ *6000*)

1/5 # 6000



**ZOOM AUTOWERKS PTE LTD**

130 Bedok Reservoir Road, Eunos Spring  
 #08-1339 Singapore 470130  
 Tel: 9450 7920  
 zoomautowerks@gmail.com

Car Number: SJV4519K  
 Model: TOYOTA VIOS  
 Damaged Area: (Rear Portion)  
 Repairer Estimation Cost of Repair :  
 Supplementary may be included during the cost of repair :

Date: 16/04/2020

not Approved  
 Make  
 15/4/20 8 days.

**Parts / Material :**

	1	Rear Bumper	459.75
2 pcs	2	Rear Bumper Side Retainer @ 65.00	
2 pcs	3	Rear Bumper Bracket @ 78.00	
2 pcs	4	Rear Bumper Reflector @ 168.00	106.25
1 set	5	Rear Bumper Clips	45.00
	6	Rear Bootlid	662.90
	7	Rear Bootlid weatherstrip	162.84
	8	Rear Bootlid Inner Lock	145.00
	9	Rear Bootlid Catch	
	10	Rear Bootlid Logo	48.50
2 pcs	11	Rear Bootlid Hinge @ 68.40	
2 pcs	12	Rear Taillamps @ 699.60	481.65 x 2 = 963.30
2 pcs	13	Rear Taillamps Panel @ 385.70	155.10
	14	Rear End Panel	645.00
	15	Rear End Panel Top Garnish	112.00
	16	Rear End Panel Top Garnish Clips	
2 pc	17	Rear Fender @ 1194.50	
2 pcs	18	Rear Fender Inner Trim Garnish @ 385.70	286.50
	19	Rear Fender Inner Trim Garnish Clips	
2 pcs	20	Rear Fender Inner Shield @ 176.00	58.50
	21	Rear Left Fender Inner Shield Clips	
	22	Rear Spare Tyre Top Garnish board	202.60
2 pcs	23	Rear Spare Tyre Top Foam @ 325.60	185 x 2 = 370
	24	Rear Spare Tyre Panel	781.65
	25	Rear Exhaust Pipe	
	26	Rear Exhaust Chrome Muffler	65.00
2 pc	27	Rear Exhaust Mouting @ 48.00	

Dr.S	\$	758.40	
Beef	\$	130.00	
See	\$	156.00	X
o/s car	\$	336.00	1 pc
see	\$	60.00	
see	\$	799.40	
see	\$	198.70	
see	\$	195.80	
see	\$	58.70	X
see	\$	75.90	
see	\$	136.80	X
see	\$	1,399.20	
o/s beef	\$	771.40	1 pc
see	\$	756.70	
see	\$	165.80	
see	\$	60.00	X
see	\$	2,389.00	X
o/s trim	\$	771.40	1 pc
see	\$	80.00	X
o/s trim	\$	352.00	1 pc
see	\$	80.00	X
see	\$	265.40	
see	\$	651.20	
crumpd/see	\$	980.00	
see	\$	824.70	X
see	\$	175.40	
see	\$	144.00	X
Parts :	\$	12,771.90	
Less Parts 25% :	\$	3,192.97	
<b>Total Parts :</b>	<b>\$</b>	<b>9,578.92</b>	<b>5403.29</b>

**Special Net Items :**

1 set	Rear Windscreen Inner Seal/Damper
	Rear Winscreen Sealant
	Rear Fender Sealant
	Rear Taillamp Panel Sealant
	Rear End Panel Sealant
	Rear Spare Tyre Panel Sealant
	Rear Exhaust Gum
	Rear Number Plate W/Base Garnish
1 set	Reverse Sensor

see	\$	148.00	30
see	\$	75.00	40
see	\$	160.00	X
see	\$	80.00	X
see	\$	80.00	50
see	\$	80.00	X
see	\$	120.00	X
see	\$	80.00	40
see	\$	280.00	200
<b>Total S/N Parts :</b>	<b>\$</b>	<b>1,103.00</b>	

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas	\$	2,200.00	1500
To Putty, Spray Paint on Affected Accident Areas	\$	1,800.00	1200
To Remove & Install Rear Exhaust to Facilitate Repairs	\$	150.00	60
To Remove & Install Fuel Tank to Facilitate Repairs	\$	200.00	60
To Check & Re-Connect all electrical wiring	\$	50.00	30
To Remove & Install Rear Bootlid Components Trim & Garnish	\$	150.00	60
To Remove & Install Rear Fenders Trim, Garnish	\$	150.00	80
To Conduct Water Leakage Test	\$	150.00	2
To Rust Proof Affected Areas	\$	200.00	100
<b>Total Labour :</b>	<b>\$</b>	<b>5,050.00</b>	

TOTAL PARTS :	\$	9,578.92
TOTAL SPECIAL NET ITEM :	\$	1,103.00
TOTAL LABOUR :	\$	5,050.00
<b>TOTAL REPAIR COST :</b>	<b>\$</b>	<b>15,731.92</b>

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-5403-29  
25-7  
P-4652-46  
S.N-360.00  
L-3090.00  
7502.46  
22  
6001.96.