Page 1 of 3 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20005222/UYF3E2

Date: 28/04/2020

REFERENCE

No:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100510491 Claimant Vehicle SFW9797H Insured Vehicle No: **SLQ1100G**

Date of Loss: 09/04/2020 Nature of Claim: TP Claim No: 1689744584SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SFW9797H

Make & Model: MERCEDES-BENZ C180, 1.6 (A) Engine No: 27491030011730 Reg. Date: 27/09/2012 (Man. Year: 2012) Chassis No: WDD2040312A760202

Colour: Odometer: 256701 km Black

Engine Capacity: 1595 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** No Pre-accident Condition: Yes

CONDITION OF TYRES

225/45 R17 Front Tyre Size: 225/45 R17 Rear Tyre Size: Front Left Side: Rear Left Side: Michelin 6 mm Michelin 6 mm Rear Right Side: Front Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---------------------|------------|------------|------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

Date of Assignment: 15/04/2020

Date Inspected: 15/04/2020 Inspected At: Bluwel Automotive Service Pte Ltd (HQ)

1 Kaki Bukit Avenue 6, #01-28/37/53/55/56

Autobay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 6.0 days

Manager: YVONNE WONG YIN CHENG MARCUS CHUA Adjuster:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---------|----------|------------------------------------|-------------------|------------|--------|
| 1 | 1 | | *BOOTLID | Dented / Buckled | 0.00 F | *- F |
| 2 | 1 | | *BOOTLID REAR LOGO | Necessary | 0.00 F | *- F |
| 3 | 1 | | *BOOTLID C180 EMBLEM | Necessary | 0.00 F | *- F |
| 4 | 1 | | *BOOTLID TG-TRONIC EMBLEM | Necessary | 0.00 F | *- F |
| 5 | 1 | | *BOOTLID C&C LOGO | Necessary | 0.00 F | *- F |
| 6 | 1 | | *BOOTLID INNER LOCK | Twisted | 0.00 F | *- F |
| 7 | 1 | | *BOOTLID WEATHERSTRIP | Twisted | 0.00 F | *- F |
| 8 | 1 | | *REAR BUMPER | Distorted | 0.00 F | *- F |
| 9 | 1 | | *REAR BUMPER CHROME MOULDING | Necessary | 0.00 F | *-F |
| 10 | 2 | | *REAR BUMPER CHROME MOULDING SIDES | Necessary | 0.00 F | *- F |
| 11 | 2 | | *REAR BUMPER SIDE RETAINERS | Cracked | 0.00 F | *- F |
| 12 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 0.00 F | *- F |
| 13 | 1 | | *REAR BUMPER REINFORCEMENT | Dented | 0.00 F | *- F |
| 14 | 1 | | *REAR END PANEL | Dented | 0.00 F | *- F |
| 15 | 1 | | *REAR END PANEL TOP GARNISH | Twisted | 0.00 F | *- F |
| 16 | 1 | | *REAR EXHAUST | Repair | 0.00 F | *- F |
| 17 | 2 | | *TAILLAMPS | Cracked | 0.00 F | *- F |
| 18 | 1 | | *REAR FENDER | Repair | 0.00 F | *- F |
| 19 | 1 | | *REAR TOP RETAINER | Cracked | 0.00 F | *- F |
| 20 | 1 | | *SET REAR BUMPER REVERSE SENSOR | Shorted | 0.00 F | *- F |
| F=Fra | anchise | part. | | T-4-1 D4- (0¢) | 0.00 | 0.00 |
| | | | | Total Parts (S\$) | 0.00 | 0.00 |

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >