

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 688X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	CRACKED	3,125.80	1,050.50
1	FRONT BUMPER SIDE RETAINER RH	NECESSARY	65.80	65.80
1	FRONT BUMPER FOG LAMP MESH RH	SERVICEABLE	155.40	-
1	HEADLAMP RH	SCRATCHED	785.50	785.50
	LESS 10% DISCOUNT		-413.25	-190.18
			3,719.25	1,711.62
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	55.00	25.00
1	FRONT BUMPER LOWER SPOILER (SN) (LOCAL REPAIR)	DEFORMED / DAMAGED	1,200.00	100.00
			1,255.00	125.00
	<u>LABOUR</u>			
	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE 'PARTS REPAIR' COLUMN INCLUSIVE OF REPLACEMENT PARTS.		720.00	300.00
	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIALS.		500.00	360.00
	APPLY RUST PROOFING ON THE ADJACENT PANELS.		20.00	20.00
	WIRING AND BULB CHECKING.		24.00	20.00
			1,264.00	700.00
	GRAND TOTAL		6,238.25	2,536.62
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,000.00

Report Ref No. CS3/AIG19022123/Hvf3e2-1

LEE HOCK ANN

Asst. Automotive Assessor

ADRIAN LING WAI PING**B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.