



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS3/AIG19022123/Hvf3e2-1

78 SHENTON WAY #09-16

AIG BUILDING

SINGAPORE 079120

Date : 21-04-2020



ATTN : LOH CHEE HENG

Code : AIG

#### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |               |                       |            |
|---------------------|---------------|-----------------------|------------|
| <b>Insured Veh.</b> | SJU 1999H     | <b>Veh. Inspected</b> | SMC 688X   |
| <b>Policy No.</b>   | 2100506016-02 | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | 3462512162SG  | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | LOH CHEE HENG | <b>Assign Date</b>    | 13/04/2020 |

#### 2. Vehicle Particulars & Condition

|                         |                       |                     |            |
|-------------------------|-----------------------|---------------------|------------|
| <b>Make &amp; Model</b> | MITSUBISHI EVO 10 GSR | <b>c.c</b>          | 1998       |
| <b>Engine No.</b>       | HIDDEN                | <b>Year of Reg.</b> | 2008       |
| <b>Chassis No.</b>      | CZ4A0004151           | <b>Colour</b>       | WHITE      |
| <b>Odometer</b>         | 180818                | <b>Steering</b>     | IN ORDER   |
| <b>Brakes</b>           | IN ORDER              | <b>Modification</b> | SPORTS RIM |
| <b>General</b>          | GOOD                  |                     |            |

#### 3. Conditions of Tyres

|                       |             |             |                |
|-----------------------|-------------|-------------|----------------|
|                       | <b>Size</b> | <b>Make</b> | <b>Balance</b> |
| <b>R/H Front Tyre</b> | 265/35Z R18 | DUNLOP      | 5 mm           |
| <b>L/H Front Tyre</b> | 265/35Z R18 | DUNLOP      | 5 mm           |
| <b>R/H Rear Tyre</b>  | 265/35Z R18 | DUNLOP      | 5 mm           |
| <b>L/H Rear Tyre</b>  | 265/35Z R18 | DUNLOP      | 5 mm           |

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

#### 5. General Information

|                       |                                       |                        |            |
|-----------------------|---------------------------------------|------------------------|------------|
| <b>Accident Date</b>  | 04/12/2019                            | <b>Inspection Date</b> | 17/12/2019 |
| <b>Survey held at</b> | 25 KAKI BUKIT RD 4 #05-66 SYNERGY @KB |                        |            |
| <b>Repairer</b>       | TRIPLE-T AUTOMOBILE                   |                        |            |

#### 5a. Remarks

- A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

|                                            |                       |
|--------------------------------------------|-----------------------|
| <b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b> | <b>3 Working Days</b> |
|--------------------------------------------|-----------------------|