

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171**

Our reference:

19-12-8743

Date:

31/12/2019

c/o Triple-T Automobile Blk 6 Defu Lane 10 #01- 556 Singapore 539187

Dear Sirs

RE:

Road Traffic Accident on 4/12/2019

Lee Wei Ming Jeremie

In accordance with your instructions received in this office on

18/12/2019

, we made arrangements to

examine the vehicle on

18/12/2019

at above-mentioned address. The following data was

recorded:

Vehicle details


Make	Misubishi	Registration	SMC688X	
Model	EVO-10 GSR	Chassis	CZ4A0004151	
Colour	White	Gearbox	Manual	
Odometer	180818km	Paintwork	Good	
Steering	Good	Brakes	Good	
Condition	Good	g ga ma ga ma ma ga ga ma ga	등 수 및 가 및 E 등 등 등 등 등 이 C C 이 는 는 는 수 나는 음식을 가실 및 구 E 등 등 등 등 등 등 등 등 등 등 등 등 등	

Tyre Depths

Front left	265/35ZR18	85% Dunlop
Front right	265/35ZR18	85% Dunlop
Rear left	265/35ZR18	85% Dunlop
Rear right	265/35ZR18	85% Dunlop

Status	REPAIRABLE		
Magnitude	Medium		
Legal status	Unroadworthy		

Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$5,200.00 and 5 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

- Impact Analysis Consulting Pte Ltd Impact Analysis Academy Pte Ltd IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd Infoknights International Services (Philippines) IABN Pte Ltd



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Our reference

19-12-8743

Date

31/12/2019

Page

2

Section A: Damaged Parts Assessment

Section Al Sa				
art's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
t Items:				1
nt bumper CORA	1	deformed/sheared -off	3125.80	3125.80
t bumper side retainer rh	1	damaged	65.80	65.80
t bumper fog lamp mesh rh 🔀 (SV C)	1	damaged	155.40	155.40
allamp th / sch	1	shifted	785.50	785.50
	Sub- Tota	costs	4132.50	4132.50
Percentage	discount :	10%	413.25	413.25
Sub-	Tot ai cost	s for parts	3719.25	3719.25
lal Blabb Ibames				
Nett Items: pumper clips / nec	set	necessary	55.00	55.00 1200.00
bumper lower spoiler \times_{\neg} (\mathcal{R})	1	deformed/damaged_	1200.00	1290.00
st bumper lower spoiler X (R) Sub- (local report)	Total cost	s for parts	1255.00	1255.00
Repair				
	*	*	0.00	0.00
	Sub- Tota	l costs	0.00	0.00
To	tal costs f	or parts	4974.25	4974.25

[•] Impact Analysis Consulting Pte Ltd. • Impact Analysis Academy Pte Ltd. • IA Racking Solutions Pte Ltd

[●] IA Accounting & Consultancy Pte Ltd ● Infoknights International Services (Philippines) ● IABN Pte Ltd



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171**

Our reference

19-12-8743

Date

31/12/2019

Page

3

Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total	
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 48.00 15		\$ 720:00	
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$	500.00
Apply rust proofing on the adjacent panels.	Sub-con	tract work.	\$	20.00
Wiring and bulb checking	\$ 48.00	0.5	\$	24.00
	Total la	bour cost	\$	1,264.00

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

Manhour rate and the number of manna operating cost and in-house@ IA Research Gun.

Paper 6 4 70

I Sure and Manhouse and

Parts 190/180 Parts less 100/0 1711.62 spenett 125 106m 706 2536.62 4s fess 200/0 2029.29 total \$2000\$

[•] Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd

 [■] IA Accounting & Consultancy Pte Ltd
 ■ Infoknights International Services (Philippines)
 ■ IABN Pte Ltd



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171**

Our reference

19-12-8743

Date

31/12/2019

Section C: Summary Table of Total Repair Cost

Description Damaged Parts Assessment (See section A)		Cost	
		\$4,974.25	- 5 - 5 - 5 - 5 - 5 - 5 - 5 - 5 - 5 - 5
Further discount	20%	\$994.85	
Recommended cost of parts		\$3,979.40	(1)
	t Calculation ection B)	\$1,264.00	(2)
Total Repair Cost (Round off to hundred)		\$5,200.00	(1) + (2)

We would recommend a sum of	\$5,200.00	and	5 working days for rep	air.
No further items will be approved w	vithout our express	ed written agreen	nent. Any significant additional	
items will be subject to a supplement	ntary report.			

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma.Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

SPRING- Recognised Certification for Management Consultants

[•] Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd

[●] IA Accounting & Consultancy Pte Ltd ● Infoknights International Services (Philippines) ● IABN Pte Ltd