

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780

Hotline: 6385 1171

Our reference:

19-12-8743

Date:

31/12/2019

c/o Triple-T Automobile Blk 6 Defu Lane 10 #01-556 Singapore 539187

Dear Sirs

RE:

Road Traffic Accident on 4/12/2019

Lee Wei Ming Jeremie

In accordance with your instructions received in this office on

18/12/2019

, we made arrangements to

examine the vehicle on

18/12/2019

at above-mentioned address. The following data was

recorded:

Vehicle details

Make	Misubishi	Registration	SMC688X		
Model	EVO-10 GSR	Chassis	CZ4A0004151		
Colour	White	Gearbox	Manual		
Odometer	180818km	Paintwork	Good		
Steering	Good	Brakes	Good		
Condition	Good		***************************************		

Tyre Depths

Front left	265/35ZR18	85% Dunlop
Front right	265/35ZR18	85% Dunlop
Rear left	265/35ZR18	85% Dunlop
Rear right	265/35ZR18	85% Dunlop

Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$5,200.00 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd Infoknights International Services (Philippines) IABN Pte Ltd



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171**

Our reference

19-12-8743

Date

31/12/2019

Page

2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
List Items:	A Control and the Control and the Control of the Co	ras var et es et alle aussaurage en et til føre et en en et en	til militar – Ommer str. Millerstoff fr. publikel fræmskriverender. Der viker 20,5 i v	and help a served the first of the All Managember day Theory is a glasse of
Front bumper	1	deformed/sheared -off	3125.80	3125.80
Front bumper side retainer rh	1	damaged	65.80	65.80
Front bumper fog lamp mesh rh	1	damaged	155.40	155.40
Headlamp rh	1	shifted	785.50	785.50
	Sub- Tota	il costs	4132.50	4132.50
	Percentage discount :	10%	413.25	413.25
	Sub-Total cos	ts for parts	3719.25	3719.25
Special Nett Items:				
Front bumper clips	set	necessary	55.00	55.00
Front bumper lower spoiler	1	deformed/damaged_	1200.00	1200.00
	Sub-Total cos	ts for parts	1255.00	1255.00
Parts Repair				
St. replacement of the second	*	*	0.00	0.00
	Sub- Tota	ıl costs	0.00	0.00
	Total costs	for parts	4974.25	4974.25

Subsidiaries of Impact Analysis Consultant:

 [■] Impact Analysis Consulting Pte Ltd ● Impact Analysis Academy Pte Ltd ● IA Racking Solutions Pte Ltd

[●] IA Accounting & Consultancy Pte Ltd ● Infoknights International Services (Philippines) ● IABN Pte Ltd



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171**

Our reference

19-12-8743

Date

31/12/2019

Page

3

Section B: Labour Cost Calculation

	Но	urly rate	Manhr. Req.		Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$	48.00	15	\$	720.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work. \$!		500.00		
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$	20.00	
Wiring and bulb checking	\$	48.00	0.5	\$	24.00
		Total la	bour cost	\$	1,264.00

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

Subsidiaries of Impact Analysis Consultant:

[•] Impact Analysis Consulting Pte Ltd • Impact Analysis Academy Pte Ltd • IA Racking Solutions Pte Ltd

[●] IA Accounting & Consultancy Pte Ltd ● Infoknights International Services (Philippines) ● IABN Pte Ltd



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Our reference

19-12-8743

Date

31/12/2019

Section C: Summary Table of Total Repair Cost

Description Damaged Parts Assessment (See section A)		Cost	,
		\$4,974.25	3375
Further discount	20%	\$994.85	
Recommended cost of parts		\$3,979.40	(1)
	st Calculation ection B)	\$1,264.00	(2)
Total Repair Cost (Round off to hundred)		\$5,200.00	(1) + (2)

We would recommend a sum of	\$5,200.00	and	5	working days for repair.
No further Items will be approved	without our express	sed written agreem	ent. Any signific	cant additional
items will be subject to a suppleme	entary report.			

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma. Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

SPRING- Recognised Certification for Management Consultants

Subsidiaries of Impact Analysis Consultant:

● Impact Analysis Consulting Pte Ltd ● Impact Analysis Academy Pte Ltd ● IA Racking Solutions Pte Ltd

● IA Accounting & Consultancy Pte Ltd ● Infoknights International Services (Philippines) ● IABN Pte Ltd www.iaconsultingss.com













































