

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3402M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BUMPER	DEFORMED	1,052.20	1,052.20
1	FRT BUMPER UPR BRKT RH	DEFORMED	22.40	22.40
1	FRT BUMPER BRKT RH	DEFORMED	24.60	24.60
1	FRT BUMPER GRILLE RH	NOT NECESSARY	93.60	-
1	HEADLAMP RH	CRACKED	1,388.00	1,388.00
1	RADIATOR GRILLE	NOT NECESSARY	1,480.00	-
1	RADIATOR GRILLE H EMBLEM	NOT NECESSARY	39.50	-
1	BONNET HINGE RH	NOT NECESSARY	41.00	-
1	FRT FENDER RH	TO REPAIR SEE LABOUR	663.00	-
	LESS 20% DISCOUNT		-960.86	-497.44
			3,843.44	1,989.76
	<u>SPECIAL NETT ITEMS</u>			
1	FRT FENDER ADV STICKER RH (SN)	NECESSARY	100.00	100.00
			100.00	100.00
	<u>LABOUR</u>			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRT FENDER RH.		600.00	420.00
	SPRAYPAINT CHARGE.		500.00	400.00
	CHECK ALL LIGHTING.		40.00	30.00
	TUFF COAT ON AFFECTED PARTS.		40.00	30.00
			1,180.00	880.00
	GRAND TOTAL		5,123.44	2,969.76
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,350.00

Report Ref No. NS/INC20005228/T1qf3e2



MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.