

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20005231/QEA3Q2

Date: 18/03/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : PC4293P	Insured Vehicle No :	SHC8613T
Date of Loss: 26/03/2020	Nature of Claim: TP	Claim No: MCT20030461

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC4293P		
Make & Model:	MITSUBISHI ROSA, 3.0 D BE641JRMDEB (A)	Engine No:	4P10B82186
Reg. Date:	30/12/2015 (Man. Year: 2015)	Chassis No:	BE641JK30097
Colour:	White	Odometer:	215679 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	7.00 R16 LT	Rear Tyre Size:	7.00 R16 LT
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,101.17	139.46	1,961.71	93.36
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,260.00	750.00	510.00	40.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,361.17	889.46	2,471.71	73.54
Approved Total (Overridden) (S\$)		700.00		
(S\$)	3,361.17	700.00	2,661.17	79.17
+ GST 7.00/7.00% (S\$)	235.28	49.00	186.28	79.17
Nett Amount (S\$)	3,596.45	749.00	2,847.45	79.17
+ Loss of Use (4.0 x S\$150.00/day) (S\$)		600.00		
Nett Liability (S\$)		1,349.00		
Global Sum Settlement (S\$)		1,340.00		

INSPECTION

Date of Assignment:	16/04/2020	
Date Inspected:	16/04/2020 Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	2.0 days	

Adjuster: OI SUN PIN**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Feb 2021)	
Parts:	N/A	MITSUBISHI ROSA 3.0 D BE641JRMDEB (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC4293P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BODY PANEL SIGNAL LAMP RH	Crumpled	185.95 F	*185.95 FL
2	1		*REAR BUMPER	Repair	1,588.97 F	*- FL
3	1		*REAR BUMPER SIDE BRACKET RH	Repair	113.60 F	*- FL
4	1		*REAR BUMPER REFLECTOR RH	Serviceable	212.65 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,101.17	185.95
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	46.49
Total Parts (\$\$)	2,101.17	139.46

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RENEW REAR DAMAGED PARTS ,REPLACED AND REALIGNED HYDRAULIC ,ALIGNED ALL PARTS	New	500.00	300.00
2	TO RESPRAY AFFECTED AREAS	New	550.00	400.00
3	TO TUFFCOAT AFFECTED AREA	New	150.00	30.00
4	TO REMOVE /REFIX WIRING CHECKS	New	60.00	20.00
Gross Labour Cost (\$\$)			1,260.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >