

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20005239/UBA3Q2

Date: 08/12/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : FBK3722Z **Insured Vehicle No :** GBD1495D

Date of Loss: 13/03/2020 **Nature of Claim:** TP **Claim No:** 8541996235SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBK3722Z		
Make & Model:	YAMAHA TMAX530, 530cc CVT ABS	Engine No:	J409E058907
Reg. Date:	10/07/2015 (Man. Year: 2015)	Chassis No:	JYASJ099000010360
Colour:	Grey	Odometer:	23486 km
Engine Capacity:	530 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	120/70 R15	Rear Tyre Size:	160/60 R15
Front Left Side:	Metzeler 6 mm	Rear Left Side:	Metzeler 6 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,292.00	1,917.40	374.60	16.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,104.00	350.00	754.00	68.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	3,396.00	2,267.40	1,128.60	33.23
Approved Total (Overridden) (\$\$)		1,800.00		
(\$\$)	3,396.00	1,800.00	1,596.00	47.00
+ GST 7.00/7.00% (\$\$)	237.72	126.00	111.72	47.00
Nett Amount (\$\$)	3,633.72	1,926.00	1,707.72	47.00
+ Loss of Use (4.0 x S\$20.00/day) (\$\$)		80.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,013.45		
Global Sum Settlement (\$\$)		2,000.00		

INSPECTION

Date of Assignment: 16/04/2020

Date Inspected: 16/04/2020 Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)
No. 6 Defu Lane 4
Singapore 539410

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BODY COWLING LH	Cut	136.00 F	*136.00 FL
2	1		*BOX REAR (COOCASE) 60L	Cut	720.00 F	*720.00 FL
3	1		*CASE CHAIN 2	Cut	17.00 F	*17.00 FL
4	1		*COVER TAIL LH	Cut	208.00 F	*208.00 FL
5	1		*COVER ,1	Cut	14.00 F	*14.00 FL
6	1		*DAMPER 1	Necessary	2.00 F	*2.00 FL
7	1		*DAMPER 4 (BOARD FOOTREST)	Necessary	3.00 F	*3.00 FL
8	1		*DAMPER LOCATING 2	Necessary	7.00 F	*7.00 FL
9	1		*DAMPER PLATE	Necessary	7.00 F	*7.00 FL
10	1		*EMBLEM	Necessary	28.00 F	*28.00 FL
11	1		*EMBLEM (SIDE COVER)	Necessary	83.00 F	*83.00 FL
12	1		*LEG SHIELD 1	Cut	251.00 F	*251.00 FL
13	1		*LEVER 1	Scratched	58.00 F	*58.00 FL
14	1		*MIRROR REAR VIEW LH ASSY	Cut	104.00 F	*104.00 FL
15	1		*MOLE SIDE COVER 1	Cut	171.00 F	*171.00 FL
16	1		*PLATE 1	Bent	27.00 F	*27.00 FL
17	1		*STAND MAIN	Repair	191.00 F	*- FL
18	1		*HELMET (SCORPION) EXO CITY (BLACK)	Damaged	265.00 FS	*265.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,292.00	2,101.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	183.60
Total Parts (\$)	2,292.00	1,917.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	1,104.00	350.00
Gross Labour Cost (\$\$)			1,104.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >