



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2004831  
INV Date 08/07/2020  
Reference CC3/FCI20005250/Kga3q2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 5158E  
Insured Veh. SHB 4776M  
Claim No. D20001932MFSH  
Policy No. D-18088937MFSH  
Accident Date 14/04/2020  
Inspection Date 16/04/2020

Description	Total
Third Party Express Settlement	350.00
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC3/FCI20005250/Kga3q2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 08-07-2020



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 4776M	Veh. Inspected	SHD 5158E
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D20001932MFSH	Excess (\$)	0.00
Assign From		Assign Date	16/04/2020

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JTDKB3FU103078574	Colour	M.P. WHITE / RED
Odometer	152793	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	SAILUN	9 mm
L/H Front Tyre	195/65 R15	SAILUN	9 mm
R/H Rear Tyre	195/65 R15	SAILUN	9 mm
L/H Rear Tyre	195/65 R15	SAILUN	9 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	14/04/2020	Inspection Date	16/04/2020
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 5158E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	BUCKLED	442.60	442.60
1	REAR BUMPER REINFORCEMENT	BENT	332.70	332.70
1	REAR BUMPER TOWING COVER	DENTED	15.40	15.40
1	GUARD REAR BUMPER CENTER	CRACKED	576.30	576.30
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	116.50	-
1	REAR BUMPER SIDE RETAINER RH	DISTORTED	117.70	117.70
1	ANTENNA ,ELECTRICAL KEY	SERVICEABLE	72.00	-
1	REAR TAILGATE	TO REPAIR SEE LABOUR	1,147.80	-
1	REAR TAILGATE OUTER GARNISH	SERVICEABLE	925.60	-
1	REAR TAILGATE WEATHERSTRIP	SERVICEABLE	372.30	-
1	LOCK ASSY ,BACK DOOR ,W/COURTESY LAMP SWITCH	SERVICEABLE	467.00	-
1	PANEL SUB-ASSY ,BODY LOWER BACK	SERVICEABLE	650.30	-
1	TAILLAMP LOWER RH	CRACKED	502.00	502.00
1	TAILLAMP UPPER RH	SERVICEABLE	451.80	-
1	REAR BUMPER SIDE RH	MTG CRACKED	123.70	123.70
1	REAR BUMPER SIDE LH	SERVICEABLE	123.70	-
1	TAILLAMP LOWER LH	SERVICEABLE	502.00	-
1	TAILLAMP UPPER LH	SERVICEABLE	443.30	-
1	COVER ,DECK TRIM ,REAR	SERVICEABLE	126.70	-
1	COVER ,FLOOR UNDER ,NO 1	SERVICEABLE	175.10	-
1	COVER ,FLOOR UNDER ,NO 2	SERVICEABLE	241.90	-
1	COVER ,REAR FLOOR	DISTORTED	229.90	229.90
1	PANEL SUB-ASSY ,QUARTER ,RH	TO REPAIR SEE LABOUR	871.50	-
1	REAR FENDER LINER	SERVICEABLE	139.80	-
1	DUCT ASSY ,QUARTER VENT ,RH	SERVICEABLE	67.00	-
1	SEAL ,REAR BUMPER SIDE ,RH	SERVICEABLE	88.50	-
1	PAN, REAR FLOOR	TO REPAIR SEE LABOUR	583.40	-
1	PIPE ,ASSY,EXHAUST ,TAIL	BENT	1,655.40	1,163.40
1	BRACKET ,EXHAUST PIPE SUPPORT ,NO 5	SERVICEABLE	41.80	-

Report Ref No. CC3/FCI20005250/Kga3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUPPORT ,EXHAUST PIPE ,NO 4	SERVICEABLE	49.10	-
1	SUPPORT ,EXHAUST PIPE ,NO 5	SERVICEABLE	49.10	-
1	GASKET ,EXHAUST PIPE	SERVICEABLE	53.50	-
1	PIPE ASSY ,EXHAUST FRONT	TO REPAIR SEE LABOUR	2,927.20	-
1	INSULATOR ,MAIN MUFFLER HEAT ,RH	SERVICEABLE	141.00	-
1	WIRE ,BACK DOOR ,NO .2	SERVICEABLE	294.40	-
1	WIRE ,LUGGAGE ROOM ,NO 3	SERVICEABLE	170.70	-
1	ARM ASSY ,TRAILING ,REAR RH	SERVICEABLE	370.40	-
1	ARM ASSY ,REAR SUSPENSION ,NO.1 RH	SERVICEABLE	239.20	-
1	ARM ASSY ,REAR SUSPENSION ,NO.2 RH	SERVICEABLE	497.50	-
1	ARM ASSY ,UPPER CONTROL ,REAR RH	SERVICEABLE	420.80	-
1	CARRIER SUB-ASSY ,REAR ,AXLE ,RH	SERVICEABLE	953.60	-
1	ABSORBER ASSY ,CHECK ,REAR RH	SERVICEABLE	127.00	-
1	HUB & BEARING ASSY ,REAR AXLE ,RH	SERVICEABLE	725.60	-
1	SUPPORT ASSY ,REAR SUSPENSION ,RH	SERVICEABLE	149.30	-
1	MEMBER SUB ASSY ,REAR SUSPENSION	SERVICEABLE	2,245.20	-
	LESS 25% DISCOUNT		-5,254.33	-875.92
			15,762.97	2,627.78
	<b>NETT ITEMS</b>			
1	REAR TAILGATE TOYOTA LOGO (N)	NECESSARY	47.00	47.00
1	REAR TAILGATE WORDING 'PRIUS' (N)	NECESSARY	52.90	52.90
1	REAR TAILGATE WORDING 'HYBRID' (N)	NECESSARY	53.50	53.50
	LESS 25% DISCOUNT		-	-38.35
			153.40	115.05
	<b>SPECIAL NETT ITEMS</b>			
1	SET PARKING AID (SN)	SHORTED	700.00	220.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	68.00	68.00
1	REAR TAILGATE STICKER 'TRANS-CAB' (SN)	NECESSARY	80.00	30.00
1	REAR TAILGATE STICKER '6555-3333' (SN)	NECESSARY	80.00	30.00
1	REAR BUMPER PROTECTOR (SN)	NECESSARY	120.00	30.00
1	WHEEL RIM (SN)	SERVICEABLE	1,879.40	-
1	TYRE 195/65/15 (SN)	SERVICEABLE	350.00	-

Report Ref No. CC3/FCI20005250/Kga3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WHEEL RIM COVER (SN)	SERVICEABLE	211.50	-
1	REAR RH BUMPER RETAINER CLIP (SN)	NOT NECESSARY	38.00	-
1	REAR LH BUMPER RETAINER CLIP (SN)	NOT NECESSARY	38.00	-
1	SET TAILLAMP LOWER CLIP (SN)	NOT NECESSARY	35.00	-
1	SET TAILLAMP UPPER CLIP (SN)	NOT NECESSARY	35.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	120.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	180.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	120.00	-
1	SET REAR FENDER LINER CLIP (SN)	NOT NECESSARY	35.00	-
2	REAR END PANEL SEAM SEALANT (SN)	NOT NECESSARY	170.00	-
1	SET EXHAUST BOLT ,SPRING AND NUTS (SN)	NOT NECESSARY	35.00	-
			4,294.90	378.00
	<b><u>LABOUR</u></b>			
	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR .	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT .	NOT NECESSARY	220.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO DISMANTLE AND REFIT REAR AXLE ASSY ,REMOVE AND RENEWAL OF PARTS ,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-
	TO CHECK ABS AND BRAKE EFFICIENCY ,FINAL CHECKING AND TESTING.	NOT NECESSARY	380.00	-

Report Ref No. CC3/FCI20005250/Kga3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		7,500.00	600.00
	TO REINSTALL REAR BUMPER PARKING SENSOR .		170.00	50.00
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING .	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING .	NOT NECESSARY	380.00	-
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR TAILGATE,PANEL SUB - ASSY,QUARTER,RH,PAN,REAR FLOOR AND PIPE ASSY ,EXHAUST ,FRONT.		7,500.00	400.00
	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR .	NOT NECESSARY	170.00	-
	TOWING FEES.	NOT NECESSARY	150.00	-
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.}		170.00	60.00
	TO REPAIR AND REALIGN REAR EXHAUST PIPE .}		170.00	-
	TO PULL AND JACK OUT VEHICLE BODY PANEL AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	380.00	-
	TO PERFORM A COMPREHENSIVE VEHICLE DIAGNOSTIC TEST AND RESET VEHICLE WARNING INDICATORS.	NOT NECESSARY	380.00	-
			20,660.00	1,130.00
<b>GRAND TOTAL</b>			<b>40,871.27</b>	<b>4,250.83</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>4,250.83</b>
------------------------------------	--	--	-----------------

Report Ref No. CC3/FCI20005250/Kga3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 5158E

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 5158E

RE-INSPECTION

