

...CLAIM SUBFOLDER...(Pending for Survey Report)

Non-Reporting WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Apr 2020 Edit Reg		16 Apr 2020 00:00 Edit Adj Rpt	S\$4,697.76 Edit Estimates	S\$4,697.76 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: PAN PACIFIC VAN & TRUCK LEASING PTE LTD, Co. Reg. No.: 201511635R									
Main Claimant: SOON CHIN AIK									
Vehicle Reg. No.: SLU3131H		Date of Loss: 11/04/2020 00:00 - :59 [35 Months and 9 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MFL2020D0000823		Policy/Cover Note No.: D19MFL0005549							
Vehicle Reg. No. (Insured): GBJ5890M		Policy No. (Claimant): SD18V03868/VPC2/R0							
Excess:									
Repairer: ComfortDelGro Engineering Pte Ltd (Ubi) 320 UBI ROAD 3, 408649 Ubi - Tel:									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Lalitha Krishnan - 6347 6139]									
Claimant's Insurer: Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 27/04/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
III_SG (04/06/2020): Alert - Adj Mandate Approved (S\$0.00) - SLU3131H - Claim Handler: Lalitha Krishn...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLU3131H (MFL2020D0000823)**
[GBJ5890M]
TP
SOON CHIN AIK
Apr 11 2020 12:00AM
[PAN PACIFIC VAN & TRUCK LEASING PTE LTD]
ComfortDelGro Engineering Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ☐

Video					1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print	
1	28/04/20 09:40	Video - Accident TP		Load MP4		
Photos/Images					3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print	
1	20/04/20 19:48	General View		Load JPG	☒	
2	20/04/20 19:48	General View		Load JPG	☒	
3	20/04/20 19:48	General View		Load JPG	☒	
4	20/04/20 19:48	General View		Load JPG	☒	
5	20/04/20 19:48	Odometer Reading		Load JPG	☒	
6	20/04/20 19:48	Chassis Number		Load JPG	☒	
7	20/04/20 19:48	General View		Load JPG	☒	
8	20/04/20 19:48	General View		Load JPG	☒	
9	20/04/20 19:48	General View		Load JPG	☒	
10	20/04/20 19:48	General View		Load JPG	☒	
11	20/04/20 19:48	General View		Load JPG	☒	
12	20/04/20 19:48	General View		Load JPG	☒	
13	20/04/20 19:48	General View		Load JPG	☒	
14	20/04/20 19:48	General View		Load JPG	☒	
15	20/04/20 19:48	General View		Load JPG	☒	
16	20/04/20 19:48	General View		Load JPG	☒	
17	20/04/20 19:48	General View		Load JPG	☒	
18	20/04/20 19:48	General View		Load JPG	☒	
19	20/04/20 19:48	General View		Load JPG	☒	
20	20/04/20 19:48	General View		Load JPG	☒	
21	20/04/20 19:48	General View		Load JPG	☒	
22	20/04/20 19:48	General View		Load JPG	☒	
23	20/04/20 19:48	General View		Load JPG	☒	
24	20/04/20 19:48	General View		Load JPG	☒	
25	20/04/20 19:48	General View		Load JPG	☒	
26	20/04/20 19:48	General View		Load JPG	☒	
27	20/04/20 19:48	General View		Load JPG	☒	
28	20/04/20 19:48	General View		Load JPG	☒	
29	20/04/20 19:48	General View		Load JPG	☒	
30	20/04/20 19:48	General View		Load JPG	☒	
31	20/04/20 19:48	General View		Load JPG	☒	
32	20/04/20 19:48	General View		Load JPG	☒	
33	20/04/20 19:48	General View		Load JPG	☒	
34	20/04/20 19:48	General View		Load JPG	☒	
35	20/04/20 19:48	General View		Load JPG	☒	
36	20/04/20 19:48	General View		Load JPG	☒	

Video				1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
37	20/04/20 19:48	General View		Load JPG	☒
38	20/04/20 19:48	General View		Load JPG	☒
39	20/04/20 19:48	General View		Load JPG	☒
40	20/04/20 19:48	General View		Load JPG	☒
41	20/04/20 19:48	General View		Load JPG	☒
42	20/04/20 19:48	General View		Load JPG	☒
43	20/04/20 19:48	General View		Load JPG	☒
44	20/04/20 19:48	General View		Load JPG	☒
45	20/04/20 19:48	General View		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	16/04/20 17:36	EMAIL FROM III DD 16-04-2020		Load PDF	
2	20/04/20 13:49	TP GIA REPORT		Load PDF	
3	22/04/20 12:13	TP POLICE REPORT		Load PDF	
4	22/04/20 12:23	TP ESTIMATE - MARKED		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20005253/EBA3S2**Date:** 30/06/2020REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MFL0005549
Claimant Vehicle No :	SLU3131H	Insured Vehicle No :	GBJ5890M
Date of Loss:	11/04/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0000823

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU3131H	Engine No:	R16B21601768
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Chassis No:	MRHFC5650GT001458
Reg. Date:	02/05/2017 (Man. Year: 2017)	Odometer:	31382 km
Colour:	Silver		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,900.96	2,457.76	4,443.20	64.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,650.00	2,240.00	2,410.00	51.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,550.96	4,697.76	6,853.20	59.33
+ GST 7.00/7.00% (S\$)	808.57	328.84	479.73	59.33
Nett Amount (S\$)	12,359.53	5,026.60	7,332.93	59.33

INSPECTION

Date of Assignment:	16/04/2020		
Date Inspected:	20/04/2020	Inspected At:	ComfortDelGro Engineering Pte Ltd (Ubi) 320 UBI ROAD 3 Singapore 408649
Estimated Period of Repair:	9.0 days		

Adjuster: CHEN TSUE YEE**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/30/2020

Adjuster Report

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$1,721.36 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Jun 2020)
Parts:	143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU3131H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LHR DOOR	Repair	1,110.84 FL	*- FL
2	1		*LHR DOOR RUBBER	Not Necessary	115.68 FL	*- FL
3	1		*LHR DOOR HANDLE	Not Necessary	130.32 FL	*- FL
4	1		*LHR DOOR HANDLE KNOB	Not Necessary	52.44 FL	*- FL
5	1		*LHR DOOR LOCK	Not Necessary	95.76 FL	*- FL
6	1		*LHR DOOR HINGE TOP	Not Necessary	45.48 FL	*- FL
7	1		*LHR DOOR HINGE BOTTOM	Not Necessary	45.48 FL	*- FL
8	1		*LHR DOOR CHECKER	Not Necessary	54.00 FL	*- FL
9	1		*LHR FENDER	Dented	853.92 FL	*853.92 FL
10	1		*LHR FENDER QUARTER GLASS WITH CHROME	Necessary	163.92 FL	*163.92 FL
11	1		*LHR FENDER COWLING	Crushed	75.60 FL	*75.60 FL
12	8		*LHR FENDER COWLING CLIPS	Necessary	33.60 FL	*20.00 FL
13	1		*LHR PETROL COVER (OUTER)	Not Necessary	128.04 FL	*- FL
14	1		*LHR PETROL COVER RUBBER (INNER)	Not Necessary	73.56 FL	*- FL
15	1		*LHR PETROL TANK ASSY WITH RUBBER TUBE	Not Necessary	798.48 FL	*- FL
16	1		*LHR TAIL LAMP	Broken	337.20 FL	*337.20 FL
17	1		*REAR BOOT	Repair	638.16 FL	*- FL
18	1		*REAR BOOT HINGE LH	Not Necessary	53.76 FL	*- FL
19	1		*REAR BOOT HINGE COVER LH	Not Necessary	18.48 FL	*- FL
20	1		*REAR BOOT RUBBER	Not Necessary	84.00 FL	*- FL
21	1		*REAR BOOT LAMP LH	Broken	146.76 FL	*146.76 FL
22	1		*REAR BOOT CENTRE GARNISH	Not Necessary	133.08 FL	*- FL
23	1		*REAR BOOT EMBLEM	Not Necessary	14.28 FL	*- FL
24	1		*CIVIC WORDING	Not Necessary	13.80 FL	*- FL
25	1		*1-VTEC WORDING	Not Necessary	12.60 FL	*- FL
26	1		*REAR BUMPER	Broken	556.44 FL	*556.44 FL
27	15		*REAR BUMPER CLIPS	Necessary	63.00 FL	*30.00 FL
28	1		*REAR BUMPER SIDE RETAINER LH	Broken	13.80 FL	*13.80 FL
29	1		*REAR BUMPER BRACKET (UNDER TAIL LAMP)	*Check	10.20 FL	*- FL
30	1		*REAR BUMPER REFLEXOR LAMP CVR LH	Cut	21.36 FL	*21.36 FL
31	1		*REAR BUMPER REFLEXOR LAMP LH	Cut	18.84 FL	*18.84 FL
32	1		*REAR BUMPER REINFORCEMENT	*Check	192.00 FL	*- FL
33	1		*REAR BUMPER SPONGE	*Check	80.00 FL	*- FL
34	1		*REAR END PANEL	*Check	318.00 FL	*- FL
35	1		*REAR PARKING SENSOR OUTER LH (ORG)	Shorted	174.96 FL	*174.96 FL
36	1		*REAR PARKING SENSOR INNER LH (ORG)	Not Necessary	174.96 FL	*- FL
37	1		*REAR WINDSCREEN RUBBER	*Check	1,114.00 FL	*- FL
38	1		*SPORT RIM (ORG) (RH / LH)	Cut	584.40 FL	*584.40 FL
39	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
40	1		*SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,611.20	3,057.20
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,710.24	599.44
Total Parts (\$\$)	6,900.96	2,457.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE / REINSTALL LHR UNDER CARRIAGE. *Check	New	350.00	0.00
2	TO CHECK & DISCONNECT ELECTRICAL WIRING, WIRE SOCKET ETC.	New	100.00	30.00
3	COMPUTERISE WHEEL ALIGNMENT.	New	100.00	60.00
4	TO REMOVE & REINSTALL REAR WINDSCREEN.	New	160.00	120.00
5	TO REMOVE & REPLACE / REINSTALL REAR PARKING SENSOR.	New	140.00	30.00
6	TO REMOVE & REPLACE / REINSTALL LHR DOOR & MECHANISM.	New	250.00	0.00
7	TO CUT & WELD LHR FENDER, REAR END PANEL / KNOCK & REPAIR LHR FENDER INNER PANEL, SPARE TYRE PANEL, LH SIDE SKIRTING AND ALL AFFECTED AREA.	New	1,850.00	1,000.00
8	TO PUTTY & SPRAY PAINT, LHR FENDER, LHR FENDER INNER PANEL LHR DOOR, REAR BOOT, REAR BUMPER, SPARE TYRE PANEL, END PANEL, LH SIDE SKIRTING & ALL AFFECTED AREA.	New	1,700.00	1,000.00
Gross Labour Cost (\$\$)			4,650.00	2,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >