



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XD 5366G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	CORNER STEP GARNISH	SCRATCHED	255.00	255.00
1	CORNER FAIRING - LH	SCRATCHED	580.00	580.00
1	CORNER INNER SHIELD - LH	SCRATCHED	360.00	360.00
1	REAR SIDE FENDER - LH	SERVICEABLE	850.00	-
1	DIESEL TANK	BENT	2,200.00	2,200.00
1	EXHAUST CATALYTIC CONVERTOR	BENT	2,800.00	2,800.00
1	EXHAUST CATALYTIC CONVERTOR COVER	BENT	1,500.00	1,500.00
1	RADIATOR SPRAY TANK	SERVICEABLE	240.00	-
1	FRONT TYRE - LH	SERVICEABLE	800.00	-
1	ADBLUE TANK (ADDITIONAL)	BENT	4,500.00	4,500.00
	LESS 25% DISCOUNT		-	-3,048.75
			14,085.00	9,146.25
<b><u>LABOUR</u></b>				
	TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.		1,200.00	600.00
	TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.		1,000.00	200.00
	TO REPLACE TYRE.	NOT NECESSARY	380.00	-
	TO CHECK WIRING FUNCTIONS.		200.00	50.00
	TO REMOVE & REPLACE FUEL TANK.	NOT NECESSARY	250.00	-
	TO REMOVE & REPLACE ADBLUE TANK, EXHAUST CATALYTIC CONVETOR.		1,200.00	200.00
			4,230.00	1,050.00
<b>GRAND TOTAL</b>			<b>18,315.00</b>	<b>10,196.25</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>8,150.00</b>

Report Ref No. CS/QBE20005255/R1qf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.