

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883 ON BEHALF OF TONG SHI YUN FELICIA INV No. AC2003600

INV Date 04/05/2020

Reference CS/TP20005256/Usf3n2

Code TP149

PROFESSIONAL SERVICE FEE

Vehicle No. SKR 6845P

Insured Veh.

Claim No.

Policy No.

Accident Date 13/04/2020

Inspection Date 17/04/2020

Description	Total
Survey Inspection	450.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Affiliated to Federation Internationale Des Experts En Automobile							
BLUWEL AUTOMOTIV	/E SERVICE PTE LTD	Ref : CS/TP20005256/Usf3n2					
BLK 1 KAKI BUKIT AV #01-28/51/53/55(MAIN 417883	'E 6 I OFFICE)SINGAPORE	Date: 04-05-2020					
ON BEHALF OF TON	G SHI YUN FELICIA	Code: TP149					
1.	1. Policy Particulars :- THIRD PARTY CLAIM						
Insured Veh.		Veh. Inspected	SKR 6845P				
Policy No.		Coverage (\$)	0.00				
Claim No.		Excess (\$)	0.00				
Assign From		Assign Date	17/04/2020				
2.	Vehicle Partic	culars & Condition					
Make & Model	VOLKSWAGEN GOLF (A)	c.c	1395				
Engine No.	HIDDEN	Year of Reg.	2015				
Chassis No.	WVWZZZAUZFW174417	Colour	BLUE				
Odometer	144607	Steering	IN ORDER				
Brakes	IN ORDER	Modification	SPORTS RIM				
General	GOOD						
3.	Conditi	ons of Tyres					
	Size	Make	Balance				
R/H Front Tyre	225/45 ZR17	CST	6 mm				
L/H Front Tyre	225/45 ZR17	CST	6 mm				
R/H Rear Tyre	225/45 ZR17	CST	6 mm				
L/H Rear Tyre	225/45 ZR17	CST	6 mm				
4.	•	on of Damages					
THE VEHICLE SU	STAINED DAMAGES AT THE FR	ONT O/S PORTION.					
DAMAGES SEE D	ETAILS.						
5.	Genera	I Information					
Accident Date	13/04/2020	Inspection Date	17/04/2020				
Survey held at	BLUWEL AUTOMOTIVE SERVI	CE PTE LTD					
	BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883						
5a.	Re	emarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b. Estimate Days of Repair							
ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days						



LKK Auto Consultants Pte L
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 6845P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	DENTED / BUCKLED	1,380.97	1,380.97
2	BONNET HINGES @\$64.89	SERVICEABLE	129.78	-
1	BONNET RUBBER	NECESSARY	63.79	63.79
1	BONNET INSULATOR	NOT NECESSARY	205.30	-
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,076.45	-
1	HEADLAMP O/S	BROKEN	2,009.71	2,009.71
1	HEADLAMP TOP PANEL O/S	BENT	199.00	199.00
1	FRONT FENDER O/S	BUCKLED	594.12	594.12
1	FRONT FENDER INNER SHIELD O/S	DEFORMED	188.20	188.20
1	SET FRONT FENDER INNER SHIELD CLIPS O/S	NECESSARY	50.00	50.00
1	FRONT FENDER INNER PANEL O/S	BENT	699.10	699.10
1	FRONT DOOR O/S	TO REPAIR SEE LABOUR	1,002.65	-
1	FRONT RETAINER O/S	CRACKED	65.12	65.12
	LESS 10% DISCOUNT		-	-525.00
			7,664.19	4,725.01
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.		80.00	80.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	120.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT DOOR O/S.		800.00	700.00
	TO PUTTY & SPRAY PAINTING.		1,200.00	1,000.00
	-		-	-
	-		-	_
	-		-	-
			2,250.00	1,800.00
	GRAND TOTAL		9,914.19	6,525.01

Report Ref No. CS/TP20005256/Usf3n2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		5,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/TP20005256/Usf3n2

CHUA KANG SENG Licensed Appraiser




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION

PHOTOGRAPHS FOR VEHICLE NO. SKR 6845P













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933












51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933










51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933












51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933










51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933












51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933










51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


Reg. No: 199607198R GST Reg. No. 19-9607198-R


RE-INSPECTION













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933












51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933












51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933












51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No. 199607198R GST Reg. No. 19-9607198-R

RE-INSPECTION



PHOTOGRAPHS FOR VEHICLE NO. SKR 6845P





