



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

BLUWEL AUTOMOTIVE SERVICE PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-28/51/53/55(MAIN OFFICE)
SINGAPORE 417883
ON BEHALF OF TANG LING LING

INV No. AC2003609
INV Date 04/05/2020
Reference CS/TP20005257/Uqf3n2
Code TP149



PROFESSIONAL SERVICE FEE

Vehicle No. SGT 4822E

Insured Veh.

Claim No.

Policy No.

Accident Date 10/04/2020

Inspection Date 17/04/2020

Description	Total
Survey Inspection	652.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	652.00
GST (7%)	45.64
Grand Total	697.64

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP20005257/Uqf3n2

BLK 1 KAKI BUKIT AVE 6
#01-28/51/53/55(MAIN OFFICE)SINGAPORE
417883

Date : 04-05-2020



ON BEHALF OF TANG LING LING

Code : TP149

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SGT 4822E
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	17/04/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ GLA180 (A)	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WDC1569422J146804	Colour	BLACK
Odometer	44098	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R18	YOKOHAMA	6 mm
L/H Front Tyre	235/50 R18	YOKOHAMA	6 mm
R/H Rear Tyre	235/50 R18	YOKOHAMA	6 mm
L/H Rear Tyre	235/50 R18	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/04/2020	Inspection Date	17/04/2020
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 4822E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET	TO REPAIR SEE LABOUR	1,533.00	-
1	FRONT BUMPER	DISTORTED	1,375.00	1,375.00
1	FRONT BUMPER BLACK GARNISH	GRAZED	185.00	185.00
1	FRONT BUMPER CENTRE SKIRTING	WARPED / CRACKED	620.00	620.00
1	FRONT BUMPER PDC SENSOR O/S	SHORTED	188.00	188.00
1	FRONT BUMPER PDC SENSOR RADAR	SHORTED	685.00	685.00
1	FRONT BUMPER PDC SENSOR WIRE	SERVICEABLE	311.00	-
1	FRONT BUMPER SPONGE	TORN	138.00	138.00
1	FRONT BUMPER REINFORCEMENT	BENT	715.00	715.00
2	FRONT BUMPER SIDE HOLDERS @\$85.00	NOT NECESSARY	170.00	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER LICENCE PLATE GARNISH	TORN	122.00	122.00
1	FRONT BUMPER UNDER COVER	CRACKED	648.00	648.00
1	FRONT BUMPER LOGO	CRACKED	65.00	65.00
1	FRONT GRILLE	CUT	315.00	315.00
1	FRONT GRILLE LOGO	SCRATCHED	88.00	88.00
1	FRONT GRILLE CHROME MOULDING	SCRATCHED	69.00	69.00
2	HEADLAMPS @\$2860.00	CRACKED	5,720.00	5,720.00
1	FRONT SUPPORT PANEL	CRACKED	675.00	675.00
1	AIR CON CONDENSER	NOT NECESSARY	1,110.00	-
1	RADIATOR	NOT NECESSARY	1,485.00	-
1	FRONT FENDER O/S	TO REPAIR SEE LABOUR	619.00	-
1	FRONT GRILLE INNER	CRACKED	312.00	312.00
	LESS 10% DISCOUNT		-	-1,197.00
			17,198.00	10,773.00
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	80.00	-

Report Ref No. CS/TP20005257/Uqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REFILL AIR CON GAS.		120.00	100.00
	TO DISMANTLE & REPLACING PDC SENSOR.		100.00	80.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF BONNET AND FRONT FENDER O/S.		1,080.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,000.00
			2,930.00	2,000.00
	GRAND TOTAL		20,128.00	12,773.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			10,200.00

Report Ref No. CS/TP20005257/Uqf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.