

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20005259/KEA3Q2

**Date:** 15/10/2020

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800156164
<b>Claimant</b>		
<b>Vehicle No :</b> SLT8224X	<b>Insured Vehicle No :</b>	SMH199P
Date of Loss: 13/04/2020	Nature of Claim: TP	Claim No: 1628708890SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLT8224X</b>	Engine No:	2ZRS107778
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU103575124
Reg. Date:	14/11/2017 (Man. Year: 2017)	Odometer:	181475 km
Colour:	Metallic Silver		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,192.10	1,042.02	150.08	12.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	334.10	294.10	40.00	11.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>1,526.20</b>	<b>1,336.12</b>	<b>190.08</b>	<b>12.45</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>106.83</b>	<b>93.53</b>	<b>13.30</b>	<b>12.45</b>
<b>Nett Amount (S\$)</b>	<b>1,633.03</b>	<b>1,429.65</b>	<b>203.38</b>	<b>12.45</b>
<b>+ Car Rental (3.0 x S\$71.95/day) (S\$)</b>		215.85		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>1,652.95</b>		

#### INSPECTION

Date of Assignment:	17/04/2020	
Date Inspected:	22/04/2020	Inspected At: Esteem Performance Pte Ltd - Sin Ming (HQ) 385 Sin Ming Drive Singapore 575718
Estimated Period of Repair:	2.0 days	

**Adjuster:** KENNETH KONG

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FOG LAMP LH	Mtg Cracked	910.70 FL	*910.70 FL
2	1		*FRONT BUMPER	Dented / Cracked	450.80 FL	*450.80 FL
3	1		*FRONT MANUFACT BADGE	Necessary	87.10 FL	*87.10 FL
4	1		*FRT BMP CLIP	Necessary	40.00 FL	*40.00 FL
5	1		*L/F BUMPER BRACKET	Serviceable	107.20 FL	* - FL
6	1		*R/F BUMPER BRACKET	Serviceable	107.20 FL	* - FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>1,703.00</b>	<b>1,488.60</b>
<b>- List Item Discount on L Items 30.00/30.00% (\$)</b>	510.90	446.58
<b>Total Parts (\$)</b>	<b>1,192.10</b>	<b>1,042.02</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING TO CHECK WIRING	New	50.00	20.00
2	17.0 WU X 50.00 SGD/H	New	85.00	75.00
3	LABOUR COST 23.0 WU X 50.00 SGD/H	New	115.00	115.00
4	MATERIAL COST	New	84.10	84.10
			<b>Gross Labour Cost (\$\$)</b>	<b>294.10</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >