

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC4/AIG20005261/QPA3Q2  
**Date:** 29/07/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800076085	
<b>Claimant Vehicle No :</b>	SLR4250G	<b>Insured Vehicle No :</b>	SFK9218B	
Date of Loss:	03/04/2020	Nature of Claim:	TP	Claim No: 4192593511SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLR4250G</b>		
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Engine No:	LEB4264181
Reg. Date:	15/08/2017 (Man. Year: 2016)	Chassis No:	GP71044206
Colour:	White	Odometer:	173104 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,000.00	0.00	3,000.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,770.00	950.00	820.00	46.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,770.00</b>	<b>950.00</b>	<b>3,820.00</b>	<b>80.08</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>333.90</b>	<b>66.50</b>	<b>267.40</b>	<b>80.08</b>

<b>Nett Amount (S\$)</b>	<b>5,103.90</b>	<b>1,016.50</b>	<b>4,087.40</b>	<b>80.08</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

INSPECTION

Date of Assignment: 17/04/2020

Date Inspected: 17/04/2020

Estimated Period of Repair: 2.0 days

Inspected At:

Lion City Rentals Pte Ltd (HQ)  
60 Jalan Lam Huat, #04-35/36 Carros Centre  
Singapore 737569

---

**Adjuster:** OI SUN PIN

---

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*R/L FENDER	Repair	2,000.00 FL	*- FL
2	1		*REAR BUMPER	Repair	1,500.00 FL	*- FL
3	1		*SET BUMPER CLIPS	Serviceable	200.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					3,700.00	0.00
- List Item Discount on L Items 20.00/20.00% (S\$)					700.00	0.00
Total Parts (S\$)					3,000.00	0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING R/L DOOR ,R/L FENDER AND REAR BUMPER TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	750.00	350.00
2	TO RESPRAY REAR BUMPER ,R/L FENDER AND R/L DOOR	New	900.00	600.00
3	TRANSFER DOOR MECHANISM TO FACILITATE REPAIRS AND REPLACEMENT OF PARTS	New	120.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,770.00</b>	<b>950.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >