



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SINGAPORE CIVIL DEFENCE FORCE

Ref : CS/SCD20005264/Qsf3e2

91 UBI AVE 4SINGAPORE 408827

Date : 06-05-2020



ATTN : SHAUN LIM CHI TUCK

Code : SCD

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	YN 3693K
Policy No.		Coverage (\$)	0.00
Claim No.	ACC-SMRT-20-02	Excess (\$)	0.00
Assign From	SHAUN LIM CHI TUCK	Assign Date	16/04/2020

2. Vehicle Particulars & Condition

Make & Model	ISUZU	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	NJR857030002	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/75 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/75 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/75 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/75 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/02/2020	Inspection Date	17/04/2020
Survey held at	K & S BODYWERK -NO2 2B SUNGEI KADUT DRIVE		

5a. Remarks

--

Registration No. YN 3693K

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Windscreen	1				
1.2	Windscreen Moulding	1				
1.3	Windscreen Sealant	1				
1.4	Windscreen Primer	1				
1.5	Front Panel	1				
1.6	Radiator Grille	1				
1.7	Front Bumper	1				
1.8	Front Bumper Support	1				
1.9	Front Number Plate	1				
1.10	Front Panel Sticker	1				
	LABOUR DESCRIPTION					
1	SCOPE OF REPAIRS					
1.1	Remove & replace shuttered wind screen					4
1.2	Replace wind screen moulding					1
1.3	Water seepage for wind screen					1
1.4	Remove & replace front dented panel					4
1.5	Remove & replace dislodged radiator grill					1
1.6	Remove & replace front dented bumper					2
1.7	Remove & replace front dented bumper support					2
1.8	Remove & replace front dented number plate					0.5
1.9	Replace front panel sticker					1
1.10	Putty & spray paint front panel , radiator grill & front bumper					5

3	COLLECTION & DELIVERY					
3.1	Collection From Station - Workshop (SOR 10)	1				
3.2	Delivery From Workshop - Station (SOR 9)	1				
4	ADDITIONAL SERVICES					
4.1	Admin Support					0
		TOTAL PARTS COST			\$0.00	
		TOTAL MAN-HOUR				21.5

Vehicle Inspected By



OI SUN PIN

Asst. Automotive Assessor



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. YN 3693K

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

