

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 27 Apr 2020

## **Preliminary Advice**

Insured Vehicle No : SMQ502A

TP Vehicle No : FBM303J

Make : HONDA CBF 190

Date of Inspection : 17/04/2020

Inspection At : Sg 98 Motor Pte Ltd (HQ)

BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21

Singapore 569622

Accident Date : 07/04/2020

Assignment Date : 17/04/2020

Est. Duration of Repair : 4 days

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front & n/s portion and parts claimed are consistent to the accident.

|                             |      |          |
|-----------------------------|------|----------|
| Repairer's Estimate (Gross) | :S\$ | 1,150.00 |
| Revised Amount              | :S\$ | 630.00   |
| Check Items (Estimated)     | :S\$ | 0.00     |
| Total                       | :S\$ | 630.00   |

|                 |      |
|-----------------|------|
| Lump Sum Repair | :S\$ |
|-----------------|------|

### **Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

### **Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis. Parts items is pending parts prices.