

PRESTIGE APPRAISER SERVICES

Insurance Loss Adjusters and Licensed Appraiser Regn. 652868584L

Blk 131, Rivervale Street #05-872 S'pore 540131 Tel:65528323 Fax:64574321

Our ref : PS/030/12/19

Date : 13th February 2020

M/s Acepac Rental
c/o 160 Sin Ming Drive
#05-08 Sin Ming Auto City
Singapore 575722

Dear Sir,

Re : THIRD PARTY CLAIM

We refer to your instruction to appraise the vehicle **GBG 5237 R** on 27th December 2019.

A static inspection was conducted during our survey and our report is enclosed for your perusal. The estimated repair cost submitted by **Messrs. Kum Chew Motor Workshop** for **\$23,144.80** as per our attached schedule have been inspected thoroughly each and every item and revised by us against the actual damages found on the vehicle which have been recommended by us accordingly.

The repairer has agreed to undertake repairs at our revised amount of **\$15,100.00 lump sum** corresponding to supply of parts, labour charges and spray-painting. However, we have not given instruction to authorize the repairs.

Under normal circumstances, the estimated period of repairs would be **TWELVE (12) days**. Photographs of the damaged vehicle taken by us during our inspection are enclosed.


We are reverting the matter to you for a decision.

Please do not hesitate to contact us if you need any clarification.

Assuring you of our best services.

Yours faithfully,

PRESTIGE APPRAISER SERVICES


LOUIS S C NG CAE AMIMI
Dip. MTM. Automotive Engineer
Licensed Appraiser

Encl.

PRESTIGE APPRAISER SERVICES

VEHICLE INSPECTION REPORT

To: M/s Acepac Rental
c/o 160 Sin Ming Drive
#05-08 Sin Ming Auto City
Singapore 575722

Date : 13th February 2020
Our Ref : PS/030/12/19
Policy No :
Sum Insured :
Excess : T/P Claim

Assigned By : M/s Acepac Rental
Assignment Date : 27th December 2019
Accident Date : 21st December 2019
Inspection Date : 27th December 2019
Workshop Name : Kum Chew Motor Workshop
Survey Conducted At : 160 Sin Ming Drive
#05-08 Sin Ming Auto City
Singapore 575722

PARTICULARS OF VEHICLE

Registration No	: GBG 5237 R	Mileage	: 85701km
Make/Model	: Nissan NV350	Engine No	: HIDDEN
Type Of Body	: Panel Van	Chassis No	: JN1MC2E26Z0008536
Year Of Manu./Regn.	: 2017	Max. Laden Wt.	: 3300kg
Colour	: Red	Others	: -

CONDITION OF TYRES

	R/H SIDE	L/H SIDE
Front Tyre	: 5mm 195R15 LUXOTIK	5mm 195R15 LUXOTIK
Rear Tyre	: 5mm 195R15 LUXOTIK	5mm 195R15 LUXOTIK

The above represent the estimated remaining life of the tyre treads.

PRE-ACCIDENT CONDITION (Static tests only)

Handbrake	: Serviceable	Body Work	: Good
Footbrake	: Serviceable	Paint Work	: Good
Steering	: Serviceable	Others	: -

POINT OF IMPACT

The vehicle sustained an impact on the front R/H portion.

GENERAL DESCRIPTION OF DAMAGES

The front panel, bumper assy, corner panels, front panel, floorboard panel, R/H door were dented/distorted.

For details of damages please refer to schedule attached.

REMARKS :

This survey was conducted strictly without prejudice.

PRESTIGE APPRAISER SERVICES

Vehicle No : **GBG 5237 R**

Our Ref :

PS/030/12/19

Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
	<u>LIST ITEMS</u>			
1	front bumper	dented	\$ 571.50	\$ 571.50
1	front bumper reinforcement	dented	705.00	705.00
2	front bumper side bracket	dented	117.20	117.20
8	front bumper clip	necessary	20.80	20.80
1	R/H fog lamp garnish	dented	986.20	986.20
1	front grille	broken/missing	521.50	521.50
6	front grille clip	necessary	30.00	30.00
1	front grille emblem	necessary	79.10	79.10
1	R/H headlamp	broken	611.30	611.30
1	L/H headlamp panel	dented	352.50	352.50
1	R/H headlamp	cracked	611.30	611.30
1	L/H headlamp panel	dented - repair	352.50	-
1	front panel	dented	1,221.30	1,221.30
1	R/H corner panel	dented/distorted	534.60	534.60
1	R/H door	dented - repair	1,071.40	-
1	dashboard	holder cracked	1,235.30	1,235.30
1	front floor panel	dented	1,855.30	1,855.30
			10,876.80	9,452.90
		Less 30%	-	945.29
		Sub Total A	\$ 10,876.80	\$ 8,507.61
	<u>NETT ITEMS</u>			
1	L/H fog lamp	serviceable	210.20	-
1	R/H fog lamp	holder cracked	210.20	210.20
1	inter cooler	dented	2,121.60	2,121.60
1	aircon cooling coil	dented/cracked	2,290.60	2,290.60
1	aircon evaporate unit	dented/cracked	925.00	925.00
1	aircon pipe	dented	249.20	249.20
1	air duct	dented	192.60	192.60
1	radiator assy	holder cracked	816.10	816.10
1	front windscreen moulding	necessary	82.50	82.50
			7,098.00	6,887.80
		Less 10%	-	688.78
		Sub Total B	\$ 7,098.00	\$ 6,199.02
		Sub Total A+ B	\$ 17,974.80	\$ 14,706.63
	<u>S/NETT ITEMS</u>			
1	front windscreen sealant	necessary	80.00	60.00
1	front panel cover	dented/cracked	600.00	450.00
1	R/H door lettering	necessary	50.00	38.00
	<u>Labour Charges & Misc</u>			
	To dismantle & replace damaged parts, panel beat where necessary.		1,900.00	1,600.00
	To putty, apply primer & spray-paint on the affected portion.		1,300.00	1,100.00
	To apply rust-proofing on repaired, replaced panel.		150.00	120.00
	To remove/refit dashboard to facilitate repairs.		450.00	320.00
		Balance c/f	\$ 22,504.80	\$ 18,394.63

PRESTIGE APPRAISER SERVICES

Vehicle No : **GBG 5237 R**

Our Ref : **PS/030/12/19**

Qty	Descriptions	Conditions	Repairer's Est.	Our Revised.
		Balance b/d	\$ 22,504.80	\$ 18,394.63
	To remove/renew aircon cooling coil & refill gas.		220.00	160.00
	To remove/refit front windscreen glass to facilitate repairs.		180.00	140.00
	To remove/renew radiator assy.		120.00	80.00
	To check wiring functions.		120.00	100.00
			\$ <u>23,144.80</u>	\$ <u>18,874.63</u>

Note: The repairer has agreed to undertake the repairs at our adjusted amount of **\$15,100.00 lump sum** corresponding to supply of parts, labour and spray-painting charges.

Under normal circumstances, the estimated repair period would be **TWELVE (12)** days.
Pursuant to your instruction we have **not** authorised repairs on your behalf.

PRESTIGE APPRAISER SERVICES



LOUIS SCNGCAE AMIMI (UK)

Licensed Appraiser

Dip. MTM. Automotive Engineer



