

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20005274/EEA3Q2**Date:** 11/12/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700088390
Claimant
Vehicle No : GBE4304Y **Insured Vehicle No :** SLU1483E
Date of Loss: 15/04/2020 Nature of Claim: TP Claim No: 8261482026SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBE4304Y**
Make & Model: TOYOTA HIACE, 3.0 D TURBO 5 DR (M) Engine No: 1KD2558056
Reg. Date: 10/12/2015 (Man. Year: 2015) Chassis No: JTFHT02P700178807
Colour: White Odometer: 140064 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,646.30	3,786.42	7,859.88	67.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	1,650.00	1,280.00	43.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,576.30	5,436.42	9,139.88	62.70
Approved Total (Overridden) (S\$)		4,350.00		
(S\$)	14,576.30	4,350.00	10,226.30	70.16
+ GST 7.00/7.00% (S\$)	1,020.34	304.50	715.84	70.16
Nett Amount (S\$)	15,596.64	4,654.50	10,942.14	70.16
+ Loss of Use (8.0 x S\$100.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		5,490.95		
Global Sum Settlement (S\$)		5,490.00		

INSPECTION

Date of Assignment: 17/04/2020
Date Inspected: 20/04/2020 Inspected At: Bifrost Auto Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4, #01-49, Premier @
Kaki Bukit
Singapore 415875
Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	685.60 F	*390.00 FL
2	1		*REAR BUMPER RETAINER RH	Broken	92.60 F	*92.60 FL
3	1		*REAR BUMPER RETAINER LH	Broken	92.60 F	*92.60 FL
4	1		*REAR BUMPER BRACKET (4PCS)	Bent (3Pcs Only)	220.00 F	*165.00 FL
5	1		*REAR CORNER PANEL RH	Broken	158.70 F	*158.70 FL
6	1		*TAIL LAMP RH	Broken	486.70 F	*388.00 FL
7	1		*TAIL GATE	Dented	2,150.70 F	*1,910.00 FL
8	1		*TAIL GATE LOCK	Bent	225.30 F	*225.30 FL
9	1		*TAIL GATE LOCK CATCH	Not Necessary	75.50 F	*- FL
10	1		*TAIL GATE KEY LOCK	Not Necessary	105.20 F	*- FL
11	1		*TAIL GATE LOCK HANDLE	Not Necessary	142.80 F	*- FL
12	1		*TAIL GATE LICENSE LAMP GARNISH	Not Necessary	155.20 F	*- FL
13	2		*TAIL GATE LICENSE LAMP	Not Necessary	79.60 F	*- FL
14	1		*TAIL GATE LOGO EMBLEM	Necessary	79.60 F	*79.60 FL
15	1		*TAIL GATE RUBBER BEADING	Crushed	226.80 F	*226.80 FL
16	1		*TAIL GATE INNER TRIM	Not Necessary	338.40 F	*- FL
17	1		*TAIL GATE DAMPER RH	Not Necessary	152.50 F	*- FL
18	1		*TAIL GATE DAMPER LH	Not Necessary	152.50 F	*- FL
19	1		*TAIL GATE HINGE RH	Not Necessary	135.30 F	*- FL
20	1		*TAIL GATE HINGE LH	Not Necessary	135.30 F	*- FL
21	1		*TAIL GATE WINDSCREEN	Not Necessary	1,120.00 F	*- FL
22	1		*TAIL GATE WINDSCREEN MOULDING	Not Necessary	223.60 F	*- FL
23	1		*END PANEL	Dented	865.50 F	*581.00 FL
24	1		*REAR FLOOR PANEL	Repair	1,752.30 F	*- FL
25	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
26	1		*REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
27	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
28	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
29	1		*SET TAIL GATE INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
30	1		*SET TAIL LAMP CLIP	Not Necessary	30.00 FS	*- FS
31	1		*TAIL GATE STICKER - TOYOTA HIACE	Necessary	100.00 FS	*50.00 FS
32	1		*TAIL GATE STICKER - 70KM/H	Necessary	50.00 FS	*30.00 FS
33	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	50.00 FS	*50.00 FS
34	1		*TAIL GATE WINDSCREEN INNER SEAL	Necessary	30.00 FS	*20.00 FS
35	1		*END PANEL SEALANT	Necessary	50.00 FS	*30.00 FS
36	1		*REAR FLOOR PANEL SEALANT	Not Necessary	50.00 FS	*- FS
37	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
38	1		*END PANEL TOP TRIM	Bent	152.30 F	*152.30 FL
39	1		*TAIL LAMP LH	Not Necessary	486.70 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,646.30	4,901.90
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,115.48
Total Parts (\$\$)	11,646.30	3,786.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R REAR BUMPER REVERSE SENSOR	New	80.00	30.00
2	TO CHECK WIRING AND LIGHTING SYSTEM	New	80.00	30.00
3	TO SUPPLY UNDER-COATING / PUTTY ON PART REPLACED	New	80.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	60.00	30.00
5	TO R&R REAR WINDSCREEN	New	200.00	120.00
6	TO R&R TAIL GATE MECHANISM	New	200.00	80.00
7	TO R&R REAR TRIMS AND GARNISH ASSY	New	180.00	0.00
8	TO REPAIR, REPLACE AND REALIGN DAMAGED AREAS	New	1,000.00	800.00
9	TO SPRAY PAINTING ON AFFECTED AREAS	New	900.00	500.00
10	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	New	150.00	30.00
Gross Labour Cost (S\$)			2,930.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >