

Bifrost Auto Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-49 Singapore 415875

Tel: +65 6452 4457 | Fax: +65 6452 4584

Co. Reg. No.: 201929175W

Vehicle No: **GBE4304Y**
 Model: **Toyota Hiace**
 Chassis No:
 Year of manufacturing:

NO.	DESCRIPTION	QTY	U/P	AMT
#	List Item			
	Rear bumper / <i>DD</i>	1		685.60 <i>390 /</i>
	Rear bumper retainer RH / <i>BR</i>	1		92.60 /
	Rear bumper retainer LH / <i>BR</i>	1		92.60 /
	Rear bumper bracket / <i>DT</i> <i>C'pc - \$55</i>	<i>X 3</i>		220.00 <i>165 /</i>
	Rear corner panel RH ? / <i>BR</i>	1		158.70 /
	Tail lamp RH / <i>BR</i>	1		486.70 <i>388 /</i>
	Tail lamp LH <i>X NN</i>	1		486.70 <i>X</i>
	Tail gate / <i>DD</i>	1		2150.70 <i>1910 /</i>
	Tail gate lock / <i>DT</i>	1		225.30 /
	Tail gate lock catch <i>X NN</i>	1		75.50 <i>X</i>
	Tail gate key lock <i>X NN</i>	1		105.20 <i>X</i>
	Tail gate lock handle <i>X NN</i>	1		142.80 <i>X</i>
	Tail gate license lamp garnish <i>X NN</i>	1		155.20 <i>X</i>
	Tail gate license lamp <i>X NN</i>	2		79.60 <i>X</i>
	Tail gate logo emblem / <i>PC</i>	1		79.60 /
	Tail gate rubber beading / <i>CR4</i>	1		226.80 /
	Tail gate inner trim <i>X NN</i>	1		338.40 <i>X</i>
	Tail gate damper RH <i>X NN</i>	1		152.50 <i>X</i>
	Tail gate damper LH <i>X NN</i>	1		152.50 <i>X</i>
	Tail gate hinge RH <i>X NN</i>	1		135.30 <i>X</i>
	Tail gate hinge LH <i>X NN</i>	1		135.30 <i>X</i>
	Tail gate windscreen <i>X NN</i>	1		1120.00 <i>X</i>
	Tail gate windscreen moulding <i>X NN</i>	1		223.60 <i>X</i>
	End panel / <i>DD</i>	1		865.50 <i>581 /</i>
	Rear floor panel <i>X R</i>	1		1752.30 <i>X</i>
				<i>4309-60</i>
				<i>- 25%</i>
				<i>3232-20</i>
				10339.00
Special Nett Items				
	Reverse sensor set / <i>SM</i>	1		250.00 <i>200 /</i>
	Reverse camera <i>X NN</i>	1		350.00 <i>X</i>
	Rear number plate <i>X NN</i>	1		45.00 <i>X</i>
	Rear bumper clip set / <i>PC</i>	1		50.00 <i>30 /</i>
	Tail gate inner trim clip set <i>X NN</i>	1		50.00 <i>X</i>
	Tail lamp clip set <i>X NN</i>	1		30.00 <i>X</i>
	Tail gate sticker - Toyota Hiace / <i>PC</i>	1		100.00 <i>50 /</i>

Tail gate sticker - 70km/h / MK	1	50.00	30 /
Tail gate windscreen sealant / MK	1	50.00	/
Tail gate windscreen inner seal / MK	1	30.00	20 /
End panel sealant / MK	1	50.00	30 /
Rear floor panel sealant X NN	1	50.00	X
	410	<u>1105.00</u>	

Labour & Miscellaneous Charge

To R&R rear bumper reverse sensor	80.00	30
To check wiring and lighting system	80.00	30
To supply under-coating / putty on part replaced	80.00	30
To perform anti rust treatment on affected areas	60.00	30
To R&R rear windscreen	200.00	120
To R&R tail gate mechanism	200.00	80
To R&R rear trims and garnish assy	180.00	X
To repair, replace and realign damaged areas	1000.00	800
To spray painting on affected areas	900.00	400 500
To perform water seepage test after repair	150.00	30
Sundries	50.00	30

2980.00 1650

List Items Subtotal
 Special Nett Items Subtotal
 Labour Items Subtotal
 Total

Steve CLKK)
 8322 8813
 Steve chin@lkkauts.com

WAL MK
 20/4/20, 2.99 pm
 L/S
 My AC say
 5 dys
 P-3232-20
 N-410
 L-1680
 Supp-114.22

5436-42
 L/S-4349.13
 = 4350

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Vehicle No: GBE4304Y
 Model: Toyota Hiace
 Chassis No:
 Year of manufacturing:

Co Reg No: 20192917

NO.	DESCRIPTION	QTY	U/P	AMT
	Supplementary Item			
	End panel top trim ✓ BT	1		152.30
	Special Nett Items			152.30
				0.00
	Labour & Miscellaneous Charge			

152.30
 -25%
 114.22



0.00
0.00

List Items Subtotal
 Special Nett Items Subtotal
 Labour Items Subtotal
 Total