

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM20005278/Eba3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN			Date: 06-10-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMK 5074S	Veh. Inspected	SJE 7312J	
	Policy No.	GA538987	Coverage (\$)	0.00	
	Claim No.	S0M02MCO	Excess (\$)	0.00	
	Assign From		Assign Date	17/04/2020	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA FIT	c.c	1339	
	Engine No.	HIDDEN	Year of Reg.	2008	
	Chassis No.	GE61037804	Colour	BLACK	
	Odometer	204945	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	195/55 R15	LING LONG	5 mm	
	L/H Front Tyre	195/55 R15	LING LONG	5 mm	
	R/H Rear Tyre	195/55 R15	LING LONG	5 mm	
	L/H Rear Tyre	195/55 R15	LING LONG	5 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	15/04/2020	Inspection Date	17/04/2020	
	Survey held at	•			
		53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days				