

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMG 2761H**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	REPLACED	1,020.70	1,020.70
1	FRONT BUMPER SPONGE	SERVICEABLE	128.70	-
1	FRONT BUMPER L/H SIDE RETAINER	SERVICEABLE	85.10	-
1	FRONT BUMPER R/H SIDE RETAINER	REPLACED	85.10	85.10
1	SET FRONT BUMPER CLIPS	REPLACED	35.00	35.00
1	FRONT LOGO EMBLEM	REPLACED	87.10	87.10
1	R/H HEADLAMP	SERVICEABLE	2,531.60	-
	LESS 25% DISCOUNT		-	-306.98
			3,973.30	920.92
	<b><u>LABOUR</u></b>			
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS.		800.00	200.00
	TO REALIGN HEADLAMP FOCUS.	NOT NECESSARY	35.00	-
	TO CHECK WIRING AND REWIRE.	NOT NECESSARY	60.00	-
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		600.00	200.00
			1,495.00	400.00
	<b>GRAND TOTAL</b>		<b>5,468.30</b>	<b>1,320.92</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,050.00</b>

Report Ref No. CS3/III19022345/R1td3e2-2

**MOHAMMED RASUL BIN MOHD YUNUS**

Automotive Assessor

**ADRIAN LING WAI PING****B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI**

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.