

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20005285/UGA3Q2**Date:** 03/02/2021REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	D18MPC0000020_01
Claimant		
Vehicle No : FBL5366A	Insured Vehicle No :	SMA1896R
Date of Loss: 19/03/2020	Nature of Claim: TP	Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL5366A		
Make & Model:	HARLEY-DAVIDSON STREET GLIDE S, 1.7	Engine No:	KRCH608357
Reg. Date:	07/12/2016 (Man. Year: 2016)	Chassis No:	5HD1KRCC0HB608357
Colour:	Black	Odometer:	25148 km
Engine Capacity:	1745 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	130/60R19	Rear Tyre Size:	180/55 R18
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	6,746.40	5,158.80	1,587.60	23.53	
Miscellaneous Items	0.00	0.00	0.00		
Labour	1,360.00	650.00	710.00	52.21	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
Calculated Gross Total (S\$)	8,106.40	5,808.80	2,297.60	28.34	
Approved Total (Overridden) (S\$)		4,600.00			
	(S\$)	8,106.40	4,600.00	3,506.40	43.25
	+ GST 7.00/7.00% (S\$)	567.45	322.00	245.45	43.25
	Nett Amount (S\$)	8,673.85	4,922.00	3,751.85	43.25
	Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	02/04/2020	
Date Inspected:	21/04/2020	Inspected At:
		Yew Tee Automobile Tech Pte Ltd (Kaki Bukit) Blk 25 Kaki Bukit Road 4, #01-61 SYNERGY @ KAKI BUKIT Singapore 417800
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Feb 2021)	
Parts:	N/A	HARLEY-DAVIDSON STREET GLIDE S 1.7 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL5366A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT FENDER	Dented	2,024.40 F	*1,662.00 FL	
2	1		*FRONT FORK LH (NPA)	Serviceable	0.00 F	*- FL	
3	1		*FRONT FORK RH (NPA)	Serviceable	0.00 F	*- FL	
4	1		*FUEL TANK	Dented	4,150.00 F	*3,500.00 FL	
5	1		*FUEL TANK EMBLEM RH	Necessary	122.00 F	*120.00 FL	
6	1		*SET ENGINE CRASH BAR (NPA)	Serviceable	0.00 F	*- FL	
7	1		*STEERING CONE & BEARING (NPA)	Not Necessary	0.00 F	*- FL	
8	1		*STEERING UNDER BRACKET (NPA)	Not Necessary	0.00 F	*- FL	
9	1		*FRONT FORK CENTRE STABILIZER LINK	Dented	450.00 F	*450.00 FL	
					Sub Total (\$)	6,746.40	5,732.00
					- List Item Discount on L Items 0.00/10.00% (\$)	0.00	573.20
					Total Parts (\$)	6,746.40	5,158.80

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CONDUCT WHEEL BALANCING	New	60.00	0.00
2	TO DISCONNECT AND RECONNECT,CHECK ELECTRICAL WIRING HARNESS WIRE,SOCKETS,REPLACE DAMAGED PARTS	New	40.00	0.00
3	TO DISMANTLE AND REFIT FRONT FORK	New	200.00	100.00
4	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS,STRAIGHTEN,KNOCK OUT,REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS.TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS	New	500.00	250.00
5	TO APPLY UNDERCOATING ON THE REPAIRED AND REPLACED PANELS FOR RUST PROTECTION	New	80.00	0.00
6	TO CARRY-OUT BODY CAVITY PRESERVATION	New	80.00	0.00
7	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS,PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER,CLEANING AND SANDING OF SURFACES,FINAL POLISHING AND WAXING ARE ALSO AVAILABLE	New	400.00	300.00
Gross Labour Cost (\$\$)			1,360.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >