



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2006118
INV Date 07/09/2020
Reference CC4/LPC20005286/Nps3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. FBN 2818Y
Insured Veh. SMF 1562C
Claim No. 19/20/20/VP05/023288
Policy No. Z/19/VP05/024851-001
Accident Date 03/04/2020
Inspection Date 04/05/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC20005286/Nps3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 07-09-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMF 1562C	Veh. Inspected	FBN 2818Y
Policy No.	Z/19/VP05/024851-001	Coverage (\$)	0.00
Claim No.	19/20/20/VP05/023288	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	20/04/2020

2. Vehicle Particulars & Condition

Make & Model	YAMAHA AEROX	c.c	155
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	MH3SG4640JJ045414	Colour	BLUE
Odometer	36582	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	120/70-14	PIRELLI	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70-R14	PIRELLI	4 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/04/2020	Inspection Date	04/05/2020
Survey held at	BIKE PRODUCTION PTE LTD 610 SERANGOON ROAD SINGAPORE 218216		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBN 2818Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT MUDGUARD REAR COVER	SERVICEABLE	75.00	-
1	FRONT MUDGUARD	SCRATCHED	95.00	95.00
1	WHEEL AXLE	BENT	60.00	60.00
1	BRAKE DISK	SERVICEABLE	185.00	-
1	RIGHT FORK ASSY	BENT	420.00	350.00
1	LEFT FORK ASSY	BENT	420.00	350.00
1	STEERING STEM	BENT	220.00	150.00
2	STEERING STEM BEARINGS @\$45.00	NECESSARY	90.00	90.00
1	CENTRE COVER INNER	DEFORMED	120.00	120.00
1	CENTRE COVER LOWER	SCRATCHED	140.00	140.00
1	FRONT COVER GOLD	DEFORMED	95.00	95.00
1	FRONT COVER GOLD AMBLEM	NECESSARY	25.00	25.00
1	LEFT FRONT FAIRING	CRACKED	140.00	140.00
1	LEFT FRONT FAIRING AMBLEMS	NECESSARY	35.00	35.00
1	RIGHT FRONT FAIRING	CRACKED	140.00	140.00
1	RIGHT FRONT FAIRING AMBLEMS	NECESSARY	35.00	35.00
1	HEADLAMP ASSY	CRACKED	280.00	280.00
1	HEADLAMP LOWER COVER	CRACKED	85.00	85.00
1	LEFT FRONT SIGNAL	SCRATCHED	85.00	60.00
1	LEFT MIRROR ASSY	SCRATCHED	55.00	55.00
1	LEFT LEVER	SCRATCHED	55.00	55.00
1	HANDLE BAR	BENT	140.00	140.00
1	LEFT FOOT STEP	SCRATCHED	140.00	140.00
1	LEFT FOOTSTEP RUBBER	NECESSARY	65.00	65.00
1	SIDE STAND	SCRATCHED	85.00	40.00
1	MAINSTAND	SCRATCHED	185.00	150.00
1	LEFT ENGINE COVER	SCRATCHED	295.00	250.00
1	AIRBOX ASSY	SCRATCHED	140.00	140.00
1	CENTRE INNER COVER BODY	CRACKED	135.00	135.00
1	REAR LEFT SUSPENSION	SERVICEABLE	250.00	-
1	LEFT REAR FOOTREST (ADDITIONAL)	SCRATCHED	65.00	65.00

Report Ref No. CC4/LPC20005286/Nps3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LEFT FRONT SIGNAL (ADDITIONAL)	NOT NECESSARY	95.00	-
1	LEFT REAR COVER 1 (ADDITIONAL)	CRACKED	95.00	95.00
1	LEFT REAR COVER BLACK (ADDITIONAL)	SCRATCHED	85.00	85.00
1	LEFT FRONT BLACK COVER (ADDITIONAL)	CRACKED	95.00	95.00
	LESS 10% DISCOUNT		-472.50	-376.00
			4,252.50	3,384.00
	<u>SPECIAL NETT ITEMS</u>			
1	BOX BRACKET (SN)	SCRATCHED	140.00	140.00
			140.00	140.00
	<u>LABOUR</u>			
	TOWING CHARGES.	NOT NECESSARY	100.00	-
	REPLACE ,REALIGN AND ADJUST ABOVE DAMAGED PARTS ,CHECK WIRING AND LIGHTING SYSTEM .		700.00	300.00
	TO REMOVE REPLACE AND BALANCE FRONT WHEEL RIM .		120.00	30.00
	TO KNOCK,STRAIGHTEN CHASSIS & BODY BALANCING .		380.00	100.00
	TO REMOVE /REFIT ,REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FRONT FORK TUBES.		180.00	50.00
	SPRAY PAINTING.		300.00	200.00
			1,780.00	680.00
GRAND TOTAL			6,172.50	4,204.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,300.00

Report Ref No. CC4/LPC20005286/Nps3n2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.