

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005290/T1DS3Q2

Date: 10/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900083161

Claimant
Vehicle No : SMS2094L **Insured Vehicle No :** SKC2410R

Date of Loss: 17/04/2020 Nature of Claim: TP Claim No: 3567793788SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMS2094L		
Make & Model:	TOYOTA VOXY HYBRID V, 1.8 (A)	Engine No:	2ZR2F14233
Reg. Date:	14/02/2020 (Man. Year: 2019)	Chassis No:	ZWR800410907
Colour:	Silver	Odometer:	10948 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,077.22	5,665.72	3,411.50	37.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,700.00	1,760.00	940.00	34.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,777.22	7,425.72	4,351.50	36.95
Approved Total (Overridden) (S\$)		5,950.00		
(S\$)	11,777.22	5,950.00	5,827.22	49.48
+ GST 7.00/7.00% (S\$)	824.41	416.50	407.91	49.48
Nett Amount (S\$)	12,601.63	6,366.50	6,235.13	49.48
+ Loss of Use (6.0 x S\$110.00/day) (S\$)		660.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		7,062.95		

INSPECTION

Date of Assignment: 20/04/2020

Date Inspected: 20/04/2020 Inspected At:

Em-1 Auto Pte Ltd (sin Ming) (HQ)
160 SIN MING DRIVE, #05-21 SIN
MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	2,195.70 FL	*1,712.85 FL
2	1		*TAILGATE BADGE	Not Necessary	80.70 FL	*- FL
3	1		*TAILGATE EMBLEM HYBRID	Necessary	91.70 FL	*91.70 FL
4	1		*TAILGATE OUTER GARNISH CLIPS	Not Necessary	30.00 FL	*- FL
5	2		*TAILGATE STOPPER	Not Necessary	68.20 FL	*- FL
6	2		*TAILGATE SIDE STOPPER (MALE)	Not Necessary	92.20 FL	*- FL
7	2		*TAILGATE SIDE STOPPER (FEMALE)	Not Necessary	96.20 FL	*- FL
8	1		*TAILGATE POCKET HANDLE	Deformed	59.40 FL	*59.40 FL
9	1		*TAILGATE INNER TRIM	Cracked	920.70 FL	*550.00 FL
10	1		*SET TAILGATE INNER TRIM CLIPS	Necessary	40.00 FL	*30.00 FL
11	1		*TAILGATE INNER LOCK	Bent	434.50 FL	*368.95 FL
12	1		*TAILGATE LOCK CATCH	Repair	68.10 FL	*- FL
13	1		*TAILGATE WEATHERSTRIP	Cut	327.50 FL	*327.50 FL
14	2		*TAILGATE HINGES	Repair	208.20 FL	*- FL
15	2		*TAILGATE ABSORBE	Repair	790.20 FL	*- FL
16	2		*REAR WINDSCREEN MOULDING	Necessary	180.00 FL	*180.00 FL
17	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FL	*50.00 FL
18	1		*REAR BUMPER	Deformed	1,247.10 FL	*1,025.00 FL
19	1		*REAR BUMPER SIDE RETAINERS	N/S Deformed /O/SNot Necessary	118.20 FL	*59.10 FL
20	1		*REAR BUMPER ATTACHMENT RETAINERS	N/S Deformed /O/SNot Necessary	123.40 FL	*61.70 FL
21	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
22	2		*REAR BUMPER REFLECTORS	Not Necessary	103.40 FL	*- FL
23	1		*END PANEL	Bent	785.60 FL	*530.00 FL
24	1		*END PANEL TOP TRIM	Deformed	321.50 FL	*321.50 FL
25	1		*SET END PANEL TOP TRIM CLIPS	Necessary	30.00 FL	*30.00 FL
26	1		*REAR FLOOR PANEL TOP BOARD	Deformed	691.50 FL	*691.50 FL
27	1		*REAR KEY ANTENNA	Cracked	324.10 FL	*324.10 FL
28	1		*REAR FENDER INNER TRIMS	N/S Cracked / O/SNot Necessary	1,848.20 FL	*681.00 FL
29	2		*REAR FENDER INNER TRIMS CLIPS	Necessary	60.00 FL	*30.00 FL
30	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*60.00 FS
31	1		*REAR NUMBER PLATE	Not Necessary	70.00 FS	*- FS
32	1		*SET REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
33	1		*SET BODY PANEL JOINT SEALANT	Necessary	120.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,936.30	7,454.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,859.08	1,788.58
Total Parts (\$\$)	9,077.22	5,665.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,000.00	700.00
2	SPRAY PAINTING	New	1,000.00	700.00
3	CHECK WIRING	New	50.00	30.00
4	ANTI RUST	New	90.00	30.00
5	REMOVE AND INSTALL REAR WINDSCREEN	New	140.00	120.00
6	REMOVE AND INSTALL TAILGATE PARTS	New	90.00	60.00
7	REMOVE AND INSTALL CARPET AND SEATS	New	120.00	60.00
8	REMOVE AND INSTALL REVERSE SENSOR	New	90.00	30.00
9	REMOVE AND INSTALL REAR CAMERA	New	120.00	30.00
Gross Labour Cost (\$)			2,700.00	1,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >