

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20005300/AYF3E2

**Date:** 21/07/2020

#### REFERENCE

Insured/Claimant: CHUA SWEE BOON (CAI RUIWEN) Policy No: 1700063199-02  
Date of Loss: 09/04/2020 Nature of Claim: OD Claim No: 5783914080SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGH7637S**  
 Make & Model: AUDI A4, 1.4 (A) Engine No: CVN041412  
 Reg. Date: 11/10/2017 (Man. Year: 2017) Chassis No: WAUZZZF4XHA182059  
 Colour: Black Odometer: 33080 km  
 Engine Capacity: 1395 cc  
 Market Value/New Car Price: S\$100,000.00  
 Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

#### CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17  
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	19,115.00	5,246.24	13,868.76	72.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,902.00	3,202.00	3,700.00	53.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>26,017.00</b>	<b>8,448.24</b>	<b>17,568.76</b>	<b>67.53</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,821.19</b>	<b>591.38</b>	<b>1,229.81</b>	<b>67.53</b>
<b>Nett Amount (S\$)</b>	<b>27,838.19</b>	<b>9,039.62</b>	<b>18,798.57</b>	<b>67.53</b>

#### INSPECTION

Date of Assignment: 22/04/2020  
 Date Inspected: 21/04/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)  
 55 Ubi Road 1  
 Singapore 408699  
 Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING

**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,010.00 FS	*1,608.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	269.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Not Necessary	67.00 FS	*- FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Not Necessary	185.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	198.00 FS	*- FS
6	1		*FRONT BUMPER AIR GUIDE - LH	Not Necessary	59.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,714.00 FS	*1,371.20 FS
8	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	344.00 FS	*- FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	117.00 FS	*- FS
10	1		*FRONT BUMPER CARRIER	Not Necessary	757.00 FS	*- FS
11	1		*FRONT BUMPER COVER	Not Necessary	120.00 FS	*- FS
12	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	34.00 FS	*- FS
13	1		*CAUTION SIGN STICKER	Not Necessary	13.00 FS	*- FS
14	1		*AIRCON STICKER	Not Necessary	7.00 FS	*- FS
15	1		*LOCK CARRIER BRACKET	Not Necessary	129.00 FS	*- FS
16	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	54.00 FS	*- FS
17	1		*HORN - LH HIGH TONE	Not Necessary	38.00 FS	*- FS
18	1		*SPRING SHACKLE - LH	Not Necessary	27.00 FS	*- FS
19	1		*FRONT FENDER - LH	Repair	722.00 FS	*- FS
20	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	190.00 FS	*- FS
21	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	47.00 FS	*- FS
22	1		*FRONT FENDER BRACKET - LH	Not Necessary	33.00 FS	*- FS
23	1		*DEFORMATION ELEMENT BRACKET - LH	Not Necessary	46.00 FS	*- FS
24	1		*FRONT FENDER BRACKET	Not Necessary	30.00 FS	*- FS
25	1		*FRONT FENDER BRACE - LH FRONT	Not Necessary	112.00 FS	*- FS
26	1		*WHEEL HOUSING LINER - LH	Not Necessary	226.00 FS	*- FS
27	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	86.00 FS	*- FS
28	1		*WHEEL SPOILER	Not Necessary	69.00 FS	*- FS
29	1		*WHEEL SPOILER TRIM - LH	Not Necessary	33.00 FS	*- FS
30	1		*STONE CHIP GUARD	Necessary	48.00 FS	*37.92 FS
31	1		*TOP FENDER LEDGE COVER - LH INNER	Not Necessary	29.00 FS	*- FS
32	1		*TOP FENDER LEDGE COVER - LH OUTER	Not Necessary	21.00 FS	*- FS
33	1		*BONNET	Dented	2,634.00 FS	*2,107.20 FS
34	1		*BONNET ATTACHMENT PARTS	Not Necessary	116.00 FS	*- FS
35	2		*BONNET LID HINGE - LH / RH	Not Necessary	574.00 FS	*- FS
36	3		*BONNET IMPACT PROTECTION - LH / RH / CENTRE	Not Necessary	78.00 FS	*- FS
37	1		*LED HEADLIGHT - LH	Not Necessary	7,321.00 FS	*- FS
38	1		*LEFT CYLINDER - LH	Not Necessary	198.00 FS	*- FS
39	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
40	1		*SUNDRIES	Necessary	300.00 FS	*61.92 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)** **19,115.00** **5,246.24**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,150.00	1,000.00
3	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET AND HINGES	New	3,200.00	1,650.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			<b>Gross Labour Cost (S\$)</b>	<b>6,902.00</b>
				<b>3,202.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >