



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 1567Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SIDE MIRROR MECHANISM RH	DAMAGED	868.00	868.00
1	SIDE MIRROR GLASS RH	CRACKED	499.00	499.00
1	SIDE MIRROR COVER BOTTOM RH	NOT NECESSARY	78.00	-
1	SIDE MIRROR COVER W/SIGNAL LAMP RH	CUT	380.00	185.00
1	FRONT DOOR RH (NPA)	NOT NECESSARY	-	-
	LESS 10% DISCOUNT		-182.50	-155.20
			1,642.50	1,396.80
	<u>LABOUR</u>			
	TO CHECK WIRING .		50.00	30.00
	PANEL BEATING CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS.		200.00	100.00
	SPRAY PAINTING ALL AFFECTED PARTS & AREAS.		400.00	100.00
			650.00	230.00
	GRAND TOTAL		2,292.50	1,626.80
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,300.00

Report Ref No. CS/AGI20005301/Ayf3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.