Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20005303/ABA3Q2

Date: 05/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100485180

Claimant Vehicle No: Insured Vehicle No: SLG578X

Date of Loss: 03/04/2020 Nature of Claim: TP Claim No: 2754398956SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SML8929B

Make & Model: AUDI A3, 999cc TFSI S TRONIC (LED) (A) Engine No: CHZC29866

Reg. Date: 10/06/2019 (Man. Year: 2019) Chassis No: WAUZZZ8VXKA074327

Colour: Blue Odometer: 12934 km

Engine Capacity: 999 cc Market Value/New Car N/A

Price:
Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,246.00	0.00	3,246.00	100.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,547.00	1,647.00	900.00	35.34
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
G	ross Total (S\$)	5,793.00	1,647.00	4,146.00	71.57
+ GST 7	7.00/7.00% (S\$)	405.51	115.29	290.22	71.57
Ne	tt Amount (S\$)	6,198.51	1,762.29	4,436.22	71.57
+	Loss of Use (3.0 x S	\$60.00/day) (S\$)	180.00		
	+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,944.29			

INSPECTION

Date of Assignment: 20/04/2020

Date Inspected: 20/04/2020 Inspected At: Premium Automobiles Pte Ltd (HQ)

55 UBI ROAD 1

Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: CHUA ZHEN LI

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	(Condition	Repairer's	Amount
1	1	*REAR BUMPER	F	Repair	1,851.00 FS	*-FS
2	4	*REAR BUMPER STICKY PAD	1	Not Necessary	22.00 FS	*-FS
3	1	*REAR BUMPER FIXING PARTS	N	Not Necessary	182.00 FS	*- FS
4	2	*REAR BUMPER GUIDE SECTION	N -LH/RH	Not Necessary	30.00 FS	*-FS
5	2	*REAR BUMPER LOCKING MEC	HANISM 1	Not Necessary	55.00 FS	*-FS
6	1	*REAR BUMPER SPOILER	1	Not Necessary	223.00 FS	*-FS
7	2	*REAR LIGHT REFLECTOR -LH/	RH 1	Not Necessary	78.00 FS	*-FS
8	1	*REAR BUMPER SIDE REINFOR	CEMENT BEAM	Not Necessary	538.00 FS	*-FS
9	1	*REAR BUMPER BRACKET -LH	N	Not Necessary	26.00 FS	*-FS
10	1	*REAR BUMPER BRACKET -RH	1	Not Necessary	27.00 FS	*-FS
11	2	*REAR PARKING AID SENSOR -	INNER /OUTER (NPA)	Not Necessary	0.00 FS	*-FS
12	4	*REAR PARKING AID SEAL RIN	G 1	Not Necessary	14.00 FS	*-FS
13	1	*SUNDRIES	1	Not Necessary	200.00 FS	*-FS
F=Fra	F=Franchise part. S=SpcNett.					
			To	otal Parts (S\$)	3,246.00	0.00
_						

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND REINSTALL REAR PARKING AID ,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE- ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,050.00	500.00
3	TO REAPPLY PAINT COATING (BY OWNER)	New	125.00	125.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO RESPRAY REAR BUMPER	New	900.00	550.00
	Gross Labour Cost (S\$		2,547.00	1,647.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >