



Your Ref: S9M0247N

Date: 05th May 2020

Our Ref: CS3/ASM19018878/Qvf3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01

Axa Tower

Singapore 068811

(The Motor Claims Department)

Attn : Richard Ang

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLJ 3318U
INSURED VEHICLE: SDA 6000H
ACCIDENT DATE: 12/10/2019**

We thank you for your instruction on 20/04/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLJ 3318U from M/s Impact Analysis Consultant.
- b) Singapore Accident Statement of Vehicles SLJ 3318U and SDA 6000H.
- c) Colour damaged vehicle photographs of SLJ 3318U.

Pre-Repair Inspection Date : 24/10/2019 at M/s 60 Jalan Lam Huat #05-06/07, Repairer : Jas Auto Services.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLJ 3318U
Make & Model	: B.M.W. M6 4.4 AT ABS Airbags 2WD 4DR
Year of Registration	: 2014
Chassis Number	: WBS6C92030DV74404
Engine Capacity	: 4395 cc

2. We recommend that the repairs of the entire damage require about 3 (Three) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.