

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20005321/UGA3Q2
Date: 14/10/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900207238
Claimant Vehicle No :	GBC8217A	Insured Vehicle No :	YP104D
Date of Loss:	16/04/2020	Nature of Claim:	TP
		Claim No:	9582577302SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC8217A	Engine No:	1KD2316984
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	JTFHT02P800121032
Reg. Date:	29/11/2013 (Man. Year: 2013)	Odometer:	122382 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,464.40	2,786.92	2,677.48	49.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	910.00	720.00	190.00	20.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,374.40	3,506.92	2,867.48	44.98
Approved Total (Overridden) (S\$)		2,800.00		

Nett Amount (S\$)	6,374.40	2,800.00	3,574.40	56.07
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
(S\$)		3,160.00		
Liabe Amount (50.00%) (S\$)		1,580.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,587.45		

INSPECTION

Date of Assignment: 20/04/2020

Date Inspected: 20/04/2020

Estimated Period of Repair: 4.0 days

Inspected At:

Liu's Brother Auto Engineering Workshop
 1 Kaki Bukit Ave 6 #01-01, Auto Bay@Kaki Bukit
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Dented / Buckled	835.30 F	*727.10 FL
2	1		*FRONT BONNET TOYOTA EMBLEM	Necessary	71.60 F	*71.60 FL
3	2		*FRONT HEAD LAMP	Holder Cracked	1,861.40 F	*1,408.70 FL
4	2		*FRONT HEAD LAMP CLIP	Not Necessary	70.00 FS	*- FS
5	1		*FRONT GRILLE	Cracked	665.50 F	*605.10 FL
6	1		*SET FRONT GRILLE CLIPS	Necessary	30.00 FS	*30.00 FS
7	1		*FRONT BUMPER	Distorted	796.60 F	*496.30 FL
8	1		*SET FRONT BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
9	1		*FRONT BUMPER GRILLE	Not Necessary	155.80 F	*- FL
10	1		*FRONT RH BUMPER BRACKET	Not Necessary	380.40 F	*- FL
11	1		*FRONT RH BUMPER FOG LAMP COVER	Serviceable	57.00 F	*- FL
12	1		*FRONT RH CORNER PANEL	Dented / Bent	376.50 F	*303.10 FL
13	1		*FRONT RH HEAD LAMP BRACKET	Not Necessary	116.30 F	*- FL
					Sub Total (\$\$)	5,464.40
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00
					Total Parts (\$\$)	5,464.40
						2,786.92

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	50.00	20.00
2	LABOR FOR PANEL BEATING ,CUT ,WELD ,STRAIGHTEN & REPLACING PARTS ETCS	New	400.00	300.00
3	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED	New	400.00	350.00
4	TO APPLY RUST PROOFING RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	60.00	50.00
Gross Labour Cost (\$\$)			910.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >