



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC3/AXA11009124/Krm3q2

8 SHENTON WAY #27-01 SINGAPORE 068811

Date : 03-06-2015



ATTN: JACQUELINE LEONG

Code : AXA2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKA 9716Z	Veh. Inspected	SHB 7537S
Policy No.	P1053145	Coverage (\$)	0.00
Claim No.	C0204816	Excess (\$)	0.00
Assign From		Assign Date	16/05/2011

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CROWN (M)	c.c	2986
Engine No.	HIDDEN	Year of Reg.	2004
Chassis No.	LXS120011065	Colour	WHITE/RED
Odometer	979301	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/80 R14	WEST LAKE	9 mm
L/H Front Tyre	175/80 R14	WEST LAKE	9 mm
R/H Rear Tyre	175/80 R14	WEST LAKE	9 mm
L/H Rear Tyre	175/80 R14	WEST LAKE	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/05/2011	Inspection Date	16/05/2011
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD 58 DEFU LANE 1 SINGAPORE 539498		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------