6/7/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG20005328/KGA3Q2

Date:

07/06/2021

REFERENCE

Date of Loss:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

1900077574

Claimant Vehicle No:

SHD5470C 18/04/2020

Insured Vehicle No:

Nature of Claim:

SDV5785Y TP

Claim No:

2926518990SG

JTDKB3FU603079168

2ZR2B98684

101068 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD5470C

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A)

25/01/2019 (Man. Year: 2018) Reg. Date:

Colour: Metallic Pearl White/Red

Engine Capacity: 1798 cc Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Engine No:

Chassis No:

Odometer:

Yes

Handbrake (Serviceable):

Yes

Sailun 9 mm

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Right Side:

Front Tyre Size: 195/65R15 Front Left Side: Sailun 9 mm

Rear Tyre Size: Rear Left Side:

195/65R15 Sailun 9 mm

Rear Right Side:

Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		11,475.30	3,293.10	8,182.20	71.30
Miscellaneous Items		0.00	0.00	0.00	
Labour		17,890.00	1,290.00	16,600.00	92.79
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	29,365.30	4,583.10	24,782.20	84.39
	+ GST 7.00/7.00% (S\$)	2,055.57	320.82	1,734.75	84.39

Nett Amount (S\$) 31,420.87 4,903.92 26,516.95 84.39

0.00

Global Sum Settlement (S\$)

INSPECTION

Date of Assignment: 21/04/2020

Trans-cab Auto Services (HQ) Date Inspected: Inspected At: NO. 2 ANG MO KIO ST 63 21/04/2020

Singapore 569111

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	*REAR BUMPER	Buckled	442.60 FL	*442.60 FL
2 1	*REAR BUMPER RE-INFORCEMENT	Repair	332.70 FL	*- FL
3 1	*REAR BUMPER TOWING COVER	Missing	15.40 FL	*15.40 FL
1 1	*GUARD,REAR BUMPER,CENTER	Buckled	576.30 FL	*576.30 FL
5 1	*REAR BUMPER SIDE RETAINER LH	Serviceable	116.50 FL	*- FL
3 1	*REAR BUMPER SIDE RETAINER RH	Serviceable	117.70 FL	*- FL
7 1	*REAR TAILGATE	Buckled	1,147.80 FL	*1,147.80 FL
3 1	*REAR TAILGATE OUTER GARNISH	Cracked	925.60 FL	*925.60 FL
9 1	*REAR TAILGATE WEATHERSTRIP	Serviceable	372.30 FL	*- FL
10 1	*PANEL SUB-ASSY,BODY LOWER BACK	Serviceable	650.30 FL	*- FL
11 1	*TAILLAMP LOWER RH	Cracked	502.00 FL	*502.00 FL
12 1	*TAILLAMP UPPER RH	Serviceable	451.80 FL	*- FL
13 1	*REAR BUMPER SIDE RH	Mtg Cracked	123.70 FL	*123.70 FL
14 1	*REAR BUMPER SIDE LH	Serviceable	123.70 FL	*- FL
15 1	*TAILLAMP LOWER LH	Serviceable	502.00 FL	*- FL
16 1	*TAILLAMP UPPER LH	Serviceable	443.30 FL	*- FL
17 1	*COVER,DECK TRIM,REAR	Serviceable	126.70 FL	*- FL
18 1	*COVER,FLOOR UNDER,NO 1	Serviceable	175.10 FL	*- FL
19 1	*COVER,FLOOR UNDER,NO 2	Serviceable	241.90 FL	*- FL
20 1	*COVER,REAR FLOOR	Serviceable	229.90 FL	*- FL
21 1	*PANEL SUB-ASSY,QUARTER,RH	Repair	871.50 FL	*- FL
22 1	*REAR FENDER LINER	Serviceable	139.80 FL	*- FL
23 1	*DUCT ASSY,QUARTER VENT,RH	Serviceable	67.00 FL	*- FL
24 1	*SEAL,REAR BUMPER SIDE,RH	Serviceable	88.50 FL	*- FL
25 1	*PAN,REAR FLOOR	Repair	583.40 FL	*- FL
26 1	*MOULDING,BACK DOOR OUTSIDE GARNISH,LOWER RH	Serviceable	56.50 FL	*- FL
27 1	*REAR TAILGATE TOYOTA LOGO	Necessary	47.00 F	*47.00 FN
28 1	*REAR TAILGATE WORDING PRIUS	Necessary	52.90 F	*52.90 FN
29 1	*REAR TAILGATE WORDING HYBRID	Necessary	53.50 F	*53.50 FN
30 1	*SET PARKING AID	Serviceable	700.00 FS	*- FS
31 1	*SET REAR BUMPER CLIP	Necessary	68.00 FS	*68.00 FS
32 1	*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
33 1	*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
34 1	*REAR BUMPER PROTECTOR	Not Necessary	120.00 FS	*- FS
35 1	*WHEEL RIM	Serviceable	1,879.40 FS	*- FS

6/7/2021

No.	Qty Part No.	Particulars	Condition	Repairer's	Amount
36	1	*TYRE 195/65/15	Serviceable	350.00 FS	*-FS
37	1	*WHEEL RIM COVER	Serviceable	211.50 FS	*-FS
38	1	*REAR RH BUMPER RETAINER CLIP	Not Necessary	35.00 FS	*-FS
39	1	*REAR LH BUMPER RETAINER CLIP	Not Necessary	35.00 FS	*- FS
40	1	*SET TAILLAMP LOWER CLIP	Not Necessary	35.00 FS	*- FS
41	1	*SET TAILLAMP UPPER CLIP	Not Necessary	35.00 FS	*- FS
42	2	*REAR WINDSCREEN SEALANT	Necessary	130.00 FS	*40.00 FS
43	1	*WINDSCREEN MOULDING	Necessary	180.00 FS	*180.00 FS
44	1	*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	120.00 FS	*30.00 FS
45	1	*SET REAR FENDER LINER CLIP	Not Necessary	35.00 FS	*-FS
46	2	*END PANEL SEAM SEALANT	Not Necessary	160.00 FS	*-FS
F=Fran	chise part. S=SpcN	ett. L=ListItemDisc. N=NettItemDisc.			
			Sub Total (S\$)	13,831.30	4,264.80
			 List Item Discount on L Items 25.00/25.00% (S\$) 	2,356.00	933.35
			- Nett Item Discount on N Items 0.00/25.00% (S\$)	0.00	38.35
			Total Parts (S\$)	11,475.30	3,293.10

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
3	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
4	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
7	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	7,500.00	660.00
9	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	120.00
10	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	7,500.00	400.00
11	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
12	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	0.00
13	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
14	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00
15	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
	Gross Labou	ır Cost (S\$)	17,890.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >