

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 2799Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT GRILLE W/EMBLEM (CONSISTENT)	CRACKED	1,275.00	1,247.15
1	FRONT GRILLE CENTRE BRACKET (CONSISTENT)	NOT NECESSARY	25.00	-
1	FRONT BUMPER (CONSISTENT)	TO REPAIR SEE LABOUR	1,580.00	-
1	FRONT BUMPER GRILLE (ADDITIONAL) (CONSISTENT)	TORN	83.00	83.00
1	FRONT BUMPER BRACKET (CENTRE) (ADDITIONAL) (CONSISTENT)	CRACKED	93.00	93.00
1	FRONT BUMPER SPONGE (CENTRE) (ADDITIONAL) (CONSISTENT)	TORN	123.00	123.00
1	FRONT BUMPER REINFORCEMENT (ADDITIONAL) (CONSISTENT)	DENTED	608.00	608.00
	LESS 10% DISCOUNT		-	-215.42
			3,787.00	1,938.73
	SPECIAL NETT ITEMS			
4	FRONT SENSOR (SN) (CONSISTENT)	SERVICEABLE	1,200.00	-
1	NUMBER PLATE W/CASING (SN) (CONSISTENT)	SCRATCHED	60.00	40.00
10	FRONT BUMPER CLIPS (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
			1,310.00	40.00
	<u>LABOUR</u>			
	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER .		600.00	250.00
	TO SPRAY PAINT ON AFFECTED AREAS.		600.00	200.00
	TO CHECK WIRING .		120.00	20.00
	TO APPLY UNDERCOATING FOR RUST PROOFING.	NOT NECESSARY	150.00	-
	TO DISMANTLE ,REPLACE AND /OR REPAIR FRONT SENSOR & TESTING.		150.00	40.00
			1,620.00	510.00
	GRAND TOTAL		6,717.00	2,488.73

RECOMMENDED COST OF LUMP SUM REPAIRS		1,900.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM20005334/Uga3q2





Report Ref No. CC4/ASM20005334/Uga3q2

CHUA KANG SENG
Licensed Appraiser