

(08/11/13) wef

ASS. REC. BY: *Marcus*

REF:

CO4/ASM20005334/4923

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLX2799Y

at Workshop m/s

Abwin

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

#41k

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen: *Q*

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

1244 4337

Date / Time

Action / Instruction

29/5/20 here video 27A 36663 4/5 @ 1900 confirmed with Sharifah

Veh No:

SLX2799Y

Yr Regn:

7, 11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CA*

Make:

mer benz

E200

c.c

1796

Colour

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

148091

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD212042A415106

Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: *Order* / Jammed / Leaked / Burnt or

Brake: *Order* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / *STD A/Rim* or

Tyre Size:

F:

245/40 R18 PIR

R:

GY

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

6

mm

L/Bal.

mm

D.O.A.

19/4/20

D.O.I.

22/4/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: *7*

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) *S* + RS, *SI*

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwinm9.com Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

LKK Cecilia



ESTIMATED COST: HQQ000310

TO : AXA INSURANCE SINGAPORE PTE LTD
ATTN : MOTOR CLAIM DEPARTMENT

DATE : 21-APR-2020
MAKE : MERCEDES BENZ
MODEL : E 200CGI
CHASSIS NO : WDD2120482A415106
ENGINE NO : 27186030215456
SERVICE ADVISOR : SHARIFAH
PAGE : 1 OF 1

SLX2799Y
LEE CHE HWAY ENOCH
BLK 102A PUNGGOL FIELD
#13-436
SINGAPORE 821102
CONTACT NO : 96717369

*not asked
21/4/20
1900
2 shp.
Why bit the up*

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	FRONT GRILLE W/EMBLEM	1247.15	cm 1,275.00
1	FRONT GRILLE CENTRE BRACKET	102	17 25.00 X
1	FRONT BUMPER		12 1,580.00 X
Sub Total		2,880.00	0.00

SPECIAL NETT

4	FRONT SENSOR		500 1,200.00 X
1	NUMBER PLATE W/CASING		500 60.00 40
10	FRONT BUMPER CLIPS		17 50.00 X
Sub Total		1,310.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	600.00	250
1	TO SPRAY PAINT ON AFFECTED AREAS	600.00	200
1	TO CHECK WIRING	120.00	20
1	TO APPLY UNDERCOATING FOR RUST PROOFING	150.00	X
1	TO DISMANTLE, REPLACE AND/OR REPAIR FRONT SENSOR & TESTING	150.00	40
Sub Total		1,620.00	0.00

SUB-TOTAL

5,810.00 0.00

LKK Auto Consultants hence notify the Repairer of the following:

GST - 7%

406.70 0.00

TOTAL

6,216.70 0.00

ABWIN SERVICE PTE LTD

- To resurvey before/after spray
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Prepared By

*P-2154.15
102
9-1938.73
5-2-40-00
2-510-00
2488.73*

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
Tel: 67139400 Fax: 67139415
Email: servicecentre@abwinm9.com Website: www.abwinm9.com
Company Reg. No: 201318685G GST Reg. No: 201318685G

**SUPPLEMENTARY: HQQ000323**

TO : AXA INSURANCE SINGAPORE PTE LTD
ATTN : MOTOR CLAIM DEPARTMENT

SLX2799Y
LEE CHE HWAY ENOCH
BLK 102A PUNGGOL FIELD
#13-436
SINGAPORE 821102
CONTACT NO : 96717369

DATE : 27-MAY-2020
MAKE : MERCEDES BENZ
MODEL : E 200CGI
CHASSIS NO : WDD2120482A415106
ENGINE NO : 27186030215456
SERVICE ADVISOR : SHARIFAH
PAGE : 1 OF 1

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	FRONT BUMPER GRILLE	711 83.00 ✓	
1	FRONT BUMPER BRACKET (CENTRE)	93.00 ✓	
1	FRONT BUMPER SPONGE (CENTRE)	711 123.00 ✓	
1	FRONT BUMPER REINFORCEMENT	22 608.00 ✓	
Sub Total		907.00	0.00

SUB-TOTAL	907.00	0.00
GST - 7 %	63.49	0.00
TOTAL	970.49	0.00

ABWIN SERVICE PTE LTD

Prepared By