

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20005335/KQF3N2**Date:** 13/09/2021REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSN19304719000

Claimant Vehicle No : SHC8276H **Insured Vehicle No :** SMF4900R

Date of Loss: 16/04/2020 Nature of Claim: TP Claim No: SNM20D201786/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC8276H**

Make & Model: HYUNDAI I40, 1.7 D (A) Engine No: D4DFU528775

Reg. Date: 20/08/2015 (Man. Year: 2015) Chassis No: KMHLB41UMGU077029

Colour: Light Blue Odometer: 645926 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16

Front Left Side: Hankook 9 mm Rear Left Side: West Lake 6 mm

Front Right Side: Hankook 9 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,308.40	19,919.60	12,388.80	38.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,020.00	2,740.00	4,280.00	60.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,328.40	22,659.60	16,668.80	42.38
Approved Total (Overridden) (S\$)		14,500.00		
(S\$)	39,328.40	14,500.00	24,828.40	63.13
+ GST 7.00/7.00% (S\$)	2,752.99	1,015.00	1,737.99	63.13
Nett Amount (S\$)	42,081.39	15,515.00	26,566.39	63.13

INSPECTION

Date of Assignment: 24/09/2020

Date Inspected: 22/04/2020 Inspected At: BLK 9 SECTOR C
#01-42 SIN MING
REPAIRER: BIFROST AUTO PTE LTD

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Sep 2021)
Parts: 143	HYUNDAI I40 1.7 D (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC8276H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	2,265.90 FL	*2,265.90 FL
2	1		*BONNET RUBBER (LH)	Serviceable	35.70 FL	*- FL
3	1		*BONNET RUBBER (RH)	Serviceable	35.70 FL	*- FL
4	2		*BONNET HINGE (LH/RH)	Distorted	253.40 FL	*253.40 FL
5	1		*BONNET LOCK	Distorted	142.40 FL	*142.40 FL
6	1		*BONNET ABSORBER (LH ONLY)	Serviceable	61.60 FL	*- FL
7	1		*BONNET SEAL	Serviceable	31.90 FL	*- FL
8	1		*BONNET INSULATOR CLIPS	Necessary	15.00 FL	*15.00 FL
9	1		*RADIATOR GRILLE H EMBLEM	Necessary	129.50 FL	*129.50 FL
10	1		*RADIATOR GRILLE	Cracked	1,480.00 FL	*1,480.00 FL
11	1		*FRONT BUMPER COVER	Bent	1,052.20 FL	*1,052.20 FL
12	1		*FRONT BUMPER SPONGE	Serviceable	379.20 FL	*- FL
13	1		*FRONT BUMPER REINFORCEMENT	Bent	588.40 FL	*588.40 FL
14	2		*FRONT BUMPER GRILLE (LH/RH)	Cut	149.20 FL	*149.20 FL
15	1		*FRONT BUMPER LIP	Serviceable	152.00 FL	*- FL
16	2		*FRONT BUMPER BRACKET TOP (LH/RH)	Repair	89.60 FL	*- FL
17	1		*FRONT BUMPER BRACKET (LH/RH)	O/s Distorted	98.40 FL	*49.20 FL
18	1		*FRONT BUMPER RETAINER MOUNTING	Serviceable	76.20 FL	*- FL
19	1		*FRONT BUMPER GRILLE AIR DUCT (LH/RH) (2 Pcs)	Cracked (1 Pc only)	252.40 FL	*126.20 FL
20	1		*WIPER CONTAINER ASSY	Cracked	281.60 FL	*281.60 FL
21	1		*HEADLAMP SUPPORT PANEL ASSY	Cracked	907.40 FL	*907.40 FL
22	2		*HEADLAMP (LH/RH)	O/s Cracked/N/s Mtg Cracked	2,776.00 FL	*2,776.00 FL
23	1		*HEADLAMP SUPPORT TOP COVER	Cracked	222.60 FL	*222.60 FL
24	1		*DEVICE ASSY-SWIRL	Cracked	1,367.20 FL	*1,367.20 FL
25	1		*RADIATOR	Bent	1,637.20 FL	*1,637.20 FL
26	2		*RADIATOR GUARD (LH/RH)	Cracked	153.00 FL	*153.00 FL
27	1		*RADIATOR FAN BLADE,COWLING,MOTOR ASSY	Cracked	1,194.20 FL	*1,194.20 FL
28	1		*RADIATOR HOSE UPPER	Serviceable	229.50 FL	*- FL
29	1		*RADIATOR HOSE LOWER	Serviceable	135.60 FL	*- FL
30	1		*RADIATOR EXPANSION TANK	Serviceable	163.80 FL	*- FL
31	1		*FRONT FENDER (RH)	Bent	566.30 FL	*566.30 FL
32	1		*FRONT FENDER APRON PANEL (RH)	Repair	637.00 FL	*- FL
33	1		*FRONT FENDER SHIELD (RH)	Torn	174.90 FL	*174.90 FL
34	1		*AIRCON CONDENSER	Twisted/Punctured	947.80 FL	*947.80 FL
35	1		*AIRCON SUCTION & LIQUID HOSE	Serviceable	549.10 FL	*- FL
36	1		*AIRCON DISCHARGE HOSE	Bent	194.40 FL	*194.40 FL
37	1		*AIRCON EXPANSION VALVE	Serviceable	182.90 FL	*- FL
38	1		*FRONT DOOR RH	Bent	2,256.40 FL	*2,256.40 FL
39	1		*FRONT DOOR RUBBER	Serviceable	196.00 FL	*- FL
40	2		*FRONT DOOR HINGE UPPER (LH/RH)	Repair	113.60 FL	*- FL
41	2		*FRONT DOOR HINGE LOWER (LH/RH)	Repair	125.70 FL	*- FL
42	2		*FRONT DOOR CHECK (LH/RH)	Serviceable	91.80 FL	*- FL
43	1		*FRONT WINDSCREEN MOULDING	Not Necessary	133.70 FL	*- FL
44	2		*FRONT WINDSCREEN PILLAR OUTER (LH/RH)	Repair	1,535.90 FL	*- FL
45	1		*FRONT WHEEL RIM (RH)	Dented	650.60 FL	*650.60 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*KNUCKLE ARM (RH)	Bent	595.90 FL	*595.90 FL
47	1		*FRONT WHEEL BEARING HUB ASSY (RH)	Bent	673.20 FL	*673.20 FL
48	1		*FRONT SUSPENSION LOWER ARM (RH)	Bent	1,104.00 FL	*1,104.00 FL
49	1		*FRONT SHOCK ABSORBER ASSY (RH)	Bent	684.40 FL	*684.40 FL
50	1		*FRONT SHOCK ABSORBER MOUNTING (RH)	Serviceable	217.60 FL	*- FL
51	1		*STG TIE ROD (RH)	Serviceable	186.40 FL	*- FL
52	1		*STG TIE END (RH)	Serviceable	125.20 FL	*- FL
53	1		*STABILIZER BAR ASSY	Serviceable	463.70 FL	*- FL
54	1		*STABILIZER BAR LINK (RH)	Serviceable	68.10 FL	*- FL
55	1		*ABS SENSOR	Serviceable	217.90 FL	*- FL
56	1		*FRONT DRIVE SHAFT (RH)	Repair	2,061.60 FL	*- FL
57	1		*RACK & PINION ASSY	Bent/Jammed	1,820.00 FL	*1,820.00 FL
58	1		*FRONT CHASSIS MEMBER (RH)	Repair	1,060.70 FL	*- FL
59	1		*ENGINE MOUNTING RH	Serviceable	401.60 FL	*- FL
60	1		*WIRING ENGINE W/FUSE BOX	Serviceable	3,326.00 FL	*- FL
61	1		*FRONT DOOR COMFORT LOGO	Necessary	75.00 FL	*75.00 FL
62	1		*MANIFOLD ASSY	Serviceable	1,856.30 FL	*- FL
63	1		*COOLANT	Necessary	36.00 FS	*20.00 FS
64	1		*ROCKER PANEL ADVERTISEMENT (RH)	Not Necessary	120.00 FS	*- FS
65	1		*FRONT FENDER ADVERTISEMENT LOGO	Necessary	100.00 FS	*100.00 FS
66	2		*FRONT WINDSCREEN SEALANT	Not Necessary	90.00 FS	*- FS
67	1		*FRONT ERP STICKER	Not Necessary	26.00 FS	*- FS
68	1		*FRONT TYRE (RH)(80%)	Cut	216.00 FS	*172.80 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	40,238.50	24,826.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	7,930.10	4,906.70
Total Parts (\$\$)	32,308.40	19,919.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	1,100.00
2	SPRAY PAINTING CHARGE	New	1,600.00	1,000.00
3	WIRING CHARGE	New	200.00	30.00
4	TUFF KOTE	New	160.00	90.00
5	TOWING CHARGE	New	80.00	50.00
6	RE-SET FRT POWER WINDOW SYSTEM }	New	200.00	60.00
7	TRANSFER OF DOOR MECHANISM FRONT }	New	80.00	0.00
8	FOUR WHEEL ALIGNMENT	New	120.00	60.00
9	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	200.00
10	RE-SET FRT ABS SYSTEM	New	200.00	0.00
11	REMOVE/REFIX RADIATOR	New	90.00	50.00
12	REMOVE/REFIX AIRCON & REFILL GAS	New	130.00	100.00
13	REMOVE/REFIX FUSE BOX	New	120.00	0.00
14	REMOVE/REFIX FRONT WINDSCREEN GLASS	New	120.00	0.00
15	REMOVE/REFIX ENGINE	New	600.00	0.00
16	REMOVE/REFIX DASHBOARD	New	350.00	0.00
17	FRONT CHASSIS ALIGNMENT CHARGE	New	220.00	0.00
18	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$\$)			7,020.00	2,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >