



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LEANG AUTOMOTIVE  
BLK 1 KAKI BUKIT AVE 6  
#01-68 AUTOBAY@ KAKI BUKIT

SINGAPORE 417883  
ON BEHALF OF KIM HOCK CORPORATION PTE

INV No. AC2003705

INV Date 06/05/2020

Reference CS/TP20005338/Uyf3n2

Code TP461



#### PROFESSIONAL SERVICE FEE

Vehicle No. GY 8107J

Insured Veh.

Claim No.

Policy No.

Accident Date 30/03/2020

Inspection Date 22/04/2020

Description	Total
Survey Inspection	473.00
Resurvey Inspection	
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>473.00</b>
<b>GST (7%)</b>	<b>33.11</b>
<b>Grand Total</b>	<b>506.11</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

LEANG AUTOMOTIVE

Ref : CS/TP20005338/Uyf3n2

BLK 1 KAKI BUKIT AVE 6  
#01-68 AUTOBAY@ KAKI BUKIT  
SINGAPORE 417883

Date : 06-05-2020



ON BEHALF OF KIM HOCK CORPORATION PTE LTD

Code : TP461

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	GY 8107J
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	22/04/2020

#### 2. Vehicle Particulars & Condition

Make & Model	NISSAN PICK-UP (M)	c.c	2664
Engine No.	HIDDEN	Year of Reg.	2005
Chassis No.	JN1AHGD22Z0036551	Colour	SILVER / BLUE
Odometer	531428	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185 R14	YOKOHAMA	6 mm
L/H Front Tyre	185 R14	YOKOHAMA	6 mm
R/H Rear Tyre	185 R14	YOKOHAMA	6 mm
L/H Rear Tyre	185 R14	YOKOHAMA	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

#### 5. General Information

Accident Date	30/03/2020	Inspection Date	22/04/2020
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GY 8107J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT DOOR O/S	BADLY DENTED	1,125.20	1,125.20
1	FRONT DOOR OUTER HANDLE O/S	GRAZED	148.50	148.50
1	FRONT DOOR INNER LOCK O/S	TWISTED / JAMMED	166.20	166.20
1	FRONT DOOR INNER TRIM BOARD O/S	TORN	422.30	422.30
1	FRONT DOOR GLASS REGULATOR & MOTOR O/S	SERVICEABLE	295.40	-
1	FRONT DOOR REAR PILLAR OUTER O/S	BADLY DENTED	855.20	855.20
1	FRONT DOOR REAR PILLAR INNER O/S	BADLY DENTED	810.50	810.50
1	FRONT DOOR REAR PILLAR INNER STRIP O/S	TWISTED	139.20	139.20
1	FRONT DOOR REAR PILLAR BACK AIR VENT O/S	TWISTED	122.80	122.80
1	FRONT DOOR INNER RUBBER O/S	NECESSARY	185.30	185.30
1	FRONT DOOR ROC STICKER O/S	NECESSARY	35.00	35.00
1	FRONT DRIVER SEAT	SERVICEABLE	950.00	-
1	REAR CARGO DECK	TO REPAIR SEE LABOUR	2,500.00	-
	LESS 10% DISCOUNT		-	-401.02
			7,755.60	3,609.18
	<b><u>LABOUR</u></b>			
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.		100.00	60.00
	TO TRANSFER FRONT DOOR MECHANISM.		80.00	60.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		100.00	80.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR CARGO DECK.		1,200.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,080.00	650.00
	-		-	-
	-		-	-
	-		-	-
			2,610.00	1,670.00
<b>GRAND TOTAL</b>			<b>10,365.60</b>	<b>5,279.18</b>



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>4,200.00</b>
---	--	--	-----------------

Report Ref No. CS/TP20005338/Uyf3n2

**CHUA KANG SENG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.