

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL **50 RAFFLES PLACE** #05-01/06 SINGAPORE LAND TOWER

SINGAPORE 048623

INV No. AC2003735

INV Date 08/05/2020

Reference CS/SMO20005340/Esf3n2

Code



PROFESSIONAL SERVICE FEE

SLQ 4173B Vehicle No.

Insured Veh. YN 1412T

Claim No. CMTD2001447/GPL

Policy No.

Accident Date 13/04/2020

Inspection Date 30/04/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 **LKK Auto Consultants Pte Ltd**

TEL: 6256 3561 FAX: 6256 4315

Affiliated to Federation Internationale Des Experts En Automobile						
SOMPO INSURANCE SINGAPORE PL Ref : CS/S			Ref : CS/SMO20005340	/Esf3n2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date: 08-05-2020 Code: SMO				
1.		Policy Particulars	:- THIRD PARTY CLAIM			
	Insured Veh.	YN 1412T	Veh. Inspected	SLQ 4173B		
	Policy No.		Coverage (\$)	0.00		
	Claim No.	CMTD2001447/GPL	Excess (\$)	0.00		
	Assign From	GRACE TEO	Assign Date	22/04/2020		
2.		Vehicle Partic	culars & Condition			
	Make & Model	SSANGYONG TIVOLI XLV	c.c	1597		
	Engine No.	HIDDEN	Year of Reg.	2017		
	Chassis No.	KPT36B1VSHP145838	Colour	GREY		
	Odometer	118591	Steering	IN ORDER		
	Brakes	IN ORDER	Modification	SPORTS RIM		
	General	GOOD				
3.		Condition	ons of Tyres			
		Size	Make	Balance		
	R/H Front Tyre	205/60 R16	KUMHO	5 mm		
	L/H Front Tyre	205/60 R16	KUMHO	5 mm		
	R/H Rear Tyre	205/60 R16	KUMHO	5 mm		
	L/H Rear Tyre	205/60 R16	KUMHO	5 mm		
4.		•	on of Damages			
	THE VEHICLE SU	STAINED DAMAGES AT THE FRO	ONT PORTION.			
	DAMAGES SEE D					
5.		General	Information			
	Accident Date	13/04/2020	Inspection Date	30/04/2020		
	Survey held at	MY CAR CONSULTANT PTE LT	D			
	53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934					
5a.			emarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	b. Estimate Days of Repair					
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	3 Working Days			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 4173B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET	DENTED	1,597.00	1,056.33
1	BONNET LOCK	NOT NECESSARY	167.00	-
1	FRONT BUMPER	CRUSHED	1,956.00	513.44
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	650.00	-
1	FRONT GRILLE	CUT	328.00	328.00
1	FRONT GRILLE LOGO	NECESSARY	142.00	142.00
1	FRONT SUPPORT PANEL	NOT NECESSARY	364.00	-
1	RH FRONT HEADLAMP	CUT	2,650.00	924.72
1	FRONT SUPPORT PANEL GARNISH	CUT	198.00	198.00
	LESS 10% DISCOUNT		-805.20	-316.25
			7,246.80	2,846.24
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	60.00	-
1	MISCELLANEOUS (SN)	NOT NECESSARY	150.00	-
			210.00	-
	<u>LABOUR</u>			
	TO CHECK ELECTRICAL WIRING.		80.00	30.00
	CHECK AND RESET FAULT CODE LIGHT ON.	NOT NECESSARY	120.00	-
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	100.00	-
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	120.00	-
	SPRAY PAINTING ON AFFECTED AREAS.		600.00	400.00
	PANEL BEATING ON AFFECTED AREAS.		600.00	400.00
			1,620.00	830.00
	GRAND TOTAL		9,076.80	3,676.24

RECOMMENDED COST OF LUMP SUM REPAIRS		2,950.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/SMO20005340/Esf3n2

W.

CHEN TSUE YEE

Automotive Assessor

X: S.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLQ 4173B

INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315











51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLQ 4173B

RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLQ 4173B

RE-INSPECTION











