Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC3/AIG20005345/AYF3E2

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Date: 31/08/2020

REFERENCE

Insured/Claimant: PREMIUM LEASING PTE LTD Policy No:

Date of Loss: 18/04/2020 Nature of Claim: OD Claim No: 2996510316SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKX9224E

Make & Model: AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A) Engine No: CNC069620

Reg. Date: 28/08/2015 (Man. Year: 2014) Chassis No: WAUZZZ8R0FA022746

Colour: Black Odometer: 43848 km

Engine Capacity: 1984 cc Market Value/New Car Price: S\$100,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55R19 Rear Tyre Size: 235/55R19
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,902.00	2,623.00	3,279.00	55.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,072.00	2,722.00	2,350.00	46.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,974.00	5,345.00	5,629.00	51.29
+ GST 7.00/7.00% (S\$)	768.18	374.15	394.03	51.29
Nett Amount (S\$)	11,742.18	5,719.15	6,023.03	51.29

INSPECTION

Date of Assignment: 22/04/2020

Date Inspected: 20/04/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 5

Adjuster Report Page 3 of 5

(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS \$\$398.00 NETT) Adjuster Report Page 4 of 5

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,560.00 FS	*1,560.00 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	156.00 FS	*- FS
3	1		*REAR BUMPER GUIDE SECTION-RH REAR	Not Necessary	51.00 FS	*- FS
4	1		*REAR BUMPER SPOILER	Deformed	815.00 FS	*815.00 FS
5	1		*REAR BUMPER CARRIER	Not Necessary	617.00 FS	*- FS
6	2		*REAR BUMPER BRACKET HOLDER-LH/RH	Not Necessary	404.00 FS	*- FS
7	1		*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
8	1		*TAIL LIGHT-RH	Not Necessary	282.00 FS	*- FS
9	1		*LED BRAKE LIGHT CLUSTER-RH	Not Necessary	1,371.00 FS	*- FS
10	1		*WHEEL HOUSING LINER-RH	Torn	248.00 FS	*248.00 FS
11	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	*Check	98.00 FS	*- FS
12	1		*SUNDRIES	*Check	300.00 FS	*- FS
F=Fra	anchise	part. S=Spc	Nett.			
				Total Parts (S\$)	5,902.00	2,623.00

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	TO REMOVE AND REINSTALL REAR PARKING AID.CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00					
2	TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR RHS REAR FENDER.RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,600.00	750.00					
3	TO RESPRAY REAR BUMPER,REAR BUMPER LOWER SPOILER AND RHS REAR FENDER	New	3,000.00	1,500.00					
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00					
	Gross Labour Cost (S\$)		5,072.00	2,722.00					
	Report was unsubmitted during this print-out.								

< END OF ESTIMATES >